



RENAULT

P054VCP


report date: 2024-03-28

General information

Make	RENAULT
Model	KANGOO EXPRESSION 16V
Colour	Red
Year of manufacture	2005
Top speed	96 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	105 Nm at 3.500 rpm
Engine capacity	1.149 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.4 mpg
CO2 emission	165 g/km
CO2 label	G





Internet history

Entry 2


Date	2022-01-06
Pictures	1
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-01-21
Pictures	9
Listing price	View report



source: [yesauto.com](#)



MOT history

MOT expiry date	2024-02-26
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	32
Total items failed	12

MOT #20	2023-02-27 16:23
MOT test number	750802402019
Result	✓ Passed
Next expiry date	2024-02-26

MOT #19	2022-02-02 16:25
MOT test number	511148147527
Result	✓ Passed

MOT #18	2022-01-28 12:40
MOT test number	992673525875
Result	✗ Failed

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #17	2021-04-26 14:31
MOT test number	353480653898
Result	✓ Passed

Advice Play in steering rack inner joint(s)

**MOT #16**

2020-06-18 08:53

MOT test number

511612103521

Result

✓ Passed

Advice Nearside Rear Position lamp has a product on the lens or light source but not adversely affecting light intensity (4.2.3 (b) (ii))

Advice Nearside Rear Position lamp slightly affected by the operation of another lamp indicator (4.2.3 (c))

Advice Play in steering rack inner joint(s)

MOT #15

2020-06-15 11:00

MOT test number

911234726546

Result

✗ Failed

Advice Nearside Rear Position lamp has a product on the lens or light source but not adversely affecting light intensity (4.2.3 (b) (ii))

Advice Play in steering rack inner joint(s)

Advice Nearside Rear Position lamp slightly affected by the operation of another lamp indicator (4.2.3 (c))

Fail Nearside Rear Brake pipe excessively corroded (1.1.11 (c))

MOT #14

2019-04-24 12:55

MOT test number

246515232897

Result

✓ Passed

MOT #13

2019-04-24 08:53

MOT test number

431578300340

Result

✗ Failed

Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #12** 2018-01-19 10:52**MOT test number** 723472709713**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #11** 2017-01-10 13:45**MOT test number** 968768816537**Result** ✓ Passed**MOT #10** 2017-01-06 10:22**MOT test number** 537501578665**Result** ✗ Failed**Fail** Front Tyre tread depth below requirements of 1.6mm both (4.1.E.1)**Fail** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**Fail** Rear rear brake binding both (3.7.B.1)**Fail** Nearside Front Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Nearside Rear Stop lamp emits other than a steady red light (1.2.1e)**MOT #9** 2016-01-15 12:19**MOT test number** 666467351767**Result** ✓ Passed**Advice** Rear silencer clamp corroded, silencer heat shield insecure**Advice** Slight play in steering rack ends**Advice** Tyre worn close to the legal limit both sides front (4.1.E.1)

**MOT #8** 2015-01-08 11:50**MOT test number** 339958505021**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2014-01-16 13:23**MOT test number** 968016014005**Result** ✓ Passed**Notice** OFFSIDE REAR TYRE WORN TO LEGAL LIMIT**Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2013-01-16 09:26**MOT test number** 138126113077**Result** ✓ Passed**MOT #5** 2012-01-20 11:56**MOT test number** 596010722082**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Notice** Play in steering rack inner joint(s)**MOT #4** 2010-02-09 09:07**MOT test number** 692370940082**Result** ✓ Passed**Notice** Nearside rear tyre worn to limit

**MOT #3**

2009-02-16 14:18

MOT test number

253887249046

Result

✓ Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Air bag lamp indicating a fault**Advice** Nearside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Nearside front tie rod has slight play**MOT #2**

2009-02-16 11:06

MOT test number

333467349008

Result

✗ Failed

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Air bag lamp indicating a fault**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Notice** Nearside front tie rod has slight play**Advice** Nearside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #1**

2007-12-11 12:43

MOT test number

461995347484

Result

✓ Passed

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** End cap missing on inside of nearside rear bumper



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-01-28
Last registration	2023-02-27
Complete history	See info



Registration #1	2005-01-28	17 mi
Registration #2	2007-12-11	38.271 mi
Registration #3	2009-02-16	46.342 mi
Registration #4	2009-02-16	46.342 mi
Registration #5	2010-02-09	52.736 mi
Registration #6	2012-01-20	61.297 mi
Registration #7	2013-01-16	65.020 mi
Registration #8	2014-01-16	68.350 mi
Registration #9	2015-01-08	71.642 mi
Registration #10	2016-01-15	74.642 mi
Registration #11	2017-01-06	78.620 mi
Registration #12	2017-01-10	78.621 mi
Registration #13	2018-01-01	81.277 mi
Registration #14	2018-01-01	81.277 mi
Registration #15	2018-01-01	81.277 mi
Registration #16	2018-01-01	81.277 mi
Registration #17	2018-01-01	81.277 mi
Registration #18	2018-01-01	81.277 mi
Registration #19	2018-01-01	81.277 mi
Registration #20	2018-01-01	81.277 mi
Registration #21	2018-01-01	81.277 mi
Registration #22	2018-01-01	81.277 mi
Registration #23	2018-01-01	81.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1672 mm
Height	1855 mm
Length	4035 mm
Wheel base	2600 mm
Kerb weight	1035 kg
Max. allowed weight	1570 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	F008292