



report date: 2024-03-29

General information

| | |
|---------------------|----------------|
| Make | VOLVO |
| Model | S40 D S |
| Colour | Grey |
| Year of manufacture | - |
| Top speed | 118 mph |
| 0 - 60 mph | 11.3 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 108 BHP |
| Max. torque | 240 Nm at 1.750 rpm |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 45.6 mpg |
| Consumption extra urban | 67.3 mpg |
| Consumption combined | 57.6 mpg |




LABEL UNKNOWN



Internet history

Entry 2


| | |
|---------------|-----------------------------|
| Date | 2021-08-11 |
| Pictures | 8 |
| Listing price | View report |



source: [autotrader.co.uk](#)

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-07-29 |
| Pictures | 8 |
| Listing price | View report |



source: [autotrader.co.uk](#)



MOT history

| | |
|------------------|------------------|
| MOT #17 | 2021-02-23 11:51 |
| MOT test number | 673361940649 |
| Result | ✓ Passed |
| Next expiry date | 2022-03-06 |

| | |
|-----------------|--|
| MOT #16 | 2020-02-11 10:27 |
| MOT test number | 956937393192 |
| Result | ✓ Passed |
| Advice | Offside Outer Track rod end ball joint has slight play (2.1.3 (b) (i)) |

| | |
|-----------------|--|
| MOT #15 | 2019-02-26 13:43 |
| MOT test number | 767766555174 |
| Result | ✓ Passed |
| Minor | Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i)) |

| | |
|-----------------|---|
| MOT #14 | 2018-02-22 12:33 |
| MOT test number | 321805713024 |
| Result | ✓ Passed |
| Advice | Rear brake pads wearing thin both sides and rear brake disc slight worn/scored both sides |
| Advice | Rear tyre slightly perished both sides |

| | |
|-----------------|------------------|
| MOT #13 | 2017-02-28 17:26 |
| MOT test number | 752066660619 |
| Result | ✓ Passed |

| | |
|-----------------|--|
| MOT #12 | 2017-02-28 10:42 |
| MOT test number | 836228580060 |
| Result | ✗ Failed |
| Fail | Offside Rear Hydraulic brake cylinder leaking hydraulic fluid brake calliper (3.6.A.1) |
| Fail | Nearside Front Front position lamp(s) not working (1.1.A.3b) |

**MOT #11** 2016-02-16 15:26**MOT test number** 670715782148**Result** ✓ Passed**MOT #10** 2016-02-16 13:47**MOT test number** 465167563210**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #9** 2015-02-16 16:01**MOT test number** 428397345018**Result** ✓ Passed**Advice** Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2015-02-16 09:52**MOT test number** 509197345074**Result** ✗ Failed**Fail** Rear Direction indicators incorrect colour (1.4.A.2f)**Advice** Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front coil spring broken (2.4.C.1a)**MOT #7** 2014-02-13 12:08**MOT test number** 518244044060**Result** ✓ Passed**MOT #6** 2013-03-07 17:19**MOT test number** 686276263024**Result** ✓ Passed

**MOT #5** 2012-09-18 12:40**MOT test number** 309672062241**Result** ✓ Passed**Advice** Nearside Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #4** 2012-09-18 10:53**MOT test number** 956282262286**Result** ✗ Failed**Advice** Nearside Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Fail** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)**MOT #3** 2012-01-18 11:53**MOT test number** 529888112026**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Parking brake lever has little reserve travel (3.1.6b)**Notice** Engine light on dash**MOT #2** 2012-01-18 10:49**MOT test number** 697658812057**Result** ✗ Failed**Notice** Engine light on dash**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



| | |
|-----------------|------------------|
| MOT #1 | 2010-12-16 11:46 |
| MOT test number | 281880350351 |
| Result | ✓ Passed |



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | KE57FFG |
| Plate since | 2024-03-29 |
| Current registration | KE57FFG |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 20 |
| First mileage registration | 2007-12-21 |
| Last registration | 2021-02-23 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2007-12-21 | 13 mi |
| Registration #2 | 2010-12-16 | 71.882 mi |
| Registration #3 | 2012-01-18 | 104.684 mi |
| Registration #4 | 2012-01-18 | 104.684 mi |
| Registration #5 | 2012-09-18 | 117.225 mi |
| Registration #6 | 2012-09-18 | 117.232 mi |
| Registration #7 | 2013-03-07 | 117.254 mi |
| Registration #8 | 2014-02-13 | 127.781 mi |
| Registration #9 | 2015-02-16 | 139.817 mi |
| Registration #10 | 2015-02-16 | 139.817 mi |
| Registration #11 | 2016-05-20 | 151.853 mi |
| Registration #12 | 2016-05-20 | 151.853 mi |
| Registration #13 | 2016-05-20 | 151.853 mi |
| Registration #14 | 2016-05-20 | 151.853 mi |
| Registration #15 | 2016-05-20 | 151.853 mi |
| Registration #16 | 2016-05-20 | 151.853 mi |
| Registration #17 | 2016-05-20 | 151.853 mi |
| Registration #18 | 2016-05-20 | 151.853 mi |
| Registration #19 | 2016-05-20 | 151.853 mi |
| Registration #20 | 2016-05-20 | 151.853 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1782 mm |
| Height | 1447 mm |
| Length | 4266 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1368 kg |
| Max. allowed weight | 1780 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 52 l |
| Fuel delivery | Direct Injection |
| Number of doors | 2 |
| Number of seats | 4 |

| | |
|---------------|--------|
| Engine number | 146674 |
|---------------|--------|