





General information

Make	ΤΟΥΟΤΑ
Model	VERSO VALVEMATIC ICON
Colour	Bronze
Year of manufacture	2015
Top speed	115 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	160 Nm at 4.400 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.8 mpg
CO2 emission	154 g/km
CO2 label	G



Internet history

Entry 1

Date

2021-10-05

Pictures

12

Listing price

View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-07
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	17
Total items failed	2

MOT #10	2023-10-06 09:54
MOT test number	762220185656
Result	✓ Passed
Next expiry date	2024-10-07
Minor Nearside Track rod end ball joint dust cover damaged or deteriorated, b dirt (2.1.3 (g) (i))	ut preventing the ingress of
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Nail in tyre	
Minor Nearside Side repeater lens defective which has no effect on emitted lig	ht (4.4.1 (b) (i))
Minor Offside Track rod end ball joint dust cover damaged or deteriorated, but dirt (2.1.3 (g) (i))	preventing the ingress of
Advice Offside Rear Outer Child Seat fitted not allowing full inspection of adult	belt





MOT #9	2023-10-06 08:50
MOT test number	773919156055
Result	🗙 Failed
Advice Nearside Nail in tyre	
Minor Nearside Track rod end ball joint dust cover damaged or deteriorated, but pr dirt (2.1.3 (g) (i))	reventing the ingress of
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Rear Outer Child Seat fitted not allowing full inspection of adult belt	
Minor Nearside Side repeater lens defective which has no effect on emitted light (4	I.4.1 (b) (i))
Minor Offside Track rod end ball joint dust cover damaged or deteriorated, but prev dirt (2.1.3 (g) (i))	venting the ingress of
DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 ((e))

MOT #8	2022-10-05 14:50
MOT test number	236052719690
Result	✓ Passed

MOT #7		2022-10-05 14:50
MOT test number		345538396710
Result		🗙 Failed
Pass with rectification	Rear Position lamp not working both (4.2.1 (a) (ii))	

МОТ #6	2021-10-08 14:57
MOT test number	273809489079
Result	✓ Passed

MOT #5	2021-03-26 11:17
MOT test number	218463011950
Result	✓ Passed
Advice Engine cover & undertrays fitted unable to check certain items	





MOT #4	2021-03-26 11:17	
MOT test number	214963303715	
Result	🗙 Failed	
Advice Engine cover & undertrays fitted unable to check certain items		
Pass with rectification Nearside Rear Position lamp not working (4.2.1 (a) (ii))		

MOT #3	2020-03-20 16:00
MOT test number	913876688259
Result	✓ Passed

MOT #2	2019-03-28 12:29
MOT test number	230825961938
Result	✓ Passed
AdviceNearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))AdviceNearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #1	2018-03-06 16:53
MOT test number	790519260407
Result	✓ Passed



Tax & MOT check

Tax due: 1 April 2025	✓ Taxed	Expires: 7 October 2024	✓ МОТ
Tax status			Valid until 1 April
Days left			336
MOT expiry date			7 October 2024
Full MOT history			See MOT history
Tax calculation			

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	ET
Category		LAMP
Туре		
Damage 2		AMPL
	F	A A A A A A A A A A A A A A A A A A A
Date		1º
Category		SMT.
Туре		

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this TOYOTA had different number pla	tes.
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-03-31
Last registration	2023-10-06
Complete history	See info



Registration #1	2015-03-31	8 mi
Registration #2	2018-03-06	28.641 mi
Registration #3	2019-03-28	35.138 mi
Registration #4	2020-03-20	42.334 mi
Registration #5	2021-03-26	45.446 mi
Registration #6	2021-03-26	45.446 mi
Registration #7		11.117 esi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.117 esi
Registration #11		11.777 mi
Registration #12		

More info >





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	89%
Children	75%
Pedestrian	69%
Safety systems	86%
Overall rating	82%
Video	see crash video



Dimensions & weight	
Width	1790 mm
Height	1620 mm
Length	4460 mm
Wheel base	2780 mm
Kerb weight	1525 kg
Max. allowed weight	2125 kg
Additional information	
Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 12/12

Number of axles	2
Engine number	1ZRV048871