



report date: 2024-03-29

General information

Make	FORD
Model	RANGER WILDTRAK DCB 4X4
Colour	Orange
Year of manufacture	2007
Gearbox	5 speed Manual

Engine & fuel consumption

Power	154 BHP
Max. torque	380 Nm
Engine capacity	2.953 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-23
Pictures	16
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-13
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	68
Total items failed	20

MOT #21	2024-03-14 16:34
MOT test number	435390494634
Result	✓ Passed
Next expiry date	2025-03-13
Advice	Nearside Front Brake pipe corroded, covered in grease or other material slight corroded (1.1.11 (c))
Advice	Rear Lower Shock absorbers has a slightly worn bush Both (5.3.2 (c))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Under side and components generally corroded
Advice	Offside Front Brake pipe corroded, covered in grease or other material slight corroded (1.1.11 (c))
Advice	Front Brake pad(s) wearing thin Both sides (1.1.13 (a) (ii))
Advice	Nearside Front steering idler slight wear

**MOT #20**

2024-03-12 13:09

**MOT test number**

553738021741

**Result****✗ Failed**

- Advice** Engine light on 2007 vehicle
- Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Front Service brake excessively binding Both sides (1.2.1 (f))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material slight corroded (1.1.11 (c))
- Fail** Offside Front Lower Suspension arm ball joint likely to become detached (5.3.4 (a) (ii))
- Advice** Under side and components generally corroded
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material slight corroded (1.1.11 (c))
- Advice** Front Brake pad(s) wearing thin Both sides (1.1.13 (a) (ii))
- Advice** Nearside Front steering idler slight wear
- Advice** Rear Lower Shock absorbers has a slightly worn bush Both (5.3.2 (c))

**MOT #19**

2023-01-25 09:53

**MOT test number**

871202010852

**Result****✓ Passed**

- Advice** Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #18** 2021-12-10 15:53**MOT test number** 834968743488**Result** ✓ Passed**MOT #17** 2020-11-26 17:23**MOT test number** 349442588843**Result** ✓ Passed

**Advice** Brake pipe corroded, covered in grease or other material All brake pipes slightly corroded. (1.1.11 (c))

**Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #16** 2020-11-26 15:31**MOT test number** 483375097071**Result** ✗ Failed

**Advice** Offside Front Nail in tyre

**Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))

**Advice** Brake pipe corroded, covered in grease or other material All brake pipes slightly corroded. (1.1.11 (c))

**Fail** Offside Front Headlamp aim too high (4.1.2 (a))

**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))

**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt Clip missing. (6.1.7 (g) (ii))

**Fail** Nearside Front Headlamp aim too high (4.1.2 (a))

**MOT #15**

2019-11-30 12:28

**MOT test number**

895947827744

**Result**

✓ Passed

- Advice** Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Rear Brake pipe corroded, covered in grease or other material Heavy corrosion to all metal brake pipes into rear brake compensator (1.1.11 (c))
- Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Vehicle dirty underneath

**MOT #14**

2019-11-27 09:23

**MOT test number**

138640098405

**Result**

✗ Failed

- Fail** Nearside Front Headlamp aim too high (4.1.2 (a))
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Vehicle dirty underneath
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Rear Brake pipe corroded, covered in grease or other material Heavy corrosion to all metal brake pipes into rear brake compensator (1.1.11 (c))
- Fail** Nearside Front Side repeater not working (4.4.1 (a) (ii))
- Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #13**

2018-11-23 15:18

**MOT test number**

848573038064

**Result**

✓ Passed

- Advice** Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2mm Tread depth (5.2.3 (e))
- Advice** Rear Brake pipe corroded, covered in grease or other material Into and out of rear brake compensator (1.1.11 (c))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Spare tyre defective Low pressure
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2mm Tread depth (5.2.3 (e))
- Advice** Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))

**MOT #12**

2018-11-10 10:18

**MOT test number**

675774412313

**Result**

✗ Failed

- Advice** Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2mm Tread depth (5.2.3 (e))
- Advice** Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2mm Tread depth (5.2.3 (e))
- Advice** Rear Brake pipe corroded, covered in grease or other material Into and out of rear brake compensator (1.1.11 (c))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Spare tyre defective Low pressure
- Fail** Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #11**

2017-11-09 14:59

**MOT test number**

233354283894

**Result**

✓ Passed

**Advice** Lower engine covers fitted restricting access to components**Advice** Nearside Front Lower Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt Splitting (2.4.G.2)**Advice** Nearside Front Upper Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Engine oil leak**MOT #10**

2017-11-06 16:34

**MOT test number**

826645247635

**Result**

✗ Failed

**Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Engine oil on minimum level**Fail** Nearside Rear Exhaust has a major leak of exhaust gases Exhaust broken rear box to silencer (7.1.2)**Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Lower engine covers fitted restricting access to components**Advice** Nearside Front Lower Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt Splitting (2.4.G.2)**Advice** Engine oil leak**Advice** Nearside Front Upper Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #9**

2016-10-25 11:41

**MOT test number**

313978746518

**Result**

✓ Passed

**MOT #8**

2015-12-16 13:46

**MOT test number**

911679166554

**Result**

✓ Passed



**MOT #7** 2014-12-18 09:52**MOT test number** 599452054393**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2013-12-18 11:48**MOT test number** 679682953399**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2013-12-18 11:48**MOT test number** 427782653394**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Front Headlamp aim too low (1.8)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2013-01-29 09:48**MOT test number** 508599923022**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2011-12-02 10:01**MOT test number** 169256731312**Result** ✓ Passed



MOT #2	2011-12-02 10:01
MOT test number	299006931342
Result	✗ Failed
<div>Pass with rectification</div> Front Passenger's seat insecure (6.2.A.1)	

MOT #1	2010-12-17 08:52
MOT test number	914451750396
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
13 March 2025

<b>Tax status</b>	Valid until 1 September
-------------------	-------------------------

<b>Days left</b>	124
------------------	-----

<b>MOT expiry date</b>	13 March 2025
------------------------	---------------

<b>Full MOT history</b>	<a href="#">See MOT history</a>
-------------------------	---------------------------------



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-12-31
Last registration	2024-03-14
Complete history	<a href="#">See info</a>



Registration #1	2007-12-31	18 mi
Registration #2	2010-12-17	30.112 mi
Registration #3	2011-12-02	40.721 mi
Registration #4	2013-01-29	52.166 mi
Registration #5	2013-12-18	60.510 mi
Registration #6	2014-12-18	66.604 mi
Registration #7	2015-12-16	74.762 mi
Registration #8	2016-10-25	81.846 mi
Registration #9	2017-11-06	92.405 mi
Registration #10	2017-11-09	92.497 mi
Registration #11	2018-11-10	107.552 mi
Registration #12	2019-03-29	121.557 mi
Registration #13	2019-03-29	121.557 mi
Registration #14	2019-03-29	121.557 mi
Registration #15	2019-03-29	121.557 mi
Registration #16	2019-03-29	121.557 mi
Registration #17	2019-03-29	121.557 mi
Registration #18	2019-03-29	121.557 mi
Registration #19	2019-03-29	121.557 mi
Registration #20	2019-03-29	121.557 mi
Registration #21	2019-03-29	121.557 mi

More info >





Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	122705