



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 D DRIVE SE
Colour	White
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	99 g/km
CO2 label	A






Internet history

Entry 1

Date	2022-02-12
Pictures	38
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-11
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	26
Total items failed	1

MOT #16	2024-02-06 12:58
MOT test number	348633608672
Result	✓ Passed
Next expiry date	2025-02-11
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2024-02-05 09:40
MOT test number	307233644035
Result	✗ Failed
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
MAJOR	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
DANGEROUS	Undertray likely to become detached (6.2.1 (a) (ii))
MAJOR	Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
DANGEROUS	Offside Rear Tyre has a tear, caused by separation or partial failure of its structure crack to cord x1 (5.2.3 (d) (ii))
MAJOR	Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))

**MOT #14** 2023-02-09 11:02**MOT test number** 878880565683**Result** ✓ Passed**Advice** Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement x2 (5.3.4 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing tread wear inner edge (5.2.3 (d) (ii))**MOT #13** 2023-02-09 11:02**MOT test number** 170909803498**Result** ✗ Failed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing tread wear inner edge (5.2.3 (d) (ii))**Pass with rectification** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement x2 (5.3.4 (a) (i))**MOT #12** 2022-02-12 10:58**MOT test number** 716162519307**Result** ✓ Passed**Advice** Under trays fitted**MOT #11** 2021-03-12 10:51**MOT test number** 218915739719**Result** ✓ Passed**MOT #10** 2020-03-11 16:26**MOT test number** 153185664481**Result** ✓ Passed

**MOT #9** 2020-03-11 10:38**MOT test number** 923935854309**Result** ✗ Failed

DANGEROUS Nearside Front Outer Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8 2019-03-15 15:08**MOT test number** 255360356575**Result** ✓ Passed**MOT #7** 2019-03-08 15:47**MOT test number** 708417482472**Result** ✗ Failed

MAJOR Offside Rear Service brake excessively binding (1.2.1 (f))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MAJOR Nearside Front Service brake excessively binding (1.2.1 (f))

MAJOR Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))

MOT #6 2018-02-22 11:04**MOT test number** 733951714068**Result** ✓ Passed

Advice Front Suspension arm rubber bush deteriorated but not resulting in excessive movement both (2.4.G.2)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #5 2017-02-13 12:14**MOT test number** 230426983609**Result** ✓ Passed



MOT #4	2016-02-05 09:31
MOT test number	775777441803
Result	✓ Passed
MOT #3	2015-02-07 10:52
MOT test number	635728735099
Result	✓ Passed
MOT #2	2014-03-01 10:49
MOT test number	588150764000
Result	✓ Passed
<div>Advice Front Brake pad(s) wearing thin (3.5.1g)</div>	
MOT #1	2013-02-09 10:33
MOT test number	489520443021
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
11 February 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	11 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-03-04
Last registration	2024-02-06
Complete history	See info



Registration #1	2010-03-04	12 mi
Registration #2	2013-02-09	35.749 mi
Registration #3	2014-03-01	50.543 mi
Registration #4	2015-02-07	64.062 mi
Registration #5	2016-02-05	79.314 mi
Registration #6	2017-02-13	96.620 mi
Registration #7	2018-02-22	114.971 mi
Registration #8	2019-03-08	125.439 mi
Registration #9	2019-03-15	125.442 mi
Registration #10	2020-03-01	125.442 mi
Registration #11	2020-03-01	125.442 mi
Registration #12	2020-03-01	125.442 mi
Registration #13	2020-03-01	125.442 mi
Registration #14	2020-03-01	125.442 mi
Registration #15	2020-03-01	125.442 mi
Registration #16	2020-03-01	125.442 mi
Registration #17	2020-03-01	125.442 mi
Registration #18	2020-03-01	125.442 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1382 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	957548