





report date: 2024-03-28

General information

Make	MERCEDES
Model	CLK CLK240 AVANTGARDE
Colour	Silver
Year of manufacture	2005
Top speed	143 mph
0 - 60 mph	10.2 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	170 BHP
Max. torque	240 Nm at 4.500 rpm
Engine capacity	2.597 сс
Cylinders	6
Fuel type	Petrol
Consumption city	18.8 mpg
Consumption extra urban	37.7 mpg
Consumption combined	28.0 mpg
CO2 emission	242 g/km
CO2 label	L



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2021-10-18

Pictures 14

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-12-12
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	16
Total items failed	8

MOT #19	2023-12-13 13:01
MOT test number	110341538356
Result	✓ Passed
Next expiry date	2024-12-12

MOT #18	2023-12-13 13:01
MOT test number	836247871093
Result	▼ Failed
Pass with rectification	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

MOT #17	2022-07-05 15:20
MOT test number	826029391213
Result	✓ Passed
MOT #16	2022-07-04 08:22
MOT test number	944243961282
Result	X Failed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #15	2021-07-05 10:50
MOT test number	507084856001
Result	✓ Passed
MOT #14	2021-07-01 10:52
MOT test number	126702361457
Result	× Failed
Fail Tyre tread depth below requirements of 1.6mm both front 205/55/16 (5.2.3 (e))	
Fail Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))	

Fail Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))	
MOT #13	2020-07-30 13:48
MOT test number	184324302427
Result	✓ Passed
MOT #12	2018-06-25 14:36
MOT test number	211694775372
Result	✓ Passed
MOT #11	2017-06-26 12:31
MOT test number	307345034414
Result	✓ Passed
MOT #10	2016-06-20 16:00
MOT test number	912103200598

Result	✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #9 2016-06-20 13:50

MOT test number 675339321656

Result X Failed

Fail Nearside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

Fail Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

Fail Offside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

MOT #8 2015-06-22 15:03

MOT test number 937883075105

Result
✓ Passed

Advice Offside Front wheel bearing has slight play (2.5.A.3c)

Advice Nearside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)

Advice Offside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)

MOT #7 2014-06-23 16:09

MOT test number 798024574198

Result \(\sqrt{Passed} \)

MOT #6 2013-06-25 11:44

MOT test number 455216973147

Result

Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #5 2012-06-27 15:56

MOT test number 405689272157

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #4 2011-08-23 14:21

MOT test number 389315831287

Result
✓ Passed

Notice SRS Warning light on

Notice Nail in nearside rear tyre

MOT #3 2010-09-22 12:05

MOT test number 363855160223

Result ✓ Passed

Advice Offside Front Brake pad(s) wearing thin (3.5.1g)

Notice Both ront brake discs are worn

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2009-09-21 11:52

MOT test number 131614769219

Result

Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2008-09-24 10:27

MOT test number 821178768266

Result

Passed

CarCheck.co.uk page 6/13





report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	12 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category
Type
Damage 2
Date

E AMPLE LA MARIE LA M

Category

Type

Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

O	ner	1-1-4	
1 11/4	/nar	nici	$r \cap r \vee$
\cup \vee			

Owner mistory	
For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downlo <u>here</u> .	

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

2000000	

	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	AIR AIR
Plate since	
Current registration	AIR OK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-09-05
Last registration	2023-12-13
Complete history	See info



Registration #1	2005-09-05	7 mi
Registration #2	2008-09-24	23.151 mi
Registration #3	2009-09-21	29.296 mi
Registration #4	2010-09-22	34.955 mi
Registration #5	2011-08-23	39.197 mi
Registration #6	2012-06-27	39.701 mi
Registration #7	2013-06-25	48.850 mi
Registration #8	2014-06-23	55.751 mi
Registration #9	2015-06-22	64.336 mi
Registration #10	2016-06-20	73.971 mi
Registration #11	2016-06-20	73.791 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 mg

More info >

CarCheck.co.uk page 12/13



GY55UFW report date: 2024-03-28

Dimensions & weight

Width	1740 mm
Height	1413 mm
Length	4643 mm
Wheel base	2690 mm
Kerb weight	1700 kg
Max. allowed weight	2155 kg

Additional information

Fuel tank capacity	62 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	11291231969080

CarCheck.co.uk page 13/13