





report date: 2024-03-28

### General information

Make	FIAT
Model	500L POP STAR
Colour	White
Year of manufacture	2013
Top speed	111 mph
0 - 60 mph	12.8 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	95 BHP
Max. torque	127 Nm at 4.500 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	56.5 mpg
Consumption combined	45.6 mpg
CO2 emission	145 g/km
CO2 label	F



CarCheck.co.uk page 1/12



SM130HJ report date: 2024-03-28

# Internet history

### Entry 1

Date 2021-06-04

Pictures 17

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



SM130HJ report date: 2024-03-28

MOT history

MOT expiry date	2024-06-19
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	15
Total items failed	0

MOT #14	2023-06-02 08:20
MOT test number	320413676224
Result	<b>✓</b> Passed
Next expiry date	2024-06-19
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #13	2022-06-20 10:27
MOT test number	504584428493
Result	✓ Passed
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #12	2022-04-21 15:50
MOT test number	184997194949
Result	✓ Passed
Advice Coolant leak water pump flow pipe corroded and leaking	

MOT #11	2022-01-06 14:22
MOT test number	658000486528
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

**MOT #10** 2021-06-25 09:04

**MOT test number** 955144534901

**Result** ✓ Passed

MOT #9 2021-06-24 15:42

**MOT test number** 720780430863

**Result** X Failed

**MAJOR** Brake lever has insufficient reserve travel (1.1.2 (a))

**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #8 2020-11-12 17:40

**MOT test number** 919934439124

Result \( \sqrt{Passed} \)

Advice Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7 2019-11-14 12:52

**MOT test number** 614994385382

**Result** 
✓ Passed

MOT #6 2019-11-13 13:54

**MOT test number** 158103883913

Result X Failed

**MAJOR** Electronic stability control warning lamp indicates a fault (7.12 (e))

MAJOR Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #5		2018-11-14 09:57
MOT test	number	764216232841
Result		✓ Passed
MOT #4		2018-11-13 14:24
MOT test	number	562888442931
Result		<b>×</b> Failed
MAJOR	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #3		2017-11-14 11:22
MOT test	number	165980864931
Result		<b>✓</b> Passed
MOT #2		2016-11-23 13:32
MOT test	number	765388003442
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #1	2016-02-15 17:09
MOT test number	272309228562
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 5/12



report date: 2024-03-28

## Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	19 June 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



SM13OHJ report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner	المنحطح الطا
UWNEr	nistarv
OWITCH	IIIJCOI Y

For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report		2?
***************************************		
***************************************		
***************************************		
***************************************		
***************************************		
	More info	>
Plate changes		,
See in this check if this FIAT had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	NIE NIE UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



SM13OHJ report date: 2024-03-28

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-06-28
Last registration	2023-06-02
Complete history	See info



Registration #1	2013-06-28	15 mi
Registration #2	2016-02-15	16.822 mi
Registration #3	2016-11-23	23.219 mi
Registration #4	2017-11-14	29.743 mi
Registration #5	2018-11-13	38.009 mi
Registration #6	2018-11-14	38.010 mi
Registration #7	2019-11-13	46.335 mi
Registration #8	2019-11-14	46.336 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.77 66
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		0.00 44
Registration #15		11.777 es
Registration #16		11.777 es

More info >

page 11/12 CarCheck.co.uk



report date: 2024-03-28

### Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	94%
Children	78%
Pedestrian	65%
Safety systems	71%
Overall rating	83%
Video	see crash video



# Dimensions & weight

Width	1780 mm
Height	1660 mm
Length	4140 mm
Max. allowed weight	1805 kg

## Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	4016273

CarCheck.co.uk page 12/12