



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	I10 SE
Colour	Red
Year of manufacture	2017
Top speed	103 mph
0 - 60 mph	13.8 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	86 BHP
Max. torque	121 Nm at 4.000 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-01-31
Pictures	8
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-06-06
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	34
Total items failed	6

MOT #6	2023-05-25 14:36
--------	------------------

MOT test number	126918533839
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-06-06
------------------	------------

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front dat time running light not working
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front wing damaged



MOT #5

2023-05-24 09:57

MOT test number

979447205731

Result

✗ Failed

- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Front Windscreen washer not working (3.5 (a))
- Advice** Offside Front dat time running light not working
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Windscreen washer not working (3.5 (a))
- Advice** Offside Front wing damaged
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 175/65/14 (5.2.3 (d) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #4**

2022-05-30 15:37

MOT test number

110692611467

Result

✓ Passed

- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** T/p/m/s light on
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #3

2022-05-30 13:47

MOT test number

790644615846

Result

✗ Failed

- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** T/p/m/s light on
- Advice** Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



MOT #2	2021-06-07 10:24
MOT test number	202103268220
Result	✓ Passed
MOT #1	2020-08-28 12:45
MOT test number	497470499119
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
6 June 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	6 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	EN67EHG
Plate since	2024-03-29
Current registration	EN67EHG
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-12-21
Last registration	2023-05-25
Complete history	See info



Registration #1	2017-12-21	18 mi
Registration #2	2020-08-28	30.732 mi
Registration #3	2021-06-07	30.750 mi
Registration #4		
Registration #5		
Registration #6		
Registration #7		
Registration #8		

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	79%
Children	80%
Pedestrian	71%
Safety systems	56%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1660 mm
Height	1500 mm
Length	3665 mm
Wheel base	2385 mm
Kerb weight	961 kg
Max. allowed weight	1455 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number	G4LAHM432693
---------------	--------------