



LM03WTP


report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BORA
Colour	White
Year of manufacture	2003
Gearbox	-

Engine & fuel consumption

Engine capacity	1.896 cc
Fuel type	Diesel
CO2 emission	138 g/km
CO2 label	E







Internet history

Entry 1

Date	2022-02-05
Pictures	4
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-17
MOT pass rate	71 %
MOT passed	17
Failed MOT tests	7
Total advice items	42
Total items failed	21

MOT #242024-01-18 17:09

MOT test number740515901235

Result✓ Passed

Next expiry date2025-01-17

- Minor

Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice

Front Anti-roll bar pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))
- Advice

Oil leak, but not excessive (8.4.1 (a) (i))
- Advice

Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Minor

Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice

Front Tyre worn close to legal limit/worn on edge both wearing on outer edges (5.2.3 (e))
- Advice

Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice

Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice

Rear brake backing plate missing advise

**MOT #23**

2024-01-17 16:13

**MOT test number**

673942874723

**Result****✗ Failed**

- Fail** Nearside Rear Stop lamp(s) not working not working (4.3.1 (a) (ii))
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Rear number plate light not working advise
- Advice** Rear brake backing plate missing advise
- Fail** Central Rear Seat belt installation anchorage insecure seat belt not bolted ti floor (10.1 (d))
- Fail** Front Exhaust has a major leak of exhaust gases catalytic converter leaking excessively (6.1.2 (a))
- Fail** Offside Front Shock absorbers has an excessively worn bush top mount excessively worn (5.3.2 (c))
- Advice** Nearside Front drop link is broken

**MOT #22**

2023-01-13 16:39

**MOT test number**

882985481852

**Result****✓ Passed**

- Advice** Nearside door mirror missing
- Advice** Front brake hoses staring to perish
- Advice** Offside rear wheel buckled
- Advice** Slight corrosion on subframes
- Advice** Rear no. plate in poor condition
- Advice** Slight exhaust blow cat area
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #21**

2023-01-13 08:57

**MOT test number**

206886083609

**Result****✗ Failed**

- Advice** Slight exhaust blow cat area
- Advice** Nearside door mirror missing
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Advice** Rear no. plate in poor condition
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Front brake hoses staring to perish
- Advice** Air box lid insecure
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside rear wheel buckled
- Advice** Slight corrosion on subframes
- Advice** Oil on min

**MOT #20**

2022-01-13 13:49

**MOT test number**

770285200849

**Result****✓ Passed****MOT #19**

2022-01-11 08:43

**MOT test number**

422149776240

**Result****✗ Failed**

- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Offside Front Track rod end ball joint worn to the extent there is a serious risk of detachment track rod end not secure on tie rod. (2.1.3 (b) (ii))
- Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**MOT #18** 2020-12-30 14:11**MOT test number** 582400948941**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement bottom arm back bush slightly worn (5.3.4 (a) (i))**MOT #17** 2020-12-30 11:31**MOT test number** 290544950208**Result** ✗ Failed**Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement bottom arm back bush slightly worn (5.3.4 (a) (i))**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Suspension component attachment bracket/mounting damaged and seriously weakened top strutt mounting (5.3.3 (b) (i))**MOT #16** 2019-07-01 11:49**MOT test number** 778597356689**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15** 2018-06-21 12:26**MOT test number** 768285587794**Result** ✓ Passed**Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14** 2017-06-30 12:26**MOT test number** 700418037901**Result** ✓ Passed**MOT #13** 2015-11-05 13:35**MOT test number** 495298998580**Result** ✓ Passed**MOT #12** 2015-11-05 13:35**MOT test number** 258133493134**Result** ✗ Failed**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)**MOT #11** 2014-11-28 10:58**MOT test number** 135812634395**Result** ✓ Passed**MOT #10** 2013-11-15 10:07**MOT test number** 998869813388**Result** ✓ Passed**MOT #9** 2012-11-13 13:18**MOT test number** 685918812381**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #8** 2012-11-13 10:16**MOT test number** 407178912384**Result** ✗ Failed**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Headlamp aim too high (1.8)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Nearside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Fail** Offside Headlamp aim too high (1.8)**MOT #7** 2011-11-04 12:28**MOT test number** 546918601330**Result** ✓ Passed**MOT #6** 2010-11-01 14:39**MOT test number** 600005400306**Result** ✓ Passed**MOT #5** 2009-11-06 14:28**MOT test number** 333990319381**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4** 2008-07-10 12:04**MOT test number** 121412398168**Result** ✓ Passed



**MOT #3** 2008-07-09 14:28**MOT test number** 163491598127**Result** ✗ Failed

- Fail** Nearside Headlamp aim too low (1.8)
- Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Offside Headlamp aim too low (1.8)
- Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)

**MOT #2** 2007-06-04 11:39**MOT test number** 212245857150**Result** ✓ Passed

- Notice** Offside wing mirror lens cracked still has a clear veiw to the rear
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #1** 2006-06-13 12:40**MOT test number** 140344666141**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
17 January 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	279
<b>MOT expiry date</b>	17 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>XXXXXX</b>
Plate since	2020-01-01
Current registration	 <b>XXXXXX</b>
Plate since	2020-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2003-06-24
Last registration	2024-01-18
Complete history	<a href="#">See info</a>



Registration #1	2003-06-24	22 mi
Registration #2	2006-06-13	44.523 mi
Registration #3	2007-06-04	57.589 mi
Registration #4	2008-07-09	79.351 mi
Registration #5	2008-07-10	79.351 mi
Registration #6	2009-11-06	94.581 mi
Registration #7	2010-11-01	100.610 mi
Registration #8	2011-11-04	110.654 mi
Registration #9	2012-11-13	126.973 mi
Registration #10	2012-11-13	126.974 mi
Registration #11	2013-11-15	133.549 mi
Registration #12	2014-11-28	137.799 mi
Registration #13	2015-11-05	142.398 mi
Registration #14	2016-05-20	151.377 mi
Registration #15	2016-05-20	151.377 mi
Registration #16	2016-05-20	151.377 mi
Registration #17	2016-05-20	151.377 mi
Registration #18	2016-05-20	151.377 mi
Registration #19	2016-05-20	151.377 mi
Registration #20	2016-05-20	151.377 mi
Registration #21	2016-05-20	151.377 mi
Registration #22	2016-05-20	151.377 mi
Registration #23	2016-05-20	151.377 mi
Registration #24	2016-05-20	151.377 mi
Registration #25	2016-05-20	151.377 mi
Registration #26	2016-05-20	151.377 mi

**More info** >





Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Additional information

Engine number NOT KNOWN