




report date: 2024-03-28

General information

Make	VOLVO
Model	S40 DRIVE SE EDITION START/STOP
Colour	Silver
Year of manufacture	2012
Top speed	121 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	61.4 mpg
Consumption extra urban	85.6 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2022-06-08
Pictures	9
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-09
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	21
Total items failed	6

MOT #11	2023-07-17 10:45
MOT test number	262100027846
Result	✓ Passed
Next expiry date	2024-08-09
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #10	2022-08-10 10:47
MOT test number	786724741981
Result	✓ Passed
Advice	Front windscreen has stone chip

MOT #9	2020-12-17 10:41
MOT test number	364439227602
Result	✓ Passed
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #8** 2019-06-17 15:18**MOT test number** 484067158607**Result** ✓ Passed

- Advice** Power steering component has slight seepage from a component At rack (2.1.5 (a))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))

**MOT #7** 2019-06-14 08:58**MOT test number** 313039522358**Result** ✗ Failed

- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Fail** Nearside Front Service brake excessively fluctuating (1.2.1 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Power steering component has slight seepage from a component At rack (2.1.5 (a))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #6** 2018-06-18 15:27**MOT test number** 252969937004**Result** ✓ Passed

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #5** 2018-06-18 10:55**MOT test number** 245942638386**Result** ✗ Failed**Fail** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Nearside Front Service brake excessively fluctuating (1.2.1 (e))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))**MOT #4** 2017-06-20 14:39**MOT test number** 990790513962**Result** ✓ Passed**MOT #3** 2017-06-19 09:40**MOT test number** 297743196909**Result** ✗ Failed**Fail** Nearside Front coil spring broken (2.4.C.1a)**Fail** Nearside Front Ball joint has excessive play (2.2.B.1f)**MOT #2** 2016-06-23 15:19**MOT test number** 291639081153**Result** ✓ Passed**MOT #1** 2015-06-18 09:33**MOT test number** 726039665185**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
9 August 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	94
<b>MOT expiry date</b>	9 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>SY12XWB</b>
Plate since	2019-09-28
Current registration	<b>SY12XWB</b>
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-06-29
Last registration	2023-07-17
Complete history	<a href="#">See info</a>



Registration #1	2012-06-29	29 mi
Registration #2	2015-06-18	34.307 mi
Registration #3	2016-06-23	44.889 mi
Registration #4	2017-06-19	55.311 mi
Registration #5	2017-06-20	55.311 mi
Registration #6	2018-06-18	66.709 mi
Registration #7	2018-06-18	66.709 mi
Registration #8	2019-06-18	77.109 mi
Registration #9	2019-06-18	77.109 mi
Registration #10	2019-06-18	77.109 mi
Registration #11	2019-06-18	77.109 mi
Registration #12	2019-06-18	77.109 mi
Registration #13	2023-07-17	111.109 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1396 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	2084781