



General information

Make	MINI
Model	CLUBVAN ONE
Colour	White
Year of manufacture	2014
Top speed	115 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	97 BHP
Max. torque	153 Nm at 3.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg
CO2 emission	129 g/km
CO2 label	D







Internet history

Entry 1

Date	2022-05-15
Pictures	36
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-05-27
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	13
Total items failed	1

MOT #9	2024-05-28 14:17
MOT test number	168285575962
Result	✓ Passed
Next expiry date	2025-05-27

MOT #8	2023-04-27 07:50
MOT test number	621455809284
Result	✓ Passed

MOT #7	2022-03-11 12:28
MOT test number	314485542011
Result	✓ Passed

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Central Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Central Front Oil leak, but not excessive (8.4.1 (a) (i))



MOT #6 2021-03-11 11:35

MOT test number 277480921697

Result ✓ Passed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #5 2020-03-09 14:04

MOT test number 642783219840

Result ✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #4 2019-02-28 11:38

MOT test number 117008896024

Result ✓ Passed

- Advice** Exhaust has a minor leak of exhaust gases centre box (6.1.2 (a))

MOT #3 2018-03-05 12:51

MOT test number 741479142856

Result ✓ Passed

- Advice** Slight blow exhaust centre box

MOT #2 2018-03-05 11:39

MOT test number 413563327008

Result ✗ Failed

- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Slight blow exhaust centre box



MOT #1	2017-03-06 12:21
MOT test number	371347549003
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 May 2025

✓
MOT

Expires:
27 May 2025

Tax status Valid until 1 May

Days left 199

MOT expiry date 27 May 2025

Full MOT history [See MOT history](#)

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-




Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	




Damage 2

Date	
Category	
Type	



Extra MINI salvage check

 If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	XXXXX
Plate since	2024-09-18
Current registration	XXXXX
Plate since	2024-09-18

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-03-11
Last registration	2024-05-28
Complete history	See info



Registration #1	2014-03-11	14 mi
Registration #2	2017-03-06	15.618 mi
Registration #3	2018-03-05	23.512 mi
Registration #4	2018-03-05	23.512 mi
Registration #5	2019-02-28	29.108 mi
Registration #6	2020-03-09	36.249 mi
Registration #7	2020-03-09	36.249 mi
Registration #8	2020-03-09	36.249 mi
Registration #9	2020-03-09	36.249 mi
Registration #10	2020-03-09	36.249 mi
Registration #11	2020-03-09	36.249 mi

[More info >](#)



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1683 mm
Height	1426 mm
Length	3961 mm
Wheel base	2547 mm
Kerb weight	1140 kg
Max. allowed weight	1640 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of seats	2
Number of axles	2
Engine number	A454J527