





report date: 2024-03-29

## General information

Make	CITROEN
Model	RELAY 35 L2H2 ENTERPRISE BLUEHDI
Colour	White
Year of manufacture	2019
Top speed	92 mph
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	130 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	47.9 mpg
Consumption combined	45.6 mpg
CO2 emission	163 g/km
CO2 label	G



CarCheck.co.uk page 1/11



report date: 2024-03-29

## Internet history

#### Entry 3

Date 2021-07-03

Pictures 7

Listing price View report









source: autoonline.co.uk

#### Entry 2

Date 2021-07-02

Pictures 7

Listing price <u>View report</u>









source: heycar.co.uk

#### Entry 1

Date 2021-06-30

Pictures 10

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

# MOT history

MOT expiry date	2023-12-13
MOT pass rate	40 %
MOT passed	2
Failed MOT tests	3
Total advice items	6
Total items failed	6

MOT #5	2022-12-14 08:43	
MOT test number	268868383033	
Result	<b>✓</b> Passed	
Next expiry date	2023-12-13	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))		
Advice Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))		

MOT #4	2022-12-10 10:50
MOT test number	150338500805
Result	<b>X</b> Failed
Advice Offside Front Tyre worn close to legal limit/worn on edge inside edge (5.2.3 (e))	
Fail Parking brake efficiency below requirements (1.4.2 (a) (i))	
Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge inside edge (5.2.3 (e))	
Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

 MOT #3
 2022-11-14 08:44

 MOT test number
 289985164358

Result × Failed

Fail Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #2 2021-11-24 11:28

**MOT test number** 948217787603

Result 

Passed

**MOT #1** 2021-11-23 13:44

**MOT test number** 518134506551

**Result** X Failed

**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure Out of shape inner/outer edges (5.2.3 (d) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-29

## Tax & MOT check





Expired: 13 December 2023

Tax status	Valid until 1 November
Days left	185
MOT expiry date	13 December 2023
Full MOT history	See MOT history

## Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

## Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

## Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

More info >

# Owner history For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this CITROEN had different number plates. deer of plates factor scincore

CarCheck.co.uk page 8/11



LF19UBO report date: 2024-03-29

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >


CarCheck.co.uk page 9/11



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2019-03-19
Last registration	2022-12-14
Complete history	See info



Registration #1	2019-03-19	22 mi
Registration #2		11.777 es
Registration #3		0.074
Registration #4		71.777 66
Registration #5	2021-11-23	26.261 mi
Registration #6		71,777 es
Registration #7		71,777 66
Registration #8		71,777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

## Safety ratings

NCAP rating	<b>大大大</b> 大大
Adult	59%
Children	86%
Pedestrian	26%
Safety systems	26%
Overall rating	54%
Video	see crash video



# Dimensions & weight

Width	2508 mm
Height	2524 mm
Length	5413 mm
Kerb weight	1925 kg
Max. allowed weight	3500 kg

## Additional information

Fuel tank capacity	90 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Number of axles	2
Engine number	DY2Z4002019

CarCheck.co.uk page 11/11