





#### General information

Make	BMW
Model	118 420D M SPORT GRAN COUPE
Colour	Black
Year of manufacture	2017
Top speed	144 mph
Gearbox	8 speed automatic

## Engine & fuel consumption

Power	188 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	С





Internet history	
Entry 2	
Date	2024-02-12
Pictures	0
Listing price	View report
source: carcraft.co.uk	
Entry 1	
Date	2021-06-06
Pictures	0
Listing price	View report

source: autotrader.co.uk



## MOT history

MOT expiry date	2025-02-21
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	8
Total items failed	2

MOT #7	2024-02-22 09:25
MOT test number	548445339786
Result	✓ Passed
Next expiry date	2025-02-21

МОТ #6	2024-02-20 16:03
MOT test number	707355316247
Result	🗙 Failed
<b>Fail</b> Nearside Rear Tyre tread pattern not visible over the whole tread area when m is 1.0mm (5.2.3 (e))	ninimum depth required
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Rear Fluid leak, but not excessive differential (8.4.1 (a) (i))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #5	2023-06-12 15:51
MOT test number	226553075054
Result	✓ Passed
MOT #4	2022-06-13 08:59
MOT test number	513667121776

Result

✓ Passed





MOT #3	2021-06-21 10:59
MOT test number	362235018897
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MOT #2	2020-09-01 07:28
MOT test number	107993421909
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MOT #1	2020-08-28 08:52
MOT test number	517142700614
Result	🗙 Failed
<b>Fail</b> Nearside Rear Tyre has a cut in excess of the requirements deep enough outer sidewall (5.2.3 (d) (i))	to reach the ply or cords
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	



Tax & MOT check

√ Taxed	✓ MOT
<b>Tax due:</b> 1 April 2025	<b>Expires:</b> 21 February 2025
Tax status	Valid until 1 April
Days left	336
MOT expiry date	21 February 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-





#### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Date	A.F.
Category	ante.
Туре	

#### Extra BMW salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second sec	
************	
********	
******	
************	
********	
	More info >
Plate changes See in this check if this BMW had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Carrent registration	
Carrent registration Plate since	





#### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





## Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-08-14
Last registration	2024-02-22
Complete history	<u>See info</u>



Registration #1	2017-08-14	29 mi
Registration #2	2020-08-28	31.992 mi
Registration #3	2020-09-01	31.993 mi
Registration #4		11.117 esi
Registration #5	2021-06-21	34.812 mi
Registration #6		
Registration #0		
Registration #7		11.117 mi
		10.000 mil
Registration #7		10.000 mil

More info >





## Car features

S0225	Air conditioning
\$0295	
50482	
60501	
0566	
60567	
60569	

# Safety ratings

NCAP rating	****
Adult	87%
Children	86%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	<u>see crash video</u>



Dimensions & weight	
Width	1825 mm
Height	1397 mm
Length	4638 mm
Wheel base	2810 mm
Kerb weight	1540 kg
Max. allowed weight	2100 kg
Additional information	
Fuel tank capacity	57
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles	2
Engine number	71629825