




report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA EXCLUSIV CDTI S/S
Colour	Black
Year of manufacture	2013
Top speed	117 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	54.3 mpg
Consumption combined	46.3 mpg
CO2 emission	160 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-09-21
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk

**MOT history**

<b>MOT expiry date</b>	2025-01-20
<b>MOT pass rate</b>	64 %
<b>MOT passed</b>	9
<b>Failed MOT tests</b>	5
<b>Total advice items</b>	33
<b>Total items failed</b>	9

<b>MOT #14</b>	2024-01-18 11:30
<b>MOT test number</b>	931102730402
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2025-01-20
<b>Advice</b>	Nearside Rear Tyre slightly damaged/cracking or perishing cracked/perished (5.2.3 (d) (ii))
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))

<b>MOT #13</b>	2024-01-18 10:25
<b>MOT test number</b>	104563872369
<b>Result</b>	✗ Failed
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))
<b>Advice</b>	Nearside Rear Tyre slightly damaged/cracking or perishing cracked/perished (5.2.3 (d) (ii))
<b>Fail</b>	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
<b>Fail</b>	Nearside Headlamp aim unable to be tested dip beam inop (4.1.2 (b))

<b>MOT #12</b>	2023-01-11 15:02
<b>MOT test number</b>	935567214345
<b>Result</b>	✓ Passed
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))
<b>Advice</b>	Nearside Rear Tyre slightly damaged/cracking or perishing cracked/perished (5.2.3 (d) (ii))

**MOT #11**

2023-01-10 17:43

**MOT test number**

878676172464

**Result****✗ Failed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracked/perished (5.2.3 (d) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement lower arm, rear bush (5.3.4 (a) (i))
- Fail** Nearside Front Suspension arm pin or bush excessively worn lower arm, rear bush (5.3.4 (a) (ii))

**MOT #10**

2022-01-21 09:01

**MOT test number**

681390004265

**Result****✓ Passed****MOT #9**

2021-06-05 09:06

**MOT test number**

973874576839

**Result****✓ Passed**

- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Nail in tyre
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Exhaust joints corroded

**MOT #8** 2020-06-08 09:16**MOT test number** 111776508716**Result** ✓ Passed**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #7** 2020-06-03 08:34**MOT test number** 431576940753**Result** ✗ Failed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Fail** Reversing lamp inoperative (4.6.1 (a))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**MOT #6** 2019-05-21 10:55**MOT test number** 115907112221**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5** 2019-05-21 10:55**MOT test number** 499925391988**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Rear Reversing lamp inoperative (4.6.1 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #4** 2018-05-05 10:55**MOT test number** 481779515614**Result** ✓ Passed**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**MOT #3** 2018-05-04 09:57**MOT test number** 584295562370**Result** ✗ Failed**Fail** Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Fail** Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #2** 2017-05-22 12:19**MOT test number** 311641135432**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Front Tyre worn close to the legal limit and wearing on inner edge (4.1.E.1)



MOT #1	2016-05-24 11:49
MOT test number	694541832235
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
20 January 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	20 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	<b>LY13AHV</b>
Plate since	2019-09-29
Current registration	<b>LY13AHV</b>
Plate since	2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-07-19
Last registration	2024-01-18
Complete history	<a href="#">See info</a>



Registration #1	2013-07-19	10 mi
Registration #2	2016-05-24	27.890 mi
Registration #3	2017-05-22	37.077 mi
Registration #4	2018-05-04	47.717 mi
Registration #5	2018-05-05	47.717 mi
Registration #6	2019-05-21	60.148 mi
Registration #7	2019-05-21	60.148 mi
Registration #8	2020-06-03	67.493 mi
Registration #9	2020-06-03	67.493 mi
Registration #10	2020-06-03	67.493 mi
Registration #11	2020-06-03	67.493 mi
Registration #12	2020-06-03	67.493 mi
Registration #13	2020-06-03	67.493 mi
Registration #14	2020-06-03	67.493 mi
Registration #15	2020-06-03	67.493 mi
Registration #16	2020-06-03	67.493 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2085 mm
Height	1761 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1836 kg
Max. allowed weight	2505 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 263998K LNQ