



report date: 2024-03-29

General information

Make	MAZDA
Model	2 TAMURA
Colour	Green
Year of manufacture	2010
Top speed	107 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	122 Nm at 3.500 rpm
Engine capacity	1.349 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	67.3 mpg
Consumption combined	54.3 mpg
CO2 emission	125 g/km
CO2 label	D







Internet history

Entry 1

Date	2021-06-20
Pictures	15
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-09
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	23
Total items failed	3

MOT #9 2018-11-27 13:57

MOT test number 317562540366

Result ✓ Passed

Next expiry date 2019-12-01

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front arm rear bush (5.3.4 (a) (i))

MOT #8 2018-11-24 12:31

MOT test number 627568529851

Result ✗ Failed

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front arm rear bush (5.3.4 (a) (i))

MAJOR Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MAJOR Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Advice Front Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #7** 2017-11-21 16:28**MOT test number** 391941410806**Result** ✓ Passed**Advice** Play in steering rack inner joint(s)**MOT #6** 2017-11-21 09:23**MOT test number** 470077493203**Result** ✗ Failed**Advice** Play in steering rack inner joint(s)**Advice** Front Lower sump corroded**Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #5** 2016-11-18 14:18**MOT test number** 544678481863**Result** ✓ Passed**Advice** Items removed from driver's view prior to test**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2015-11-20 15:27**MOT test number** 855943535450**Result** ✓ Passed

**MOT #3** 2014-12-02 14:29**MOT test number** 185546434314**Result** ✓ Passed**Notice** Both front tyres starting to split on inner sidewalls**Notice** Both rear tyres perishing within tread**Notice** Both front tyres perishing within tread/wearing on edges**MOT #2** 2013-08-02 13:37**MOT test number** 126884013216**Result** ✓ Passed**Notice** Rear wiper split**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #1** 2013-08-02 12:12**MOT test number** 597684613269**Result** ✗ Failed**Notice** Rear wiper split**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
9 May 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	9 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2010-01-28
Last registration	2018-11-27
Complete history	See info



Registration #1	2010-01-28	25 mi
Registration #2	2013-08-02	33.582 mi
Registration #3	2013-08-02	33.582 mi
Registration #4	2014-12-02	33.728 mi
Registration #5	2015-11-20	40.004 mi
Registration #6	2016-11-18	51.389 mi
Registration #7	2017-05-22	55.277 mi
Registration #8	2017-05-22	55.277 mi
Registration #9	2017-05-22	55.277 mi
Registration #10	2017-05-22	55.277 mi
Registration #11	2018-11-27	55.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1475 mm
Length	3895 mm
Wheel base	2490 mm
Kerb weight	1030 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	ZJ 803747