



report date: 2024-03-29

## General information

Make	VAUXHALL
Model	AGILA EXPRESSION
Colour	Black
Year of manufacture	2008
Top speed	99 mph
0 - 60 mph	14.1 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	65 BHP
Max. torque	90 Nm at 4.800 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	47.9 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg
CO2 emission	120 g/km
CO2 label	C





Internet history

Entry 1

Date	2022-01-20
Pictures	11
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-12-06
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	26
Total items failed	0

MOT #17	2023-11-24 15:38
MOT test number	904387546909
Result	✓ Passed
Next expiry date	2024-12-06
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #16	2023-11-13 14:47
MOT test number	833033005779
Result	✗ Failed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
MAJOR	Nearside Windscreen washer not working (3.5 (a))
MAJOR	Brake hose ferrule excessively corroded both rear hoses (1.1.12 (f) (i))
MAJOR	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
MAJOR	Offside Rear Brake pipe excessively corroded on axle (1.1.11 (c))

MOT #15	2022-12-06 15:26
MOT test number	887533010218
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #14**

2022-12-02 11:03

**MOT test number**

457862455354

**Result****✗ Failed****Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Battery insecure and likely to fall from carrier (4.13 (a) (ii))**MAJOR** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MAJOR** Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))**MOT #13**

2021-11-11 12:34

**MOT test number**

520921666412

**Result****✓ Passed****Advice** Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Front Macpherson strut pin or bush worn but not resulting in excessive movement offside and nenside (5.3.4 (a) (i))**MOT #12**

2021-11-10 10:14

**MOT test number**

462143075084

**Result****✗ Failed****Advice** Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #11**

2020-12-01 13:31

**MOT test number**

630614025597

**Result****✓ Passed****Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Play in steering rack inner joint(s)

**MOT #10** 2020-11-26 14:41**MOT test number** 429060686272**Result** ✗ Failed**Advice** Play in steering rack inner joint(s)**DANGEROUS** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**DANGEROUS** Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #9** 2019-12-07 10:16**MOT test number** 287054450111**Result** ✓ Passed**MOT #8** 2018-09-26 08:12**MOT test number** 256114168352**Result** ✓ Passed**MOT #7** 2017-11-11 11:22**MOT test number** 215316586836**Result** ✓ Passed**MOT #6** 2016-11-05 10:08**MOT test number** 874464882230**Result** ✓ Passed**MOT #5** 2015-11-07 12:50**MOT test number** 151030835637**Result** ✓ Passed



MOT #4	2014-11-03 12:21
MOT test number	425317404332
Result	✓ Passed
MOT #3	2013-11-13 15:20
MOT test number	356657613389
Result	✓ Passed
MOT #2	2012-11-30 11:04
MOT test number	557255032387
Result	✓ Passed
MOT #1	2011-12-02 16:12
MOT test number	728626631368
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 August 2024

✓  
**MOT**

**Expires:**  
6 December 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	93
<b>MOT expiry date</b>	6 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>LC58VGX</b>
Plate since	2019-03-29
Current registration	 <b>LC58VGX</b>
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-12-29
Last registration	2023-11-24
Complete history	<a href="#">See info</a>



Registration #1	2008-12-29	24 mi
Registration #2	2011-12-02	21.878 mi
Registration #3	2012-11-30	24.327 mi
Registration #4	2013-11-13	36.184 mi
Registration #5	2014-11-03	45.944 mi
Registration #6	2015-11-07	47.190 mi
Registration #7	2016-11-05	47.755 mi
Registration #8	2017-11-11	48.982 mi
Registration #9	2018-09-26	54.066 mi
Registration #10	2019-12-07	66.988 mi
Registration #11	2020-05-20	75.377 mi
Registration #12	2020-05-20	75.377 mi
Registration #13	2020-05-20	75.377 mi
Registration #14	2020-05-20	75.377 mi
Registration #15	2020-05-20	75.377 mi
Registration #16	2020-05-20	75.377 mi
Registration #17	2020-05-20	75.377 mi
Registration #18	2020-05-20	75.377 mi
Registration #19	2020-05-20	75.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	975 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	1023339