



report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT 260 LR P/V
Colour	White
Year of manufacture	2011
Gearbox	5 speed Manual

Engine & fuel consumption

Power	84 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel





LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-22
Pictures	14
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-03-16
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	29
Total items failed	11

MOT #16	2024-02-18 11:25
MOT test number	536243105348
Result	✓ Passed
Next expiry date	2025-03-16

MOT #15	2024-02-16 12:03
MOT test number	812382694966
Result	✗ Failed
MAJOR Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength inner wheel arch (5.3.6 (a) (i))	

MOT #14	2023-03-17 16:47
MOT test number	547055276999
Result	✓ Passed
Advice Offside Integral body structure is corroded but structural rigidity is not significantly reduced inner seal (6.1.1 (c) (i))	
Advice Offside Front Brake pipe corroded, covered in grease or other material under chassis rail (1.1.11 (c))	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice Nearside Front Brake pipe corroded, covered in grease or other material under chassis rail (1.1.11 (c))	

MOT #13	2022-03-04 16:02
MOT test number	317594004209
Result	✓ Passed

**MOT #12**

2022-03-04 10:30

MOT test number

544199259103

Result

✗ Failed

DANGEROUS Offside Front Anti-roll bar linkage fractured (5.3.3 (b) (ii))**MOT #11**

2021-01-19 14:40

MOT test number

456180349569

Result

✓ Passed

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #10**

2020-01-10 14:41

MOT test number

460969893569

Result

✓ Passed

Minor Nearside Windscreen damaged but not adversely affecting driver's view stone chip (3.2 (a) (i))**Advice** Offside Rear Outer Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Outer Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #9** 2020-01-10 13:49**MOT test number** 133575602914**Result** ✗ Failed**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MAJOR** Offside Front Suspension arm pin or bush excessively worn wishbone rear bush (5.3.4 (a) (i))**Advice** Offside Rear Outer Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Nearside Windscreen damaged but not adversely affecting driver's view stone chip (3.2 (a) (i))**MAJOR** Nearside Front Suspension arm pin or bush excessively worn wishbone rear bush (5.3.4 (a) (i))**Advice** Nearside Rear Outer Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #8** 2019-01-09 17:31**MOT test number** 229842199349**Result** ✓ Passed**Advice** Vehicles internal headlight adjuster altered to recheck lights**MOT #7** 2019-01-09 17:31**MOT test number** 388740339269**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**Advice** Vehicles internal headlight adjuster altered to recheck lights**Pass with rectification** Headlamp aim too low (4.1.2 (a))**MOT #6** 2018-01-05 14:00**MOT test number** 152965310503**Result** ✓ Passed

**MOT #5** 2018-01-04 14:45**MOT test number** 811051582881**Result** ✗ Failed

- Fail** Brake pedal anti-slip provision incomplete (3.3.A.1b)
- Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #4 2017-01-10 15:53**MOT test number** 902889377573**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2017-01-10 12:22**MOT test number** 499124394094**Result** ✗ Failed

- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside front brake excessively fluctuating (3.7.B.3)
- Fail** Nearside Stop lamp not working (1.2.1b)
- Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Nearside front brake excessively fluctuating (3.7.B.3)
- Fail** Front Brakes imbalanced across an axle (3.7.B.5b)

MOT #2 2016-01-13 08:38**MOT test number** 428932052900**Result** ✓ Passed



MOT #1	2015-01-05 15:39
MOT test number	757285005054
Result	✓ Passed
Advice	Offside Front Shock absorber has a light misting of oil (2.7.3)
Advice	Nearside Front Shock absorber has a light misting of oil (2.7.3)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
16 March 2025

Tax status		Valid until 1 July
Days left		63
MOT expiry date		16 March 2025
Full MOT history		See MOT history



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	YR61CYL
Plate since	2024-03-28
Current registration	YR61CYL
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-09-30
Last registration	2024-02-18
Complete history	See info



Registration #1	2011-09-30	17 mi
Registration #2	2015-01-05	48.657 mi
Registration #3	2016-01-13	72.642 mi
Registration #4	2017-01-10	88.769 mi
Registration #5	2017-01-10	88.769 mi
Registration #6	2018-01-04	99.879 mi
Registration #7	2018-01-05	99.879 mi
Registration #8	2019-01-09	108.045 mi
Registration #9	2019-01-09	108.045 mi
Registration #10	2019-01-09	108.045 mi
Registration #11	2019-01-09	108.045 mi
Registration #12	2019-01-09	108.045 mi
Registration #13	2019-01-09	108.045 mi
Registration #14	2019-01-09	108.045 mi
Registration #15	2019-01-09	108.045 mi
Registration #16	2019-01-09	108.045 mi
Registration #17	2019-01-09	108.045 mi
Registration #18	2019-01-09	108.045 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2360 mm
Height	1989 mm
Length	4863 mm
Kerb weight	1699 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	AA82133