



report date: 2024-03-29

General information

Make	MAZDA
Model	5 D TS2 7STR
Colour	Silver
Year of manufacture	-
Top speed	111 mph
0 - 60 mph	12.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	310 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	44.8 mpg





LABEL UNKNOWN



Internet history

Entry 1

Date	2021-12-12
Pictures	25
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT #17</b>	2022-10-15 07:27
<b>MOT test number</b>	778000288118
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-10-14
<b>Advice</b>	Rear brake discs rusty
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #16</b>	2021-10-08 10:48
<b>MOT test number</b>	846930554224
<b>Result</b>	✓ Passed
<b>Advice</b>	General corrosion
<b>Advice</b>	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
<b>Advice</b>	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

<b>MOT #15</b>	2020-10-06 08:58
<b>MOT test number</b>	672919156484
<b>Result</b>	✓ Passed
<b>Advice</b>	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
<b>Advice</b>	Slight corrosion to underside of vehicle
<b>Advice</b>	Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

**MOT #14**

2019-10-08 11:42

**MOT test number**

310810594485

**Result**

✓ Passed

- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Undertrays fitted
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Surface corrosion on underside of vehicle
- Advice** Slight uneven wear on rear tyres

**MOT #13**

2019-10-08 11:42

**MOT test number**

285946535395

**Result**

✗ Failed

- Advice** Surface corrosion on underside of vehicle
- Advice** Slight uneven wear on rear tyres
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Undertrays fitted
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #12** 2018-10-05 13:10**MOT test number** 151814637642**Result** ✓ Passed

**Advice** Offside Inner Vehicle structure is corroded but structural rigidity is not significantly reduced sill (6.1.1 (c) (i))

**Advice** Offside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced chassis leg (6.1.1 (c) (i))

**Advice** Nearside Inner Vehicle structure is corroded but structural rigidity is not significantly reduced sill (6.1.1 (c) (i))

**Advice** Nearside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced chassis leg (6.1.1 (c) (i))

**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #11** 2017-10-10 15:34**MOT test number** 851562191941**Result** ✓ Passed

**Advice** Rear Anti-roll bar linkage worn but not seriously weakened both (2.4.G.1)

**Advice** Surface corrosion to seals

**MOT #10** 2016-10-04 10:49**MOT test number** 922728456816**Result** ✓ Passed**MOT #9** 2016-10-03 11:03**MOT test number** 581941047245**Result** ✗ Failed

**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

**MOT #8** 2015-10-01 15:52**MOT test number** 826415833006**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Engine warning light came on when idling**MOT #7** 2015-09-28 14:29**MOT test number** 370850383924**Result** ✗ Failed**Fail** Nearside Front Lower Bonded suspension unit bonding failed and part of unit is likely to become displaced arm (2.4.F.2)**Fail** Electronic stability system warning lamp indicates a fault (3.4.1c)**Fail** Nearside Rear coil spring broken (2.4.C.1a)**Advice** Engine warning light came on when idling**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2014-09-26 09:38**MOT test number** 308309464258**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #5** 2013-09-23 11:37**MOT test number** 776116863203**Result** ✓ Passed



MOT #4	2012-09-25 09:18
MOT test number	329309362272
Result	✓ Passed
MOT #3	2011-09-23 09:53
MOT test number	506266361274
Result	✓ Passed
MOT #2	2011-09-23 09:11
MOT test number	195166761244
Result	✗ Failed
<div><div>Fail</div>Nearside Rear Shock absorber has a serious fluid leak (2.7.3)</div>	
MOT #1	2010-09-29 16:41
MOT test number	931312070204
Result	✓ Passed



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-09-30
Last registration	2022-10-15
Complete history	<a href="#">See info</a>



Registration #1	2007-09-30	16 mi
Registration #2	2010-09-29	32.558 mi
Registration #3	2011-09-23	40.549 mi
Registration #4	2011-09-23	40.549 mi
Registration #5	2012-09-25	51.391 mi
Registration #6	2013-09-23	65.955 mi
Registration #7	2014-09-26	77.879 mi
Registration #8	2015-09-28	90.098 mi
Registration #9	2015-10-01	90.183 mi
Registration #10	2016-10-03	102.221 mi
Registration #11	2016-10-03	102.221 mi
Registration #12	2016-10-03	102.221 mi
Registration #13	2016-10-03	102.221 mi
Registration #14	2016-10-03	102.221 mi
Registration #15	2016-10-03	102.221 mi
Registration #16	2016-10-03	102.221 mi
Registration #17	2016-10-03	102.221 mi
Registration #18	2016-10-03	102.221 mi
Registration #19	2016-10-03	102.221 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1755 mm
Height	1665 mm
Length	4505 mm
Wheel base	2750 mm
Kerb weight	1645 kg
Max. allowed weight	2225 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	RF 261439