



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM
Colour	Silver
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	194 BHP
Max. torque	422 Nm at 1.900 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	50.4 mpg
Consumption combined	41.5 mpg
CO2 emission	176 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-06-13
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-07-02
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	16
Total items failed	2

MOT #12 2023-06-29 09:44

MOT test number 813875477431

Result ✓ Passed

Next expiry date 2024-07-02

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #11 2022-06-14 08:54

MOT test number 540530637375

Result ✓ Passed

Advice Rear Suspension arm corroded but not seriously weakened multipool arms (5.3.3 (b) (i))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #10 2022-06-14 08:54

MOT test number 935445230766

Result ✗ Failed

Pass with rectification Nearside Headlamp aim too high (4.1.2 (a))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Pass with rectification Offside Headlamp aim too high (4.1.2 (a))

Advice Rear Suspension arm corroded but not seriously weakened multipool arms (5.3.3 (b) (i))



MOT #9	2021-07-03 07:07
MOT test number	952244244635
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge bad on inside (5.2.3 (e))

MOT #8	2021-06-25 11:25
MOT test number	974931908695
Result	✗ Failed
MAJOR	Nearside Rear Other passenger door cannot be opened from outside the vehicle or inside (6.2.3 (a))
MAJOR	Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
MAJOR	Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge bad on inside (5.2.3 (e))

MOT #7	2020-08-18 11:17
MOT test number	136866458175
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge worn heavily on inner edge (5.2.3 (e))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #6	2019-08-28 11:52
MOT test number	411160286513
Result	✓ Passed

MOT #5	2018-08-23 08:17
MOT test number	186664442463
Result	✓ Passed
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))



MOT #4	2017-08-03 13:26
MOT test number	369672858514
Result	✓ Passed
Advice	N/s o/s rear tyres worn on inner edge

MOT #3	2016-08-11 09:23
MOT test number	814043232337
Result	✓ Passed

MOT #2	2015-08-19 07:01
MOT test number	663084661831
Result	✓ Passed

MOT #1	2014-08-26 10:43
MOT test number	308278234465
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
2 July 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	2 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	BF61KPP
Plate since	2019-09-28
Current registration	BF61KPP
Plate since	2019-09-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-09-01
Last registration	2023-06-29
Complete history	See info



Registration #1	2011-09-01	6 mi
Registration #2	2014-08-26	22.363 mi
Registration #3	2015-08-19	31.805 mi
Registration #4	2016-08-11	41.551 mi
Registration #5	2017-08-03	49.501 mi
Registration #6	2018-08-23	58.398 mi
Registration #7	2019-08-28	65.794 mi
Registration #8	2020-06-29	75.277 mi
Registration #9	2021-06-29	85.277 mi
Registration #10	2022-06-29	95.277 mi
Registration #11	2023-06-29	105.277 mi
Registration #12	2024-06-29	115.277 mi
Registration #13	2025-06-29	125.277 mi
Registration #14	2026-06-29	135.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1890 mm
Height	1760 mm
Length	4660 mm
Wheel base	2700 mm
Kerb weight	1920 kg
Max. allowed weight	2570 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number	D4HBAU340655
---------------	--------------