





report date: 2024-03-28

General information

Make	SUZUKI
Model	VITARA SZ-T
Colour	Red
Year of manufacture	2017
Top speed	112 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	156 Nm at 4.400 rpm
Engine capacity	1.586 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	53.3 mpg
CO2 emission	123 g/km
CO2 label	D



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date	2021-02-04	
Pictures	1	
Listing price	<u>View report</u>	



source: autoonline.co.uk

CarCheck.co.uk page 2/12



B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-07-20
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	15
Total items failed	6

MOT #6		2023-07-10 11:05
MOT test	number	739465504085
Result		✓ Passed
Next expi	ry date	2024-07-20
Advice	Rear wiper blade split	
Advice	Offside Front Play in steering rack inner joint(s)	
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

CarCheck.co.uk page 3/12



MK67JZH

report date: 2024-03-28

MOT #5 2023-07-06 11:03 778882254955 **MOT test number** Result × Failed Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii)) Rear Registration plate deteriorated but not likely to be misread (0.1 (b)) **Advice** Fail Offside Front Position lamp not working (4.2.1 (a) (ii)) Advice Offside Front Play in steering rack inner joint(s) Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii)) Fail **Advice** Rear wiper blade split Nearside Front Position lamp not working (4.2.1 (a) (ii)) Fail **Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #4	2022-07-21 11:35
MOT test number	303096481965
Result	✓ Passed
MOT #3	2021-10-01 13:24
MOT test number	530870623116
Result	✓ Passed

		•
MOT #2		2020 10 05 15 20
MOT #2		2020-10-05 15:28
MOT test	number	826601809974
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.	14 (a) (ii))
Advice	Oil change sign on	

CarCheck.co.uk page 4/12



MOT #1 2020-10-05 12:03

MOT test number 442623758009

Result X Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Oil change sign on

Fail Nearside Rear Position lamp not working (4.2.1 (a) (ii))

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 September
Days left	126
MOT expiry date	20 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 6/12



MK67JZH

report date: 2024-03-28

Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e when miscory		
For how long did the current and previous owner(s) have this SUZUKI? How many owners have? Check it in the premium report and see all owner registrations. Download the full is		

	More info	>
Plate changes		
See in this check if this SUZUKI had different number plates.		
Number of plates		,
Current registration	UK NEW	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this SUZUKI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-09-14
Last registration	2023-07-10
Complete history	See info



Registration #1	2017-09-14	25 mi
Registration #2	2020-10-05	56.505 mi
Registration #3	2020-10-05	56.505 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	****
Adult	89%
Children	85%
Pedestrian	76%
Safety systems	75%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1775 mm
Height	1610 mm
Length	4175 mm
Wheel base	2500 mm
Kerb weight	1150 kg
Max. allowed weight	1730 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	M16A-2091179

CarCheck.co.uk page 12/12