



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN FSI SE 7 STR
Colour	Black
Year of manufacture	2004
Top speed	116 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	155 Nm at 4.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.1 mpg
Consumption extra urban	44.1 mpg
Consumption combined	37.2 mpg
CO2 emission	180 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-06-12
Pictures	15
Listing price	View report



source: yesauto.com





MOT history

MOT expiry date	2025-01-26
MOT pass rate	73 %
MOT passed	16
Failed MOT tests	6
Total advice items	37
Total items failed	21

MOT #22	2024-01-27 12:07
MOT test number	994144834013
Result	✓ Passed
Next expiry date	2025-01-26

MOT #21	2021-08-05 13:31
MOT test number	261392762598
Result	✓ Passed

MOT #20	2021-08-04 15:05
MOT test number	511579769499
Result	✗ Failed

Fail Offside Rear Service brake excessively binding (1.2.1 (f))

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt insecure (5.3.4 (b) (ii))

Advice EPC light illuminated

Fail Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #19** 2020-04-27 09:26**MOT test number** 789122373572**Result** ✓ Passed**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Minor** Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #18** 2019-04-04 10:41**MOT test number** 803432889962**Result** ✓ Passed**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #17** 2019-04-03 13:29**MOT test number** 118165222334**Result** ✗ Failed**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #16** 2018-04-16 15:20**MOT test number** 653294333895**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit both side (4.1.E.1)**MOT #15** 2017-04-12 16:55**MOT test number** 617183013653**Result** ✓ Passed**Advice** Tyre worn close to the legal limit Both front tyres wearing on inner edge (4.1.E.1)**MOT #14** 2017-04-12 10:22**MOT test number** 560911649463**Result** ✗ Failed**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**Pass with rectification** Offside Rear position lamp(s) not working (1.1.A.3b)**Fail** Offside Front Anti-roll bar linkage ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Advice** Tyre worn close to the legal limit Both front tyres wearing on inner edge (4.1.E.1)**MOT #13** 2016-04-05 11:16**MOT test number** 252062589401**Result** ✓ Passed

**MOT #12** 2016-04-05 11:16**MOT test number** 881206597800**Result** ✗ Failed

- Pass with rectification** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Pass with rectification** Nearside Stop lamp not working (1.2.1b)
- Pass with rectification** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Pass with rectification** Nearside Rear position lamp(s) not working (1.1.A.3b)
- Pass with rectification** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)

MOT #11 2015-02-10 12:57**MOT test number** 386041545080**Result** ✓ Passed**MOT #10** 2014-05-14 13:37**MOT test number** 828984634190**Result** ✓ Passed

- Notice** Offside front suspension coil spring, both rear suspension coil springs and rear antiroll bar starting to rust
- Notice** Rear screen washerr jet not working
- Notice** Front suspension lower wishbones inner rear bushes slight movement
- Notice** Offside door mirror glass small cracks
- Notice** Rear indicator bulbs starting to discolour

**MOT #9**

2014-05-14 11:17

MOT test number

247294734479

Result**✗ Failed**

- Notice** Offside door mirror glass small cracks
- Notice** Rear indicator bulbs starting to discolour
- Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)
- Notice** Offside front suspension coil spring, both rear suspension coil springs and rear antiroll bar starting to rust
- Notice** Nearside front tyre tread worn to 2mm and inner edge worn low
- Notice** Rear screen washerr jet not working
- Fail** Offside Rear Stop lamp not working (1.2.1b)
- Notice** Front suspension lower wishbones inner rear bushes slight movement

MOT #8

2013-05-18 12:41

MOT test number

607598133105

Result**✓ Passed**

- Notice** Rear indicator bulbs starting to discolour
- Notice** Offside front tyre tread inner edge starting to wear
- Notice** Front brake pads wearing low
- Notice** Both rear and offside front suspension coil springs starting to rust
- Notice** Rear screen washer jet not working
- Notice** Both rear tyre treads inner edges worn low
- Notice** Front lower suspension wishbones inner rear bushes slight movement
- Notice** Brake discs starting to wear



MOT #7	2012-04-21 10:16
---------------	------------------

MOT test number	898022712126
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2011-05-17 09:22
---------------	------------------

MOT test number	545027731156
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2010-05-14 09:58
---------------	------------------

MOT test number	113254730156
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2009-05-19 10:38
---------------	------------------

MOT test number	460469339136
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2008-04-30 16:33
---------------	------------------

MOT test number	131701628100
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2007-04-11 12:18
---------------	------------------

MOT test number	773701807132
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
---------------	---

Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	--



MOT #1	2007-04-11 09:55
MOT test number	253151507175
Result	✗ Failed
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
26 January 2025

Tax status	Valid until 1 January
Days left	247
MOT expiry date	26 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2023-03-29
Current registration	 *****
Plate since	2023-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-04-30
Last registration	2024-01-27
Complete history	See info



Registration #1	2004-04-30	25 mi
Registration #2	2007-04-11	23.073 mi
Registration #3	2007-04-11	23.073 mi
Registration #4	2008-04-30	29.264 mi
Registration #5	2009-05-19	37.572 mi
Registration #6	2010-05-14	43.623 mi
Registration #7	2011-05-17	50.815 mi
Registration #8	2012-04-21	54.950 mi
Registration #9	2013-05-18	62.964 mi
Registration #10	2014-05-14	70.478 mi
Registration #11	2015-02-10	75.981 mi
Registration #12	2016-04-05	79.671 mi
Registration #13	2016-05-20	81.377 mi
Registration #14	2016-05-20	81.377 mi
Registration #15	2016-05-20	81.377 mi
Registration #16	2016-05-20	81.377 mi
Registration #17	2016-05-20	81.377 mi
Registration #18	2016-05-20	81.377 mi
Registration #19	2016-05-20	81.377 mi
Registration #20	2016-05-20	81.377 mi
Registration #21	2016-05-20	81.377 mi
Registration #22	2016-05-20	81.377 mi
Registration #23	2016-05-20	81.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1652 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1498 kg
Max. allowed weight	2160 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of axles	2
Engine number	BAG 016823