



report date: 2024-03-28

General information

Make	AUDI
Model	TT ROADSTER 150
Colour	Blue
Year of manufacture	2003
Top speed	133 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	210 Nm at 1.750 rpm
Engine capacity	1.781 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	43.5 mpg
Consumption combined	34.0 mpg
CO2 emission	197 g/km
CO2 label	J






Internet history

Entry 2


Date	2021-07-05
Pictures	8
Listing price	View report



source: autotrader.co.uk

Entry 1

Date	2021-05-21
Pictures	8
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2022-06-08
MOT pass rate	65 %
MOT passed	15
Failed MOT tests	8
Total advice items	56
Total items failed	15

MOT #23	2021-05-17 15:22
MOT test number	461370671845
Result	✓ Passed
Next expiry date	2022-06-08
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #22**

2021-05-14 08:42

MOT test number

847426524318

Result**✗ Failed****Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #21**

2020-06-09 18:34

MOT test number

928088935194

Result**✓ Passed****Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #20**

2018-06-14 14:16

MOT test number

365479004806

Result

✓ Passed

- Advice** Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement lower rear near side and off side (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear slight bind on rear brakes

MOT #19

2017-08-24 11:09

MOT test number

908871724882

Result

✓ Passed

- Advice** Minor score on the nearside rear brake disc
- Advice** Slight bind on the nearside rear brake
- Advice** Nearside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

MOT #18

2016-04-05 14:29

MOT test number

408904043756

Result

✓ Passed

MOT #17

2016-03-31 09:08

MOT test number

228547703202

Result

✗ Failed

- Fail** Offside Brake pipe excessively corroded front to rear (3.6.B.2c)
- Fail** Nearside Brake pipe excessively corroded front to rear (3.6.B.2c)



MOT #16	2014-07-03 17:02
MOT test number	146124284114
Result	✓ Passed

MOT #15	2014-03-04 14:55
MOT test number	128383864476
Result	✓ Passed

MOT #14	2013-03-28 15:28
MOT test number	719737283094
Result	✓ Passed
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Notice	Nearside front tyre worn on inner edge (205/55 R16 91Y)
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Notice	Oil leak
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #13**

2012-07-17 15:35

MOT test number

429529692127

Result

✓ Passed

- Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Notice** Brake warning light on
- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** Air bag light on
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Engine covers fitted obscuring some components in the engine bay

MOT #12

2012-07-16 17:26

MOT test number

717498192150

Result

✗ Failed

- Notice** Brake warning light on
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Notice** Air bag light on
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Fail** Offside Rear coil spring fractured (2.4.C.1a)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



MOT #11	2011-07-19 16:42
MOT test number	615120901269
Result	✓ Passed
Advice	Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #10	2011-07-19 12:17
MOT test number	885470601227
Result	✗ Failed
Fail	Rear brake juddering severely (3.7.A.5b)
Fail	Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Notice	Both rear brake discs rusted on in side
Advice	Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #9	2010-07-26 15:27
MOT test number	872237500224
Result	✓ Passed
Notice	Front brake discs worn
Advice	Offside rear brake juddering slightly (3.7.A.5b)
Notice	Rear brake dicsc rusted

**MOT #8** 2010-07-26 11:37**MOT test number** 290727400221**Result** ✗ Failed**Notice** Rear brake disc rusted**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Notice** Front brake discs worn**Advice** Offside rear brake juddering slightly (3.7.A.5b)**Fail** Centre Exhaust system not adequately supported (7.1.1)**MOT #7** 2009-11-11 14:22**MOT test number** 434345519404**Result** ✓ Passed**MOT #6** 2009-11-11 12:57**MOT test number** 562825419358**Result** ✗ Failed**Fail** Offside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2008-11-13 16:16**MOT test number** 471228918374**Result** ✓ Passed



MOT #4	2008-11-12 15:18
MOT test number	811217818357
Result	✗ Failed
Fail	Offside Front Macpherson strut has excessive movement in the upper support bearing assembly (2.5.B.1b)
MOT #3	2007-10-02 12:05
MOT test number	940135677200
Result	✓ Passed
MOT #2	2007-10-02 09:31
MOT test number	833525577285
Result	✗ Failed
Fail	Nearside Front Tyre not fitted in accordance with side wall instructions (4.1.D.1f)
Fail	Offside Front Tyre not fitted in accordance with side wall instructions (4.1.D.1f)
MOT #1	2006-09-04 10:19
MOT test number	943277646288
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
28 November 2021

✕
MOT

Expired:
8 June 2022

Tax status	Expired at 28 November 2021
Days left	883 days too late
MOT expiry date	8 June 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2020-01-01
Current registration	XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2003-09-30
Last registration	2021-05-17
Complete history	See info



Registration #1	2003-09-30	11 mi
Registration #2	2006-09-04	40.503 mi
Registration #3	2007-10-02	58.751 mi
Registration #4	2007-10-02	58.752 mi
Registration #5	2008-11-12	75.372 mi
Registration #6	2008-11-13	75.379 mi
Registration #7	2009-11-11	87.370 mi
Registration #8	2009-11-11	87.370 mi
Registration #9	2010-07-26	88.099 mi
Registration #10	2010-07-26	88.099 mi
Registration #11	2011-07-19	96.588 mi
Registration #12	2011-07-19	96.588 mi
Registration #13	2012-07-16	104.468 mi
Registration #14	2013-05-20	111.377 mi
Registration #15	2013-05-20	111.377 mi
Registration #16	2013-05-20	111.377 mi
Registration #17	2013-05-20	111.377 mi
Registration #18	2013-05-20	111.377 mi
Registration #19	2013-05-20	111.377 mi
Registration #20	2013-05-20	111.377 mi
Registration #21	2013-05-20	111.377 mi
Registration #22	2013-05-20	111.377 mi
Registration #23	2013-05-20	111.377 mi
Registration #24	2013-05-20	111.377 mi
Registration #25	2013-05-20	111.377 mi
Registration #26	2013-05-20	111.377 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1856 mm
Height	1348 mm
Length	4041 mm
Wheel base	2429 mm
Kerb weight	1335 kg
Max. allowed weight	1635 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2

Engine number

AUM 100083