

Ford



General information

| Make | FORD |
|---------------------|----------------|
| Model | C-MAX ZETEC |
| Colour | Blue |
| Year of manufacture | 2013 |
| Top speed | 112 mph |
| 0 - 100 km/h | 11.5 seconds |
| 0 - 60 mph | 12.6 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 92 kW / 125 HP / 104 BHP | |
|-------------------------|--------------------------|--|
| Max. torque | 159 Nm at 4.000 rpm | |
| Engine capacity | 1.596 cc | |
| Cylinders | 4 | |
| Fuel type | Petrol | |
| Consumption city | 33.6 mpg | |
| Consumption extra urban | 54.3 mpg | |
| Consumption combined | 44.1 mpg | |
| CO2 emission | 149 g/km | |
| CO2 label | F | |







| 2021-10-24 |
|--------------------|
| 0 |
| View report |
| |
| |
| 2021-10-23 |
| 1 |
| <u>View report</u> |
| |





source: autotrader.co.uk



MOT history

| MOT expiry date | 2024-10-29 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 8 |
| Failed MOT tests | 0 |
| Total advice items | 10 |
| Total items failed | 0 |

| MOT #8 | 2023-10-27 08:01 |
|------------------|------------------|
| MOT test number | 549889789276 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-29 |

| MOT #7 | 2022-10-18 10:41 |
|-----------------|------------------|
| MOT test number | 882809121869 |
| Result | ✓ Passed |

| МОТ #6 | 2021-10-21 15:15 |
|-----------------|------------------|
| MOT test number | 338141892719 |
| Result | ✓ Passed |

| MOT #5 | 2020-10-05 10:25 |
|--|------------------|
| MOT test number | 806256575316 |
| Result | ✓ Passed |
| Advice Offside Front Tyre worn close to legal limit/worn on edge 2.8mm (5.2.3 (e | e)) |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge 2.8mm (5.2.3 | (e)) |





| MOT #4 | | 2019-04-08 13:35 |
|-----------------------|---|----------------------|
| MOT test | number | 816682269985 |
| Result | | ✓ Passed |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice | Nearside Front Brake lining(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice retainer st | Nearside Front Outer Nearside front outer CV gaiter has slight grease marks o ill secure | on driveshaft . Clip |
| | | |

| MOT #3 | 2018-04-12 09:27 |
|--|------------------|
| MOT test number | 949539127852 |
| Result | ✓ Passed |
| Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1) | |

| МОТ #2 | 2017-04-26 09:37 |
|-----------------|------------------|
| MOT test number | 740334692356 |
| Result | ✓ Passed |

| MOT #1 | | 2016-04-29 11:11 |
|----------|---|------------------|
| MOT test | number | 592485170003 |
| Result | | ✓ Passed |
| Advice | Nearside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Under tray fitted | |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) | |



Tax & MOT check

| ✓ Taxed Tax due: 1 November 2024 | ✓ MOT Expires: 29 October 2024 |
|---|---|
| Tax status | Valid until 1 November |
| Days left | 186 |
| MOT expiry date | 29 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | F |
| Single payment (12 months) | £ 200,00,- |
| Single six month payment | £ 110,00,- |
| Total payable by 12 monthly instalments | £ 210,00,- |





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-------------|
| Date | FER I |
| Category | A PLANE |
| Туре | |
| Damage 2 | AMPLE |
| Damage 2 | E Stand |
| Date | * |
| Category | ante. |
| Туре | |

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| *********** | |
| ******* | |
| ******* | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this FORD had different number plates. | |
| Number of plates | 7 |
| Carrent registration | |
| Plate since | |
| Carrent registration | |
| Plate since | |
| | |





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 11 |
| First mileage registration | 2013-04-30 |
| Last registration | 2023-10-27 |
| Complete history | <u>See info</u> |



| Registration #1 | 2013-04-30 | 15 mi |
|------------------------------------|------------|--|
| Registration #2 | 2016-04-29 | 21.184 mi |
| Registration #3 | 2017-04-26 | 28.234 mi |
| Registration #4 | 2018-04-12 | 35.054 mi |
| Registration #5 | 2019-04-08 | 42.262 mi |
| Registration #6 | 2020-10-05 | 48.452 mi |
| | | |
| Registration #7 | | |
| Registration #7 Registration #8 | | 11.000 est |
| - | | 0.000 es |
| Registration #8 | | 0.000 est 0.000 est 0.000 est 0.000 est |





Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| S0482 | |
| \$0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 92% |
| Children | 83% |
| Pedestrian | 50% |
| Safety systems | 71% |
| Overall rating | 80% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|-----------------------|
| Width | 2067 mm |
| Height | 1626 mm |
| Length | 4380 mm |
| Wheel base | 2850 mm |
| Kerb weight | 1274 kg |
| Max. allowed weight | 1860 kg |
| Additional information | |
| Fuel tank capacity | 55 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of axles CarCheck.co.uk | 2 page 11/11 |