



report date: 2024-03-29

General information

Make	SUZUKI
Model	SPLASH GLS PLUS
Colour	Red
Year of manufacture	2009
Top speed	109 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	86 BHP
Max. torque	114 Nm at 4.400 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	50.4 mpg
CO2 emission	131 g/km
CO2 label	E







Internet history

Entry 1

Date	2021-06-04
Pictures	24
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-10-28
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	5
Total items failed	8

MOT #16	2023-10-26 10:19
MOT test number	888643224757
Result	✓ Passed
Next expiry date	2024-10-28
Minor	Offside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #15	2022-10-29 06:32
MOT test number	785963046318
Result	✓ Passed

MOT #14	2022-06-03 14:54
MOT test number	558763664983
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #13** 2022-06-01 16:31**MOT test number** 458721422816**Result** ✗ Failed**Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Offside Front Upper Suspension component pin or bush excessively worn Top shock absorber mounting (5.3.4 (a) (i))**MOT #12** 2021-06-04 10:33**MOT test number** 559085225421**Result** ✓ Passed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #11** 2020-06-15 14:53**MOT test number** 382520354808**Result** ✓ Passed**MOT #10** 2019-07-27 08:45**MOT test number** 390315101203**Result** ✓ Passed**MOT #9** 2018-07-14 09:48**MOT test number** 120250616447**Result** ✓ Passed

**MOT #8** 2017-07-25 11:13**MOT test number** 209876946111**Result** ✓ Passed**MOT #7** 2017-07-24 08:24**MOT test number** 744779340205**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**Fail** Offside Front Brake pipe excessively corroded (3.6.B.2c)**Fail** Nearside Front Macpherson strut has excessive movement at the upper attachment (2.5.A.1c)**MOT #6** 2016-07-16 08:31**MOT test number** 940259121043**Result** ✓ Passed**MOT #5** 2015-07-18 09:42**MOT test number** 907439295183**Result** ✓ Passed**MOT #4** 2014-07-15 15:42**MOT test number** 235616194476**Result** ✓ Passed**MOT #3** 2013-08-13 15:03**MOT test number** 856695623293**Result** ✓ Passed**MOT #2** 2013-03-07 14:58**MOT test number** 336556063003**Result** ✓ Passed



MOT #1	2012-03-23 15:50
MOT test number	817613982016
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
28 October 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	28 October 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	YX09PVW
Plate since	2019-03-29
Current registration	YX09PVW
Plate since	2019-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-03-20
Last registration	2023-10-26
Complete history	<a href="#">See info</a>



Registration #1	2009-03-20	22 mi
Registration #2	2012-03-23	17.382 mi
Registration #3	2013-03-07	25.382 mi
Registration #4	2013-08-13	28.196 mi
Registration #5	2014-07-15	30.777 mi
Registration #6	2015-07-18	33.205 mi
Registration #7	2016-07-16	35.538 mi
Registration #8	2017-07-24	40.103 mi
Registration #9	2017-07-25	40.143 mi
Registration #10	2018-05-20	45.277 mi
Registration #11	2019-05-20	50.277 mi
Registration #12	2020-05-20	55.277 mi
Registration #13	2021-05-20	60.277 mi
Registration #14	2022-05-20	65.277 mi
Registration #15	2023-05-20	70.277 mi
Registration #16	2024-05-20	75.277 mi
Registration #17	2025-05-20	80.277 mi
Registration #18	2026-05-20	85.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1680 mm
Height	1590 mm
Length	3715 mm
Wheel base	2360 mm
Kerb weight	1065 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	K12B-1045882