



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	AVENSIS D-4D T3X
Colour	Silver
Year of manufacture	2007
Top speed	130 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	310 Nm at 3.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	156 g/km
CO2 label	G





MOT history

MOT expiry date	2021-07-10
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	25
Total items failed	21

MOT #18 2020-07-11 09:52

MOT test number 176632981601

Result ✓ Passed

Next expiry date 2021-07-10

Advice Offside Rear Brake pipe corroded, covered in grease or other material and nearside rear (1.1.11 (c))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #17 2019-12-19 09:57

MOT test number 557200527647

Result ✓ Passed

Advice Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #16 2018-11-27 10:08

MOT test number 491500239735

Result ✓ Passed

**MOT #15** 2017-12-04 10:22**MOT test number** 224127487311**Result** ✓ Passed**MOT #14** 2016-12-12 12:04**MOT test number** 630649053734**Result** ✓ Passed**MOT #13** 2016-12-09 12:07**MOT test number** 530069115550**Result** ✗ Failed

- Fail** Nearside Rear coil spring broken (2.4.C.1a)
- Fail** Offside Rear Anti-roll bar has excessive play in a pin/bush (2.4.G.2)
- Fail** Offside Rear Stop lamp not working (1.2.1b)
- Fail** Nearside Rear Anti-roll bar has excessive play in a pin/bush (2.4.G.2)
- Fail** Nearside Side repeater not working (1.4.A.2c)

MOT #12 2016-06-22 08:31**MOT test number** 714074456486**Result** ✓ Passed**MOT #11** 2016-05-12 15:49**MOT test number** 550308160338**Result** ✓ Passed

**MOT #10**

2016-05-11 15:15

MOT test number

633869839089

Result**✗ Failed**

- Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Front Suspension arm fractured (2.4.G.1)
- Fail** Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)
- Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside Side repeater not working in mirror (1.4.A.2c)
- Fail** Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)
- Fail** Nearside Front Power steering component(s) leaking rack gaitor leaking (2.3.3b)
- Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)

MOT #9

2015-05-06 16:04

MOT test number

746796625138

Result**✓ Passed**

- Notice** Advise osf tyre has cut

MOT #8

2015-05-06 16:04

MOT test number

337446925175

Result**✗ Failed**

- Pass with rectification** Nearside Front Headlamp aim too low (1.8)
- Notice** Advise osf tyre has cut
- Pass with rectification** Offside Front Headlamp aim too low (1.8)

**MOT #7**

2014-08-28 11:47

MOT test number

389250544240

Result

✓ Passed

Advice Power steering component(s) has slight seepage from a component (2.3.3b)**Notice** Under-trays fitted obscuring some underside components**Notice** Rear bumper insecure**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #6**

2014-08-27 11:58

MOT test number

986999834276

Result

✗ Failed

Notice Engine covers fitted obscuring some components in the engine bay**Fail** Power steering malfunctioning (2.3.3a)**Notice** Nail in offside rear tyre**Notice** Under-trays fitted obscuring some underside components**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Power steering component(s) has slight seepage from a component (2.3.3b)**Notice** Rear bumper insecure**MOT #5**

2013-08-19 15:51

MOT test number

535931833288

Result

✓ Passed

Notice Under-trays fitted obscuring some underside components**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Offside front tyre has cut on inner sidewall.**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #4** 2013-08-19 12:30**MOT test number** 129431833286**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Under-trays fitted obscuring some underside components**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Notice** Offside front tyre has cut on inner sidewall.**MOT #3** 2012-08-07 10:25**MOT test number** 328060622294**Result** ✓ Passed**MOT #2** 2011-09-05 10:21**MOT test number** 507008041294**Result** ✓ Passed**MOT #1** 2010-07-24 11:38**MOT test number** 600975000234**Result** ✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
1 December 2020

✕
MOT

Expired:
10 July 2021

Tax status

Expired at 1 December 2020

Days left

1245 days too late

MOT expiry date

10 July 2021

Full MOT history

[See MOT history](#)

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-07-27
Last registration	2020-07-11
Complete history	See info



Registration #1	2007-07-27	15 mi
Registration #2	2010-07-24	73.894 mi
Registration #3	2011-09-05	80.958 mi
Registration #4	2012-08-07	86.757 mi
Registration #5	2013-08-19	95.791 mi
Registration #6	2013-08-19	95.791 mi
Registration #7	2014-08-27	105.425 mi
Registration #8	2014-08-28	105.425 mi
Registration #9	2015-05-06	111.618 mi
Registration #10	2015-05-06	111.618 mi
Registration #11	2015-05-06	111.618 mi
Registration #12	2015-05-06	111.618 mi
Registration #13	2015-05-06	111.618 mi
Registration #14	2015-05-06	111.618 mi
Registration #15	2015-05-06	111.618 mi
Registration #16	2015-05-06	111.618 mi
Registration #17	2015-05-06	111.618 mi
Registration #18	2015-05-06	111.618 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1760 mm
Height	1480 mm
Length	4630 mm
Wheel base	2700 mm
Kerb weight	1455 kg
Max. allowed weight	1970 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4415177540