



RENAULT

CF54FGD

report date: 2024-03-29

General information

Make	RENAULT
Model	TRAFIC LL29DCI 140 LWB L/C P/V
Colour	Green
Year of manufacture	2005
Top speed	106 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	133 BHP
Max. torque	310 Nm at 1.750 rpm
Engine capacity	2.464 cc
Cylinders	4
Fuel type	Diesel





MOT history

MOT expiry date	2023-01-24
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	38
Total items failed	7

MOT #20	2022-01-25 11:03
MOT test number	132620434661
Result	✓ Passed
Next expiry date	2023-01-24
Minor	Offside Front Position lamp light intensity obviously reduced (4.2.3 (a) (i))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #19	2020-12-31 16:19
MOT test number	350104405350
Result	✓ Passed

MOT #18	2020-01-09 11:23
MOT test number	514289924213
Result	✓ Passed
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Front Shock absorbers has slight external damage to the casing Corroded (5.3.2 (b))
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Front Shock absorbers has slight external damage to the casing Corroded (5.3.2 (b))

**MOT #17**

2020-01-08 08:52

MOT test number

602218744435

Result**✗ Failed**

- MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Nearside Front Shock absorbers has slight external damage to the casing Corroded (5.3.2 (b))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Offside Front Shock absorbers has slight external damage to the casing Corroded (5.3.2 (b))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #16

2019-01-15 14:51

MOT test number

854505829929

Result**✓ Passed****MOT #15**

2019-01-15 09:37

MOT test number

657436439094

Result**✗ Failed**

- MAJOR** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #14

2018-01-23 16:37

MOT test number

635269176500

Result**✓ Passed**

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #13**

2018-01-18 08:42

MOT test number

181527490782

Result**✗ Failed**

- Advice** Offside rear brake fluctuating, but not excessively (3.7.B.3)
- Fail** Offside Rear coil spring broken (2.4.C.1a)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Brake pad(s) wearing thin very close (3.5.1g)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Nearside Stop lamp not working (1.2.1b)
- Advice** Slight bind o/s/f wheel
- Fail** Nearside Rear coil spring broken (2.4.C.1a)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)

MOT #12

2017-01-20 09:25

MOT test number

555590877966

Result**✓ Passed**

- Advice** Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #11

2017-01-18 08:37

MOT test number

916866978558

Result**✗ Failed**

- Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)
- Advice** Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #10** 2016-01-08 12:23**MOT test number** 449189059609**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)**MOT #9** 2015-01-15 11:31**MOT test number** 366245815039**Result** ✓ Passed**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)**MOT #8** 2014-01-17 13:00**MOT test number** 177837414455**Result** ✓ Passed**Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**MOT #7** 2013-01-10 09:07**MOT test number** 396070813078**Result** ✓ Passed**Notice** Slight bind on both rear wheels**Advice** Offside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**MOT #6** 2012-01-04 13:59**MOT test number** 267774402016**Result** ✓ Passed**Notice** O/s/front wiper blade slightly deteriared

**MOT #5** 2012-01-04 13:59**MOT test number** 886974902054**Result** ✗ Failed**Notice** O/s/front wiper blade slightly deteriared**Pass with rectification** Offside Front Front constant velocity joint is insecure (2.5.C.1b)**MOT #4** 2011-01-11 11:42**MOT test number** 519941011094**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Advice** Offside Rear wheel bearing has slight play (2.6.2)**MOT #3** 2010-01-11 13:03**MOT test number** 173341510472**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear wheel bearing has slight play (2.6.2)**MOT #2** 2009-01-05 13:39**MOT test number** 931535709097**Result** ✓ Passed**MOT #1** 2008-01-09 12:39**MOT test number** 902899408003**Result** ✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-01-04
Last registration	2022-01-25
Complete history	See info



Registration #1	2005-01-04	17 mi
Registration #2	2008-01-09	29.937 mi
Registration #3	2009-01-05	39.867 mi
Registration #4	2010-01-11	49.887 mi
Registration #5	2011-01-11	58.522 mi
Registration #6	2012-01-04	64.942 mi
Registration #7	2013-01-10	70.598 mi
Registration #8	2014-01-17	75.209 mi
Registration #9	2015-01-15	79.966 mi
Registration #10	2016-01-08	86.055 mi
Registration #11	2016-01-08	86.055 mi
Registration #12	2016-01-08	86.055 mi
Registration #13	2016-01-08	86.055 mi
Registration #14	2016-01-08	86.055 mi
Registration #15	2016-01-08	86.055 mi
Registration #16	2016-01-08	86.055 mi
Registration #17	2016-01-08	86.055 mi
Registration #18	2016-01-08	86.055 mi
Registration #19	2016-01-08	86.055 mi
Registration #20	2016-01-08	86.055 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2232 mm
Height	1985 mm
Length	5182 mm
Kerb weight	1794 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	C041159