





report date: 2024-03-29

General information

Make	FIAT
Model	PANDA ACTIVE
Colour	Blue
Year of manufacture	2012
Top speed	101 mph
0 - 60 mph	13.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.1 mpg
Consumption extra urban	70.6 mpg
Consumption combined	57.7 mpg
CO2 emission	113 g/km
CO2 label	С



CarCheck.co.uk page 1/13



GK120TG

report date: 2024-03-29

Internet history

Entry 1

Date 2021-02-05

Pictures 4

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-07-05
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	19
Total items failed	8

MOT #13		2023-07-06 14:50
MOT test	number	207532660085
Result		✓ Passed
Next expi	ry date	2024-07-05
Advice	Rear Coil spring corroded both (5.3.1 (b) (i))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #12		2023-07-06 10:57
MOT test	number	259452107810
Result		X Failed
Advice	Rear Coil spring corroded both (5.3.1 (b) (i))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
MAJOR	Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))	
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #11

MOT test number

S88960450571

Result

Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

 MOT #10
 2021-08-16 10:47

 MOT test number
 248687870862

 Result
 ✓ Passed

 MOT #9
 2020-02-24 12:31

 MOT test number
 925718095796

 Result
 ✓ Passed

MOT #8 2019-03-15 09:48

MOT test number 143946964895

Result \rightarrow Passed

Advice Front brake calipers , pins worn and pad carriers also has wear. Calipers rattling.

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Exhaust system corroded.

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #7 2018-03-23 12:20

MOT test number 195223516550

Result ✓ Passed

Advice Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

CarCheck.co.uk page 4/13



MOT #6 2018-03-23 12:20

MOT test number 759931606464

Result X Failed

Pass with rectification Nearside Rear Upper Shock absorber has an excessively worn bush (2.7.4)

Pass with rectification Nearside Rear Outer Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Pass with rectification Offside Rear Upper Shock absorber has an excessively worn bush (2.7.4)

Advice Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #5 2017-04-04 14:16

MOT test number 793485642572

Result

Passed

Advice Exhaust rear silencer corroded.

MOT #4 2017-04-04 14:16

MOT test number 147174118288

Result × Failed

Pass with rectification Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Exhaust rear silencer corroded.

Pass with rectification Offside Front Suspension arm rubber mounting deteriorated resulting in excessive movement (2.4.G.2)

Pass with rectification Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Pass with rectification Nearside Front Suspension arm rubber mounting deteriorated resulting in

excessive movement (2.4.G.2)

MOT #3 2016-03-03 10:55

MOT test number 637710957407

CarCheck.co.uk page 5/13



MOT #2 2016-03-03 10:55

MOT test number 413843428865

Result × Failed

Pass with rectification Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #1 2015-03-13 12:50

MOT test number 147992675022

Result \(\sqrt{Passed} \)

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	5 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report		e?

	More info	>
Plate changes		
See in this check if this FIAT had different number plates.		
Number of plates		,
Current registration	UK NE	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-03-31
Last registration	2023-07-06
Complete history	See info



Registration #1	2012-03-31	7 mi
Registration #2	2015-03-13	13.912 mi
Registration #3	2016-03-03	20.570 mi
Registration #4	2016-03-03	20.570 mi
Registration #5	2017-04-04	24.089 mi
Registration #6	2017-04-04	24.089 mi
Registration #7	2018-03-23	27.421 mi
Registration #8	2018-03-23	27.421 mi
Registration #9		9.77 es
Registration #10		11.777 es
Registration #11		9.77 m
Registration #12		11.777 es
Registration #13		9.377 es
Registration #14		0.00 44
Registration #15		11,177 mi

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1578 mm
Height	1540 mm
Length	3538 mm
Wheel base	2299 mm
Kerb weight	860 kg
Max. allowed weight	1305 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	4 page 13/1

Number of axles 2

Engine number 6492127