






report date: 2024-03-29

General information

Make	RENAULT
Model	TRAFIC
Colour	White
Year of manufacture	-
Gearbox	-

Engine & fuel consumption

Fuel type Diesel



CarCheck.co.uk page 1/15



report date: 2024-03-29

MOT history

Advice

MOT test number

Result

Next expiry date

Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice

Offside Front Inner Steering rack has slight free play detected at steering wheel rack joint (2.3 (a) (i))

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT test number

263406089831

Result

X Failed

Fail Nearside Front Brake pipe excessively corroded (1.1.11 (c))

Advice Offside Front Inner Steering rack has slight free play detected at steering wheel rack joint (2.3 (a) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #23

MOT test number

Result

2019-11-01 15:28

134333241978

✓ Passed

MOT #22 2019-10-25 15:44 **MOT** test number 463589549023 Result × Failed Fail Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii)) Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) Fail Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) **Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i)) Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Fail

CarCheck.co.uk page 2/15



report date: 2024-03-29

MOT #21		2018-09-05 15:02
MOT test	number	156740288876
Result		✓ Passed
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #20		2017-09-20 10:56
MOT test	number	619839573865
Result		✓ Passed
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.	1i)
Advice	Nearside Rear Panhard rod corroded but not seriously weakened (2.4.G.1)	
Advice	Nearside Front low tread on outer edge	
Advice	Offside Headlamp has a product on the lens but not seriously reducing light output	ıt (1.7.5a)
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Offside Rear Panhard rod corroded but not seriously weakened (2.4.G.1)	

CarCheck.co.uk page 3/15



report date: 2024-03-29

MOT #19 2017-09-18 13:36

MOT test number 249529354025

Result X Failed

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Rear Panhard rod corroded but not seriously weakened (2.4.G.1)

Fail Nearside Track rod end ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.2.C.1c)

Advice Offside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Rear Panhard rod corroded but not seriously weakened (2.4.G.1)

Fail Rear Brake pipe inadequately clipped across vehicle (3.6.B.1)

Advice Nearside Front low tread on outer edge

Fail Offside Track rod end ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.2.C.1c)

Advice Brake valve corroded but not excessively weakened (3.6.A.2b)

MOT #18 2016-08-03 12:16

MOT test number 910857625768

Result

Passed

Advice Nearside Front Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)

MOT #17 2015-07-10 11:57

MOT test number 969691195180

CarCheck.co.uk page 4/15



report date: 2024-03-29

MOT #16 2015-07-09 14:21 815890995167 **MOT** test number Result × Failed Fail Offside Rear position lamp(s) not working (1.1.A.3b) Fail Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2) Fail Windscreen washer provides insufficient washer liquid (8.2.3) Fail Nearside Front position lamp(s) not working (1.1.A.3b) Fail Rear fog lamp not working (1.3.2b) Fail Offside Rear Brake pipe excessively corroded (3.6.B.2c) Registration plate lamp not working (1.1.C.1d) Fail

MOT #15

MOT test number

Passed

Notice Windscreen damaged at lower edge out of drivers view

CarCheck.co.uk page 5/15



report date: 2024-03-29

MOT #14 2014-08-28 17:22 798800044268 **MOT** test number Result **★** Failed Fail Offside Rear fog lamp insecure (1.3.2a) Fail Offside Track rod end ball joint has excessive play (2.2.B.1f) Notice Windscreen damaged at lower edge out of drivers view Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.C.1b) Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2) Fail Offside Rear fog lamp emits a light other than red (1.3.2e) Fail Emissions not tested (7.4.B.1) Fail Offside Rear coil spring broken (2.4.C.1a) Oil leak **Notice** Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #13	2013-09-05 16:10
MOT test number	797058043250
Result	✓ Passed
MOT #12	2013-09-04 14:44
MOT test number	238267843289
Result	≍ Failed
Fail Nearside Rear wheel bearing rough when rotated (2.6.1)	
Fail Nearside Front position lamp(s) not working (1.1.A.3b)	

CarCheck.co.uk page 6/15



report date: 2024-03-29

× Failed

 MOT #11
 2012-09-14 12:40

 MOT test number
 538088252270

Result ✓ Passed

Advice

Result

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #10 2012-09-12 08:45

MOT test number 925816452266

Fail Nearside Stop lamp not working (1.2.1b)

Advice Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

Fail Offside Front position lamp(s) not working (1.1.A.3b)

Advice Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #9 2011-09-12 20:35

MOT test number 655605051270

MOT #8 2011-09-12 20:35

MOT test number 607505251274

Result X Failed

Pass with rectification Nearside Front Shock absorber has a serious fluid leak (2.7.3)

Pass with rectification Offside Front Front suspension has excessive play in a lower suspension ball

joint (2.5.B.1a)

Pass with rectification Nearside Front Front suspension has excessive play in a lower suspension ball

joint (2.5.B.1a)

MOT #7 2010-08-16 10:21

MOT test number 980308920209

Result ✓ Passed

CarCheck.co.uk page 7/15



report date: 2024-03-29

MOT #6

MOT test number

Result

Advice Nearside Inner Track rod end ball joint has slight play (2.2.B.1f)

MOT test number

Result

Advice Offside Inner Track rod end ball joint has slight play (2.2.B.1f)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Inner Track rod end ball joint has slight play (2.2.B.1f)

Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #4 2008-09-08 11:47 **MOT** test number 834452658245 Result Failed **Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Nearside Inner Track rod end ball joint has slight play (2.2.B.1f) **Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a) Fail Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a) **Advice** Offside Inner Track rod end ball joint has slight play (2.2.B.1f)

MOT #3

MOT test number

Result

Advice Offside Inner Ball joint has slight play (2.2.B.1f)

Advice Nearside Inner Ball joint has slight play (2.2.B.1f)

CarCheck.co.uk page 8/15



report date: 2024-03-29

MOT #2 2006-08-31 15:50 **MOT test number** 962303646214 Result ✓ Passed 2006-08-29 14:20 MOT #1 **MOT test number** 990891246239 × Failed Result **Advice** Nearside Track rod end ball joint has slight play (2.2.B.1f) Notice Front tyre tread down to 3mm in places Fail Offside Track rod end ball joint has excessive play (2.2.B.1f)

CarCheck.co.uk page 9/15



report date: 2024-03-29

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-29

More info >

Owner history For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this RENAULT had different number plates. about of pliates faste since

CarCheck.co.uk page 12/15



report date: 2024-03-29

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >


CarCheck.co.uk page 13/15



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2003-09-11
Last registration	2020-10-28
Complete history	See info



Registration #1	2003-09-11	27 mi
Registration #2	2006-08-29	59.319 mi
Registration #3	2006-08-31	59.331 mi
Registration #4	2007-09-10	70.838 mi
Registration #5	2008-09-08	76.438 mi
Registration #6	2008-09-10	76.438 mi
Registration #7	2009-09-08	84.334 mi
Registration #8	2010-08-16	91.103 mi
Registration #9	2011-09-12	96.021 mi
Registration #10	2012-09-12	103.652 mi
Registration #11	2012-09-14	103.652 mi
Registration #12	2013-09-04	116.041 mi
Registration #13	2013-09-05	116.045 mi
Registration #14		11.177 es
Registration #15		11.777 es
Registration #16		11.177 es
Registration #17		11.777 es
Registration #18		11.177 es
Registration #19		11.777 es
Registration #20		11.777 ea
Registration #21		11.777 ea
Registration #22		11.777 66
Registration #23		11.777 mi
Registration #24		11.777 ea
Registration #25		9.77 sc



GU53EAW report date: 2024-03-29

Car features

S0225	Air conditioning
50295	
50482	
50501	
60566	
60567	
50569	

Additional information

CarCheck.co.uk page 15/15