



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T26 SWB P/V 85TDI
Colour	White
Year of manufacture	2008
Top speed	91 mph
0 - 60 mph	23.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	84 BHP
Max. torque	200 Nm at 2.000 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.1 mpg
Consumption extra urban	39.2 mpg
Consumption combined	35.3 mpg



LABEL UNKNOWN



MOT history

MOT expiry date	2023-04-12
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	4
Total items failed	5

MOT #13	2022-04-13 14:48
MOT test number	596331746987
Result	✓ Passed
Next expiry date	2023-04-12

MOT #12	2021-03-13 12:47
MOT test number	939558377468
Result	✓ Passed

MOT #11	2019-05-15 11:37
MOT test number	223702050317
Result	✓ Passed

Advice Offside Rear brake slight bind

MOT #10	2018-05-15 08:44
MOT test number	182324129149
Result	✓ Passed

Advice Offside Front Inner Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

**MOT #9** 2017-05-19 14:03**MOT test number** 568412842299**Result** ✓ Passed**MOT #8** 2016-05-16 10:07**MOT test number** 320641556141**Result** ✓ Passed**MOT #7** 2015-05-16 11:52**MOT test number** 827646135107**Result** ✓ Passed**Advice** Rear Stop lamp damaged, but still visible from a reasonable distance (1.2.1d)**MOT #6** 2014-05-17 11:41**MOT test number** 276207934448**Result** ✓ Passed**MOT #5** 2014-05-17 11:41**MOT test number** 179277934157**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high (1.8)**MOT #4** 2013-06-18 16:45**MOT test number** 939379363127**Result** ✓ Passed**MOT #3** 2012-07-18 10:31**MOT test number** 959000202278**Result** ✓ Passed



MOT #2	2012-07-17 15:16
MOT test number	495369992194
Result	✗ Failed
Fail	Offside Rear Brake lining(s) less than 1.5 mm thick (3.5.1g)
Fail	Nearside Registration plate lamp not working (1.1.C.1d)
Fail	Nearside Rear Brake lining(s) less than 1.5 mm thick (3.5.1g)
Fail	Nearside Rear coil spring fractured (2.4.C.1a)

MOT #1	2011-07-12 15:22
MOT test number	749373491137
Result	✓ Passed



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2008-08-04
Last registration	2022-04-13
Complete history	See info



Registration #1	2008-08-04	16 mi
Registration #2	2011-07-12	69.763 mi
Registration #3	2012-07-17	90.653 mi
Registration #4	2012-07-18	90.653 mi
Registration #5	2013-06-18	92.533 mi
Registration #6	2014-05-17	105.526 mi
Registration #7	2015-05-16	123.855 mi
Registration #8	2016-05-20	131.277 mi
Registration #9	2017-05-20	131.277 mi
Registration #10	2018-05-20	131.277 mi
Registration #11	2019-05-20	131.277 mi
Registration #12	2020-05-20	131.277 mi
Registration #13	2022-04-13	131.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1904 mm
Height	1969 mm
Length	4890 mm
Kerb weight	1798 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3

Number of axles

2

Engine number

BRR 042121