





report date: 2024-03-29

### General information

Make	VOLKSWAGEN
Model	SCIROCCO TSI DSG
Colour	Black
Year of manufacture	2010
Top speed	135 mph
0 - 60 mph	8.0 seconds
Gearbox	7 speed Semi Auto

## Engine & fuel consumption

Power	160 BHP
Max. torque	240 Nm at 1.500 rpm
Engine capacity	1.390 сс
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.8 mpg
CO2 emission	147 g/km
CO2 label	F



CarCheck.co.uk page 1/12



**MJ10DXU** 

report date: 2024-03-29

### Internet history

### Entry 3


Date 2022-02-14

**Pictures** 13

Listing price View report









source: autotrader.co.uk

#### Entry 2

Date	2021-07-07
Pictures	3

View report

Listing price







source: cargurus.co.uk

#### Entry 1

Date	2021-07-06

3 **Pictures** 

Listing price View report







source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-10-26
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	18
Total items failed	1

MOT #12	2023-10-17 09:26
MOT test number	601024805299
Result	<b>✓</b> Passed
Next expiry date	2024-10-26

MOT #11	2022-10-27 12:41
MOT test number	251217597625
Result	✓ Passed
Minor Nearside Front Brake hose slightly twisted (1.1.12 (b) (i))	
Advice Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))	
Advice Offside Front Tyre worn close to legal limit/worn on edge inner edge slightly	worn (5.2.3 (e))
Minor Central Rear Stop lamp(s) with a multiple light source up to 1/2 not functioni	ng (4.3.1 (a) (i))
Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice Fuel cap seal cracked	
Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive arm bush (5.3.4 (a) (i))	e movement trailing
Minor Nearside Side repeater with a multiple light source up to 1/2 not functioning	(4.4.1 (a) (i))
Advice Both sides rear registration plate lamps dim	

CarCheck.co.uk page 3/12



**MOT #10** 2021-11-30 15:10

MOT test number 505065502334

Result \rightarrow Passed

Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #9** 2020-11-21 11:09

**MOT test number** 847540248424

MOT #8 2019-06-01 14:18

**MOT test number** 415956124810

Result \( \sqrt{Passed} \)

Advice Offside Rear Tyre worn close to legal limit/worn on edge Just legal (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Front Anti-roll bar linkage ball joint dust cover severely deteriorated Nearside + Offside (5.3.4 (b) (i))

Advice Rear Brake pad(s) wearing thin Nearside + Offside (1.1.13 (a) (ii))

MOT #7 2018-05-28 12:48

**MOT test number** 585930264679

Advice Rear Tyre worn close to legal limit/worn on edge Both tyres on 1.6mm limit (5.2.3 (e))

Minor Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #6 2017-05-27 10:07

MOT test number 311695345153

**Result** 
✓ Passed

CarCheck.co.uk page 4/12



Fail

MJ10DXU report date: 2024-03-29

 MOT #5
 2016-05-27 09:57

 MOT test number
 521698381067

 Result
 ✓ Passed

 MOT #4
 2015-05-28 13:45

 MOT test number
 619038145128

 Result
 ✓ Passed

 Notice
 N/s/f wiper blade split

MOT #3	2014-05-17 12:01
MOT test number	299407734146
Result	<b>✓</b> Passed
MOT #2	2014-05-17 11:22
MOT test number	446087534199
Result	<b>≍</b> Failed

MOT #1	2013-05-16 15:20
MOT test number	268976733182
Result	✓ Passed

Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

CarCheck.co.uk page 5/12



# Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	26 October 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12




### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



#### Extra VOLKSWAGEN salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



More info >

### Owner history

C Miles Miscory	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	
**************************************	
2000000	
***************************************	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	
Current registration	AIR WIE
Plate since	
Current registration	NK SIK
Plate since	

CarCheck.co.uk page 9/12



### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

 $\quad \text{More info} \quad > \quad$ 


CarCheck.co.uk page 10/12



Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-05-24
Last registration	2023-10-17
Complete history	See info



Registration #1	2010-05-24	12 mi
Registration #2	2013-05-16	28.100 mi
Registration #3	2014-05-17	39.610 mi
Registration #4	2014-05-17	39.610 mi
Registration #5	2015-05-28	51.876 mi
Registration #6	2016-05-27	57.712 mi
Registration #7	2017-05-27	67.555 mi
Registration #8	2018-05-28	78.359 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.177 es
Registration #15		11.777 es

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 11/12



### Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	87%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	76%
Video	see crash video



# Dimensions & weight

Width	1810 mm
Height	1404 mm
Length	4256 mm
Wheel base	2578 mm
Kerb weight	1318 kg
Max. allowed weight	1730 kg

# Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	2
CarChack so uk	nago 12/13

CarCheck.co.uk page 12/12

Number of seats	4
Number of axles	2
Engine number	CAV 164230