



General information

Make	VOLKSWAGEN
Model	POLO SE TDI
Colour	Grey
Year of manufacture	2011
Top speed	106 mph
0 - 60 mph	13.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	195 Nm at 1.500 rpm
Engine capacity	1.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	78.5 mpg
Consumption combined	67.3 mpg
CO2 emission	102 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-02-06
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history**

MOT expiry date	2024-05-20
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	10
Total items failed	1

MOT #11	2023-04-26 10:22
MOT test number	945996577168
Result	✓ Passed
Next expiry date	2024-05-20

MOT #10	2022-04-23 08:02
MOT test number	190832969270
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))

MOT #9	2022-04-23 08:02
MOT test number	141502688348
Result	✗ Failed
Pass with rectification	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))

MOT #8	2021-04-30 10:38
MOT test number	168357745459
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 1.6mm (5.2.3 (e))

**MOT #7** 2020-05-09 08:32**MOT test number** 825473839654**Result** ✓ Passed**MOT #6** 2019-05-21 09:16**MOT test number** 217815579939**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear exhaust silencer deteriorated**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #5** 2018-05-21 14:07**MOT test number** 977479608618**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge and bald on inner edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge and bald on inner edge (5.2.3 (e))**MOT #4** 2017-02-21 14:03**MOT test number** 856741276211**Result** ✓ Passed**MOT #3** 2015-12-17 13:29**MOT test number** 549408162032**Result** ✓ Passed**MOT #2** 2014-12-08 13:01**MOT test number** 107372744375**Result** ✓ Passed



MOT #1	2013-12-27 15:09
MOT test number	905331363386
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
20 May 2024

Tax status	Valid until 1 June
Days left	34
MOT expiry date	20 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 DE60YSU
Plate since	2019-06-29
Current registration	 DE60YSU
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2011-01-18
Last registration	2023-04-26
Complete history	See info



Registration #1	2011-01-18	26 mi
Registration #2	2013-12-27	22.944 mi
Registration #3	2014-12-08	33.602 mi
Registration #4	2015-12-17	38.225 mi
Registration #5	2017-02-21	51.981 mi
Registration #6	2018-05-21	61.785 mi
Registration #7	2019-05-21	69.281 mi
Registration #8	2020-05-21	75.277 mi
Registration #9	2021-05-21	81.273 mi
Registration #10	2022-05-21	87.269 mi
Registration #11	2023-04-26	93.265 mi
Registration #12		
Registration #13		

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1682 mm
Height	1485 mm
Length	3970 mm
Wheel base	2470 mm
Kerb weight	1157 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

CFW 104375