



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE LUNA 8V
Colour	Black
Year of manufacture	2008
Top speed	110 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	148 Nm at 3.800 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.9 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	185 g/km
CO2 label	I







Internet history

Entry 1

Date	2021-06-04
Pictures	43
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-27
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	17
Total items failed	17

MOT #19	2023-07-21 11:37
MOT test number	420583965190
Result	✓ Passed
Next expiry date	2024-07-27

MOT #18	2023-07-20 09:12
MOT test number	516486040707
Result	✗ Failed
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Fail	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #17	2022-07-28 14:10
MOT test number	908039781890
Result	✓ Passed

MOT #16	2021-07-05 13:00
MOT test number	181825421176
Result	✓ Passed

MOT #15	2020-07-23 15:48
MOT test number	369497629470
Result	✓ Passed



MOT #14	2019-07-18 08:30
MOT test number	374088092616
Result	✓ Passed
Advice	Nearside Front Play in steering rack inner joint(s)

MOT #13	2019-07-16 10:39
MOT test number	162024782598
Result	✗ Failed
Advice	Nearside Front Play in steering rack inner joint(s)
Fail	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Fail	Exhaust system insecure centrev exhaust sleeve (6.1.2 (a))

MOT #12	2018-07-18 11:39
MOT test number	389316633921
Result	✓ Passed
Minor	Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Advice	Exhaust has a minor leak of exhaust gases at jointing sleeve (6.1.2 (a))
Minor	Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #11	2017-07-25 15:18
MOT test number	295032475377
Result	✓ Passed
Advice	Nearside Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)
Advice	Central Exhaust has a minor leak of exhaust gases at joining sleeve (7.1.2)
Advice	Offside Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)

**MOT #10**

2017-07-25 08:51

MOT test number

661487330800

Result

✗ Failed

Fail Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Central Exhaust has a minor leak of exhaust gases at joining sleeve (7.1.2)**Advice** Offside Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)**Fail** Nearside Headlamp not working on main beam (1.7.5a)**Advice** Nearside Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)**Fail** Offside Front Suspension arm has excessive play in a pin/bush rear bush in arm (2.4.G.2)**MOT #9**

2016-07-12 09:57

MOT test number

253230064836

Result

✓ Passed

MOT #8

2015-07-24 14:41

MOT test number

106805505282

Result

✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7**

2014-05-27 16:04

MOT test number

519647844136

Result

✓ Passed

**MOT #6** 2014-05-24 14:41**MOT test number** 516614644179**Result** ✗ Failed**Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #5** 2013-06-10 16:35**MOT test number** 699671963145**Result** ✓ Passed**MOT #4** 2013-06-03 15:37**MOT test number** 379064753136**Result** ✗ Failed**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Fail** Nearside Headlamp not working on main beam (1.7.5a)**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**MOT #3** 2012-06-01 14:11**MOT test number** 428023552197**Result** ✓ Passed**MOT #2** 2011-06-03 15:16**MOT test number** 288654051401**Result** ✓ Passed



MOT #12011-05-21 11:41

MOT test number148711841148

ResultX Failed

- Fail

Offside Front Headlamp not working on dipped beam (1.7.5a)
- Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail

Front Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)
- Advice

Front Brake pad(s) wearing thin (3.5.1g)
- Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓

Taxed

Tax due:
1 August 2024

✓

MOT

Expires:
27 July 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	27 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-05-20
Last registration	2023-07-21
Complete history	See info



Registration #1	2008-05-20	12 mi
Registration #2	2011-05-21	29.764 mi
Registration #3	2011-06-03	30.224 mi
Registration #4	2012-06-01	35.951 mi
Registration #5	2013-06-03	51.934 mi
Registration #6	2013-06-10	52.014 mi
Registration #7	2014-05-24	58.510 mi
Registration #8	2014-05-27	58.515 mi
Registration #9	2015-07-24	62.384 mi
Registration #10	2016-07-12	67.745 mi
Registration #11	2017-07-25	71.842 mi
Registration #12	2018-05-20	75.277 mi
Registration #13	2018-05-20	75.277 mi
Registration #14	2018-05-20	75.277 mi
Registration #15	2018-05-20	75.277 mi
Registration #16	2018-05-20	75.277 mi
Registration #17	2018-05-20	75.277 mi
Registration #18	2018-05-20	75.277 mi
Registration #19	2018-05-20	75.277 mi
Registration #20	2018-05-20	75.277 mi
Registration #21	2018-05-20	75.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1721 mm
Height	1502 mm
Length	4129 mm
Wheel base	2516 mm
Max. allowed weight	1770 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Engine number

BFS 071176