



General information

Make	VOLKSWAGEN
Model	PASSAT HIGHLINE TDI
Colour	Black
Year of manufacture	2009
Top speed	128 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	148 g/km
CO2 label	F



**MOT history**

MOT expiry date	2024-08-05
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	24
Total items failed	4

MOT #15	2023-08-03 09:53
MOT test number	907685590353
Result	✓ Passed
Next expiry date	2024-08-05

MOT #14	2022-07-12 14:31
MOT test number	584249574060
Result	✓ Passed

MOT #13	2021-07-28 09:18
MOT test number	907679641454
Result	✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Exhaust system corroded
- Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #12	2020-07-17 07:33
MOT test number	337357123505
Result	✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11** 2019-08-06 16:08**MOT test number** 251733693175**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**MOT #10** 2018-07-25 09:09**MOT test number** 842000452054**Result** ✓ Passed**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Minor** Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))**MOT #9** 2017-07-10 16:11**MOT test number** 658319635053**Result** ✓ Passed**MOT #8** 2017-07-10 11:27**MOT test number** 476267735438**Result** ✗ Failed**Fail** Offside Rear coil spring broken (2.4.C.1a)**Advice** Rust lip rear discs**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2016-07-07 09:32**MOT test number** 496152380619**Result** ✓ Passed**Advice** Rust lip rear discs**Advice** Dpf fitted

**MOT #6** 2016-07-06 09:27**MOT test number** 660442468945**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Nearside rear tyre starting to perish in tread**Advice** Rust lip rear discs**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside rear tyre worn on inner edge**Advice** Dpf fitted**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2015-06-20 09:06**MOT test number** 285071175464**Result** ✓ Passed**Advice** Nearside Front Upper Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**MOT #4** 2014-07-10 08:11**MOT test number** 155901594146**Result** ✓ Passed**MOT #3** 2013-06-18 16:32**MOT test number** 739519563178**Result** ✓ Passed**Notice** Front tyres starting to perrish**Notice** Front tyres worn on edge



MOT #2	2013-06-18 10:33
MOT test number	115489163156
Result	✗ Failed
<div><div>Notice</div>Front tyres worn on edge</div> <div><div>Notice</div>Front tyres starting to perrish</div> <div><div>Fail</div>Offside Side repeater excessively deteriorated so that it is not visible from a reasonable distance (1.4.A.2e)</div>	

MOT #1	2012-06-22 15:20
MOT test number	249264572478
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
5 August 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	5 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	RJ09AHK
Plate since	2019-03-29
Current registration	RJ09AHK
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-07-13
Last registration	2023-08-03
Complete history	See info



Registration #1	2009-07-13	12 mi
Registration #2	2012-06-22	29.144 mi
Registration #3	2013-06-18	39.304 mi
Registration #4	2013-06-18	39.304 mi
Registration #5	2014-07-10	49.156 mi
Registration #6	2015-06-20	58.944 mi
Registration #7	2016-07-06	68.025 mi
Registration #8	2016-07-07	68.025 mi
Registration #9	2016-07-07	68.025 mi
Registration #10	2016-07-07	68.025 mi
Registration #11	2016-07-07	68.025 mi
Registration #12	2016-07-07	68.025 mi
Registration #13	2016-07-07	68.025 mi
Registration #14	2016-07-07	68.025 mi
Registration #15	2016-07-07	68.025 mi
Registration #16	2016-07-07	68.025 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1517 mm
Length	4774 mm
Wheel base	2709 mm
Kerb weight	1510 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CBA 174034