



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	PREVIA GS
Colour	Green
Year of manufacture	1996
Top speed	111 mph
0 - 60 mph	11.3 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	135 BHP
Max. torque	204 Nm at 4.000 rpm
Engine capacity	2.438 cc
Cylinders	4
Fuel type	Petrol
Consumption city	16.6 mpg
Consumption extra urban	27.4 mpg
Consumption combined	22.1 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-29
Pictures	4
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2021-10-13
MOT pass rate	68 %
MOT passed	15
Failed MOT tests	7
Total advice items	58
Total items failed	12

MOT #222020-10-06 12:10

MOT test number252269246859

Result✓ Passed

Next expiry date2021-10-13

- Advice** Front Coil spring corroded (5.3.1 (b) (i))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources 50% working (4.7.1 (b) (i))
- Advice** Exhaust emits blue smoke during acceleration (8.2.1.2 (g))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Drive shaft damaged but serviceable (6.1.7 (e))
- Advice** Rear Coil spring corroded (5.3.1 (b) (i))
- Minor** Offside Steering box leaking oil (2.1.1 (e) (i))



MOT #21

2020-10-06 12:03

MOT test number

938384491465

Result

✗ Failed

- Advice

Offside Front Drive shaft damaged but serviceable (6.1.7 (e))
- Fail

Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice

Rear Coil spring corroded (5.3.1 (b) (i))
- Minor

Offside Steering box leaking oil (2.1.1 (e) (i))
- Pass with rectification

Offside Front Obligatory mirror insecure (3.3 (b) (ii))
- Advice

Front Coil spring corroded (5.3.1 (b) (i))
- Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Exhaust emits blue smoke during acceleration (8.2.1.2 (g))
- Minor

Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources 50% working (4.7.1 (b) (i))



MOT #20

2019-10-05 10:46

MOT test number

577174142864

Result

✓ Passed

- Advice

Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice

Rear Registration plate lamp slightly deteriorate
- Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Front Oil leak, but not excessive (8.4.1 (a) (i))
- Minor

Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice

Rear Coil spring corroded (5.3.1 (b) (i))
- Advice

Exhaust emits blue smoke during acceleration (8.2.1.2 (g))
- Minor

Offside Front Steering box leaking oil (2.1.1 (e) (i))
- Advice

Brake pedal wearing smooth (1.1.2 (c))
- Minor

Offside Front Obligatory mirror slightly loose (3.3 (b) (i))
- Advice

Front Coil spring corroded (5.3.1 (b) (i))

**MOT #19**

2019-10-05 10:46

MOT test number

893205855199

Result**✗ Failed**

- Minor** Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Pass with rectification** Rear Exhaust emissions likely to be affected by an induction leak (8.2.1.1 (b))
- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Offside Front Obligatory mirror slightly loose (3.3 (b) (i))
- Advice** Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Exhaust emits blue smoke during acceleration (8.2.1.2 (g))
- Advice** Rear Registration plate lamp slightly deteriorate
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Brake pedal wearing smooth (1.1.2 (c))
- Minor** Offside Front Steering box leaking oil (2.1.1 (e) (i))
- Advice** Front Coil spring corroded (5.3.1 (b) (i))

MOT #18

2018-10-03 10:38

MOT test number

139215909579

Result**✓ Passed**

- Advice** Exhaust has a minor leak of exhaust gases middle box (6.1.2 (a))
- Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #17** 2018-10-03 10:38**MOT test number** 691693542704**Result** ✗ Failed**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a))**Advice** Exhaust has a minor leak of exhaust gases middle box (6.1.2 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))**MOT #16** 2017-10-04 13:29**MOT test number** 703789853497**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Headlamp damaged but light output not reduced (1.7.5a)**Advice** Oil leak**MOT #15** 2017-10-04 12:19**MOT test number** 215789489397**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Headlamp damaged but light output not reduced (1.7.5a)**Fail** Offside Rear Body or chassis has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)**Advice** Oil leak

**MOT #14** 2016-10-04 14:24**MOT test number** 165224031655**Result** ✓ Passed**Advice** Power steering component(s) has slight seepage from a seal underside, steering rack (2.3.3b)**Advice** Exhaust has a minor leak of exhaust gases joint (7.1.2)**MOT #13** 2016-10-04 08:55**MOT test number** 300780327895**Result** ✗ Failed**Advice** Exhaust has a minor leak of exhaust gases joint (7.1.2)**Advice** Power steering component(s) has slight seepage from a seal underside, steering rack (2.3.3b)**Fail** Nearside Front Brake hose excessively damaged (3.6.B.4d)**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Fail** Offside Stop lamp not working (1.2.1b)**MOT #12** 2015-09-17 10:14**MOT test number** 570618314603**Result** ✓ Passed**MOT #11** 2014-10-02 11:04**MOT test number** 516025274266**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #10** 2013-10-02 12:19**MOT test number** 318405373440**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #9** 2012-10-03 15:52**MOT test number** 329297572277**Result** ✓ Passed**MOT #8** 2011-10-06 13:25**MOT test number** 628289471249**Result** ✓ Passed**Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)**Advice** Nearside Rear Brake hose slightly deteriorated (3.6.B.4d)**Advice** Offside Rear Brake hose slightly deteriorated (3.6.B.4d)**MOT #7** 2010-10-05 13:01**MOT test number** 100828870237**Result** ✓ Passed**MOT #6** 2009-10-14 14:02**MOT test number** 983647489235**Result** ✓ Passed**MOT #5** 2009-10-07 17:29**MOT test number** 103620789259**Result** ✗ Failed**Fail** Offside Rear fog lamp not working (1.3.2b)**Fail** Nearside Registration plate lamp not working (1.1.5c)**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**MOT #4** 2008-10-06 11:43**MOT test number** 792910188223**Result** ✓ Passed



MOT #3	2007-04-11 14:07
MOT test number	614941607169
Result	✓ Passed

MOT #2	2007-04-11 11:34
MOT test number	260471907196
Result	✗ Failed
<div><div>Notice</div> Vehical presenter is advised to replace the both front tyre</div> <div><div>Fail</div> Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)</div>	

MOT #1	2006-03-24 17:30
MOT test number	874673186059
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
1 September 2021

✕
MOT

Expired:
13 October 2021

Tax status	Expired at 1 September
Days left	971 days too late
MOT expiry date	13 October 2021
Full MOT history	See MOT history



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	1996-12-12
Last registration	2020-10-06
Complete history	See info



Registration #1	1996-12-12	7 mi
Registration #2	2006-03-24	63.178 mi
Registration #3	2007-04-11	74.024 mi
Registration #4	2007-04-11	74.204 mi
Registration #5	2008-10-06	81.980 mi
Registration #6	2009-10-07	89.528 mi
Registration #7	2009-10-14	89.637 mi
Registration #8	2010-10-05	94.807 mi
Registration #9	2011-10-06	101.890 mi
Registration #10	2012-10-03	108.306 mi
Registration #11	2013-10-02	113.924 mi
Registration #12	2014-10-02	120.957 mi
Registration #13	2015-10-02	120.957 mi
Registration #14	2016-10-02	120.957 mi
Registration #15	2017-10-02	120.957 mi
Registration #16	2018-10-02	120.957 mi
Registration #17	2019-10-02	120.957 mi
Registration #18	2020-10-02	120.957 mi
Registration #19	2021-10-02	120.957 mi
Registration #20	2022-10-02	120.957 mi
Registration #21	2023-10-02	120.957 mi
Registration #22	2024-10-02	120.957 mi
Registration #23	2025-10-02	120.957 mi
Registration #24	2026-10-02	120.957 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Additional information

Fuel tank capacity	76 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	2TZ0986894