



Mercedes-Benz

LG08XXX

report date: 2024-03-29

General information

Make	MERCEDES
Model	C CLK200K AVANTGARDE
Colour	Black
Year of manufacture	2008
Top speed	144 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	181 BHP
Max. torque	250 Nm at 2.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.8 mpg
Consumption extra urban	41.5 mpg
Consumption combined	31.7 mpg
CO2 emission	214 g/km
CO2 label	K





Internet history

Entry 2

Date	2021-10-27
Pictures	26
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-09-21
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)



## MOT history

MOT expiry date	2024-08-03
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	17
Total items failed	20

MOT #20 2023-08-04 15:29

MOT test number 792497094160

Result ✓ Passed

Next expiry date 2024-08-03

**Advice** Nearside Front Tyre slightly damaged/cracking or perishing slight damage to side wall (5.2.3 (d) (ii))

**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Nearside Rear Road wheel slightly distorted rim damaged (5.2.2 (c) (i))

MOT #19 2023-08-01 18:17

MOT test number 268941083573

Result ✗ Failed

**Advice** Nearside Rear Road wheel slightly distorted rim damaged (5.2.2 (c) (i))

**Fail** Offside Brake pipe excessively corroded front to rear above tank (1.1.11 (c))

**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

**Fail** Nearside Brake pipe excessively corroded front to rear above tank (1.1.11 (c))

**Advice** Nearside Front Tyre slightly damaged/cracking or perishing slight damage to side wall (5.2.3 (d) (ii))

**MOT #18** 2021-11-17 13:45**MOT test number** 681894461380**Result** ✓ Passed**MOT #17** 2021-04-20 13:46**MOT test number** 205302474290**Result** ✓ Passed**MOT #16** 2020-04-21 14:01**MOT test number** 538472677735**Result** ✓ Passed**MOT #15** 2020-04-21 09:55**MOT test number** 509454291845**Result** ✗ Failed

- Fail** Offside Front Road wheel fixing missing (5.2.1 (a) (i))
- Fail** Offside Rear Road wheel fixing missing (5.2.1 (a) (i))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Nearside Front Road wheel fixing missing (5.2.1 (a) (i))
- Fail** Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #14** 2019-04-08 13:18**MOT test number** 908125628782**Result** ✓ Passed

**MOT #13** 2019-04-08 13:18**MOT test number** 995721435117**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))**MOT #12** 2018-03-29 14:52**MOT test number** 164496384485**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #11** 2018-03-29 11:07**MOT test number** 902757638216**Result** ✗ Failed**Fail** Offside Rear Tyre(s) incorrect because different size tyres are fitted on the same axle. space saver fitted (4.1.A.1a)**Fail** Offside Stop lamp not working (1.2.1b)**MOT #10** 2017-04-07 09:01**MOT test number** 577017309625**Result** ✓ Passed**MOT #9** 2017-04-04 13:04**MOT test number** 680987664943**Result** ✗ Failed**Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement front arm (2.4.G.2)**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm 245/40R17 (4.1.E.1)

**MOT #8** 2016-03-11 14:06**MOT test number** 885060320185**Result** ✓ Passed**MOT #7** 2015-03-03 15:05**MOT test number** 156882565079**Result** ✓ Passed**MOT #6** 2015-03-03 15:05**MOT test number** 476222365030**Result** ✗ Failed**Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)**MOT #5** 2014-02-27 09:33**MOT test number** 547528454055**Result** ✓ Passed**Notice** O/s/r alloy damaged**MOT #4** 2013-02-26 12:28**MOT test number** 259537153059**Result** ✓ Passed**Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front wheel bearing has slight play (2.5.A.3c)

**MOT #3** 2013-02-25 14:44**MOT test number** 166106053439**Result** ✗ Failed**Fail** Offside Front Suspension arm ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front wheel bearing has slight play (2.5.A.3c)**Fail** Offside Front Anti-roll bar ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2012-02-25 11:31**MOT test number** 188466352067**Result** ✓ Passed**MOT #1** 2011-02-15 15:50**MOT test number** 816136941074**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Unable to inspect brake master cylinder, front suspension & steering fully due to covers fitted**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
3 August 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	3 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-





Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 <b>LG08XXX</b>
Plate since	2024-03-29
Current registration	 <b>LG08XXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-03-01
Last registration	2023-08-04
Complete history	<a href="#">See info</a>



Registration #1	2008-03-01	7 mi
Registration #2	2011-02-15	21.255 mi
Registration #3	2012-02-25	30.802 mi
Registration #4	2013-02-25	37.328 mi
Registration #5	2013-02-26	37.328 mi
Registration #6	2014-02-27	44.642 mi
Registration #7	2015-03-03	48.189 mi
Registration #8	2016-03-11	53.359 mi
Registration #9	2017-04-04	69.158 mi
Registration #10	2017-04-07	69.158 mi
Registration #11	2018-03-29	85.253 mi
Registration #12	2019-03-29	85.253 mi
Registration #13	2019-03-29	85.253 mi
Registration #14	2019-03-29	85.253 mi
Registration #15	2019-03-29	85.253 mi
Registration #16	2019-03-29	85.253 mi
Registration #17	2019-03-29	85.253 mi
Registration #18	2019-03-29	85.253 mi
Registration #19	2019-03-29	85.253 mi
Registration #20	2019-03-29	85.253 mi
Registration #21	2019-03-29	85.253 mi
Registration #22	2019-03-29	85.253 mi

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2715 mm
Kerb weight	1685 kg
Max. allowed weight	2145 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27195530985150