



report date: 2024-03-29

General information

Make	VOLVO
Model	S40 D SPORT
Colour	White
Year of manufacture	2009
Top speed	127 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-10-11
Pictures	8
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-28
MOT pass rate	62 %
MOT passed	13
Failed MOT tests	8
Total advice items	36
Total items failed	24

MOT #21	2023-10-27 14:45
MOT test number	561792049984
Result	✓ Passed
Next expiry date	2024-10-28
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))

MOT #20	2023-10-24 09:21
MOT test number	194480341480
Result	✗ Failed
Fail	Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))
Fail	Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #19**

2022-10-29 14:28

**MOT test number**

480563857644

**Result**

✓ Passed

**Advice** Rear Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))

**Advice** Rear Coil spring worn both coils (5.3.1 (b) (i))

**Advice** Rear Tyre slightly damaged/cracking or perishing both tyres (5.2.3 (d) (ii))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear pin/bush (5.3.4 (a) (i))

**MOT #18**

2022-10-26 15:20

**MOT test number**

500685484543

**Result**

✗ Failed

**Fail** Road wheel more than one fixing missing one from each wheel (5.2.1 (a) (ii))

**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**Advice** Rear Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))

**Fail** Nearside Front Suspension arm pin or bush excessively worn rear pin/bush (5.3.4 (a) (i))

**Fail** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Advice** Rear Tyre slightly damaged/cracking or perishing both tyres (5.2.3 (d) (ii))

**Advice** Rear Coil spring worn both coils (5.3.1 (b) (i))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear pin/bush (5.3.4 (a) (i))

**Fail** Front Registration plate inscription illegible (0.1 (b))

**MOT #17**

2022-09-30 08:12

**MOT test number**

765847799666

**Result****✗ Failed**

- Fail** Nearside Front Road wheel fixing missing (5.2.1 (a) (i))
- Fail** Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Fail** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Front Road wheel fixing missing (5.2.1 (a) (i))
- Fail** Offside Rear Road wheel fixing missing (5.2.1 (a) (i))
- Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values limit 0.51 (8.2.2.2 (f))

**MOT #16**

2021-10-20 15:57

**MOT test number**

195707099898

**Result****✓ Passed**

- Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Front Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**MOT #15** 2021-01-26 09:10**MOT test number** 402048569514**Result** ✓ Passed**MOT #14** 2020-02-04 13:38**MOT test number** 504940464215**Result** ✓ Passed**MOT #13** 2020-01-31 10:06**MOT test number** 592322675607**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**Fail** Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #12** 2019-01-15 09:49**MOT test number** 110150224767**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))**MOT #11** 2018-01-30 11:00**MOT test number** 528756584828**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #10** 2017-01-30 08:31**MOT test number** 506025080932**Result** ✓ Passed**MOT #9** 2016-01-05 11:51**MOT test number** 457472090345**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit inner edge (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit inner edge (4.1.E.1)**MOT #8** 2015-01-15 15:57**MOT test number** 389615715027**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2015-01-15 14:25**MOT test number** 868525915096**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #6** 2014-01-21 16:22**MOT test number** 468041424089**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #5** 2014-01-21 16:03**MOT test number** 599701624058**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Front Brake pedal anti-slip provision missing (3.3.A.1b)**MOT #4** 2013-03-25 14:34**MOT test number** 315004883051**Result** ✓ Passed**MOT #3** 2013-03-25 10:38**MOT test number** 337934383001**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Front Brake pedal anti-slip provision missing (3.3.A.1b)**MOT #2** 2012-02-15 13:18**MOT test number** 248616142080**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2012-02-15 11:05**MOT test number** 159216942467**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)





Tax & MOT check

✓

Taxed

Tax due:  
1 August 2024

✓

MOT

Expires:  
28 October 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	28 October 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2009-03-04
Last registration	2023-10-27
Complete history	<a href="#">See info</a>



Registration #1	2009-03-04	29 mi
Registration #2	2012-02-15	26.481 mi
Registration #3	2012-02-15	26.481 mi
Registration #4	2013-03-25	36.529 mi
Registration #5	2013-03-25	36.529 mi
Registration #6	2014-01-21	43.407 mi
Registration #7	2014-01-21	43.407 mi
Registration #8	2015-01-15	51.426 mi
Registration #9	2015-01-15	51.426 mi
Registration #10	2016-01-05	59.046 mi
Registration #11	2017-01-30	68.292 mi
Registration #12	2018-01-30	73.919 mi
Registration #13	2019-01-30	79.546 mi
Registration #14	2019-01-30	79.546 mi
Registration #15	2019-01-30	79.546 mi
Registration #16	2019-01-30	79.546 mi
Registration #17	2019-01-30	79.546 mi
Registration #18	2019-01-30	79.546 mi
Registration #19	2019-01-30	79.546 mi
Registration #20	2019-01-30	79.546 mi
Registration #21	2019-01-30	79.546 mi
Registration #22	2019-01-30	79.546 mi
Registration #23	2019-01-30	79.546 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1481 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	436040