





report date: 2024-03-29

General information

Make	KIA
Model	CARENS 3 ECODYNAMICS CRDI
Colour	Silver
Year of manufacture	2015
Top speed	119 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	330 Nm at 2.000 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	61.4 mpg
Consumption combined	56.5 mpg
CO2 emission	132 g/km
CO2 label	E



CarCheck.co.uk page 1/11



Internet history

Er	ıtı	rv	2

Date	2023-08-21
Pictures	0
Listing price	View report

source: carcraft.co.uk

Entry 1

Date	2021-09-03
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

RK15PUA report date: 2024-03-29

MOT expiry date	2025-01-21
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	4
Total items failed	7

MOT #7	2024-01-22 13:22
MOT test number	185405611698
Result	✓ Passed
Next expiry date	2025-01-21

MOT #6	2023-04-29 07:35
MOT test number	237903134385
Result	✓ Passed

MOT #5	2020-12-17 11:50
MOT test number	830582398640

Minor Nearside Front Side repeater lens defective which has no effect on emitted light Mirror indicator lens damaged but functioning as intended (4.4.1 (b) (i))

CarCheck.co.uk page 3/11



RK15PUA

report date: 2024-03-29

MOT #4 2020-12-16 09:22

MOT test number 829275320316

Result X Failed

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords outer sidewall cut to cords yellow chalk Avon 225/45/R17 (5.2.3 (d) (i))

Fail Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Rear Nail in tyre screw yellow chalk repairable. sidewall worn & damaged/ageing.

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords outer sidewall cut to cords. Pirelli 225/45/R17 94W (5.2.3 (d) (i))

Fail Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Minor Nearside Front Side repeater lens defective which has no effect on emitted light Mirror indicator lens damaged but functioning as intended (4.4.1 (b) (i))

MOT #3 2019-04-05 12:40

MOT test number 579113261416

Result
✓ Passed

MOT #2 2019-04-05 10:46

MOT test number 126269779980

Result X Failed

Fail Front Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))

Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #1 2018-04-10 11:53

MOT test number 172116394918

Advice Wet test

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	21 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 5/11



RK15PUA

report date: 2024-03-29

Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

*		
For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report I		

	More info	>
Plate changes		
See in this check if this KIA had different number plates.		
Number of plates		,
Current registration	NK SILE	
Plate since		
Current registration	NK MAN	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-04-02
Last registration	2024-01-22
Complete history	See info



Registration #1	2015-04-02	9 mi
Registration #2	2018-04-10	32.917 mi
Registration #3	2019-04-05	40.594 mi
Registration #4	2019-04-05	40.594 mi
Registration #5	2020-12-16	46.151 mi
Registration #6		11.177 es
Registration #7		11.777 es
Registration #8		
3		
Registration #9		11.177 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	94%
Children	76%
Pedestrian	64%
Safety systems	81%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1805 mm
Height	1605 mm
Length	4525 mm
Wheel base	2750 mm
Kerb weight	1716 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	58 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 11/11

Number of axles 2

Engine number D4FDEU466366