



report date: 2024-03-28

General information

Make	VAUXHALL
Model	VECTRA VVT EXCLUSIV
Colour	Beige
Year of manufacture	2008
Top speed	126 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 3.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.2 mpg
CO2 emission	173 g/km
CO2 label	H





Internet history

Entry 1	
Date	2021-09-12
Pictures	43
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-20
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	52
Total items failed	1

MOT #20 2023-09-19 11:36**MOT test number** 976232330876**Result** ✓ Passed**Next expiry date** 2024-09-20

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 3mm and inner edge worn smooth (5.2.3 (e))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Exhaust mounting defective (6.1.2 (a))

MOT #19 2022-09-16 08:38**MOT test number** 844595278307**Result** ✓ Passed

- Advice** Exhaust mounting defective (6.1.2 (a))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #18**

2022-09-15 07:28

MOT test number

585770248442

Result**✗ Failed**

- MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- MAJOR** Offside Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
- Advice** Exhaust mounting defective (6.1.2 (a))
- MAJOR** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- MAJOR** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- MAJOR** Nearside Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- MAJOR** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #17

2021-09-21 11:05

MOT test number

982465132196

Result**✓ Passed****MOT #16**

2021-07-13 15:46

MOT test number

155234660011

Result**✓ Passed**

- Advice** Exhaust has a minor leak of exhaust gases front flexi inner broken (6.1.2 (a))

**MOT #15** 2021-07-13 09:27**MOT test number** 247826148646**Result** ✗ Failed**MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Exhaust has a minor leak of exhaust gases front flexi inner broken (6.1.2 (a))**MOT #14** 2020-07-24 15:03**MOT test number** 741502947911**Result** ✓ Passed**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #13** 2020-07-24 08:46**MOT test number** 780051073706**Result** ✗ Failed**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MAJOR** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**MAJOR** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Minor** Nearside Rear Upper Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))**MAJOR** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MAJOR** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Minor** Nearside Rear Upper Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #12** 2019-07-18 15:58**MOT test number** 256916859412**Result** ✓ Passed**Advice** Tyre worn close to legal limit/worn on edge both rear on legal limit and perished (5.2.3 (e))**Advice** Tyre worn close to legal limit/worn on edge both front on legal limit and perished (5.2.3 (e))**MOT #11** 2019-07-18 13:09**MOT test number** 678093244115**Result** ✗ Failed**Advice** Tyre worn close to legal limit/worn on edge both front on legal limit and perished (5.2.3 (e))**MAJOR** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Tyre worn close to legal limit/worn on edge both rear on legal limit and perished (5.2.3 (e))**MOT #10** 2018-07-09 15:43**MOT test number** 697467470772**Result** ✓ Passed**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Exhaust flexy front pipe deteriorated but not likely to become detached.**Advice** Rear Direction indicator slightly discoloured both sides, (4.4.3 (a))**Advice** Sill covers fitted preventing full inspection.

**MOT #9** 2018-07-09 10:10**MOT test number** 754809876505**Result** ✗ Failed**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Exhaust flexy front pipe deteriorated but not likely to become detached.**Advice** Rear Direction indicator slightly discoloured both sides, (4.4.3 (a))**Advice** Sill covers fitted preventing full inspection.**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #8** 2017-07-07 10:00**MOT test number** 921937049402**Result** ✓ Passed**Advice** Registration plate deteriorated but not likely to be misread front and rear, (6.3.1d)**Advice** Items removed from driver's view prior to test**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Sill covers fitted preventing full inspection.**MOT #7** 2016-07-06 10:44**MOT test number** 151506356725**Result** ✓ Passed**MOT #6** 2015-07-08 09:51**MOT test number** 656239085114**Result** ✓ Passed**MOT #5** 2014-07-09 12:45**MOT test number** 415200094182**Result** ✓ Passed



MOT #4 2013-07-04 16:10

MOT test number 768845683188

Result ✓ Passed

MOT #3 2013-07-04 12:32

MOT test number 386175283131

Result ✗ Failed

Fail Offside Front coil spring broken (2.4.C.1a)

MOT #2 2012-07-11 09:44

MOT test number 137003692133

Result ✓ Passed

MOT #1 2011-07-13 10:37

MOT test number 265794091416

Result ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
20 September 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	20 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Number of owners	1
Current owner since	2019-01-01
Previous owner since	2019-01-01
Number of owners	1
Current owner since	2019-01-01
Previous owner since	2019-01-01

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 KW08NKH
Plate since	2019-01-01
Current registration	 KW08NKH
Plate since	2019-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-07-23
Last registration	2023-09-19
Complete history	See info



Registration #1	2008-07-23	11 mi
Registration #2	2011-07-13	28.985 mi
Registration #3	2012-07-11	32.390 mi
Registration #4	2013-07-04	35.550 mi
Registration #5	2013-07-04	35.550 mi
Registration #6	2014-07-09	41.022 mi
Registration #7	2015-07-08	46.916 mi
Registration #8	2016-07-06	52.932 mi
Registration #9	2017-07-07	57.389 mi
Registration #10	2018-07-09	61.900 mi
Registration #11	2018-07-09	61.902 mi
Registration #12	2019-07-09	61.902 mi
Registration #13	2019-07-09	61.902 mi
Registration #14	2019-07-09	61.902 mi
Registration #15	2019-07-09	61.902 mi
Registration #16	2019-07-09	61.902 mi
Registration #17	2019-07-09	61.902 mi
Registration #18	2019-07-09	61.902 mi
Registration #19	2019-07-09	61.902 mi
Registration #20	2019-07-09	61.902 mi
Registration #21	2019-07-09	61.902 mi
Registration #22	2019-07-09	61.902 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4596 mm
Wheel base	2700 mm
Kerb weight	1350 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	20KV4564