



TOYOTA

DU5IZBL

report date: 2024-03-28

General information

Make	TOYOTA
Model	LAND CRUISER GX TD
Colour	Silver
Year of manufacture	2001
Top speed	105 mph
0 - 60 mph	13.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	201 BHP
Max. torque	430 Nm at 1.400 rpm
Engine capacity	4.164 cc
Cylinders	6
Fuel type	Diesel
Consumption city	20.2 mpg
Consumption extra urban	30.1 mpg
Consumption combined	25.4 mpg
CO2 emission	292 g/km
CO2 label	M








Internet history

Entry 1

Date	2021-10-09
Pictures	38
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2022-09-22
MOT pass rate	94 %
MOT passed	16
Failed MOT tests	1
Total advice items	27
Total items failed	1

MOT #17 2021-09-23 10:41

MOT test number 667499319972

Result ✓ Passed

Next expiry date 2022-09-22

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Integral body structure is corroded but structural rigidity is not significantly reduced all over (6.1.1 (c) (i))
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced sills (6.1.1 (c) (i))

MOT #16 2020-11-24 10:02

MOT test number 251291254449

Result ✓ Passed

- Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Inner Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #15** 2019-11-22 15:00**MOT test number** 730461658318**Result** ✓ Passed

Advice Offside Rear Inner Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Advice Nearside Rear Inner Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

MOT #14 2018-11-12 12:38**MOT test number** 942898237138**Result** ✓ Passed

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Inner Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Advice Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Inner Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Advice Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #13 2017-11-08 13:12**MOT test number** 309974702663**Result** ✓ Passed**MOT #12** 2016-11-16 17:58**MOT test number** 519461952406**Result** ✓ Passed**MOT #11** 2015-11-02 10:48**MOT test number** 810190005840**Result** ✓ Passed

Advice Tyre worn close to the legal limit both rear tyres (4.1.E.1)

**MOT #10** 2014-11-01 14:18**MOT test number** 329385704326**Result** ✓ Passed**MOT #9** 2013-10-02 10:30**MOT test number** 309705873415**Result** ✓ Passed**MOT #8** 2012-07-13 16:32**MOT test number** 379135992185**Result** ✓ Passed**Advice** Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Rear coil spring corroded (2.4.C.1b)**Advice** Front Front wheel bearing has slight play (2.5.A.3c)**MOT #7** 2012-07-13 16:32**MOT test number** 665075592186**Result** ✗ Failed**Advice** Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Rear coil spring corroded (2.4.C.1b)**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Front Front wheel bearing has slight play (2.5.A.3c)**MOT #6** 2011-06-21 12:58**MOT test number** 206722371181**Result** ✓ Passed



MOT #5	2010-06-15 10:50
---------------	------------------

MOT test number	151516360174
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2009-04-22 09:36
---------------	------------------

MOT test number	834982219130
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2008-04-23 10:00
---------------	------------------

MOT test number	890474718174
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2007-04-17 17:44
---------------	------------------

MOT test number	603437307117
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2006-05-18 14:48
---------------	------------------

MOT test number	291818436455
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Front brake grabbing slightly (3.7.A.2b)
---------------	--

Advice	Rear Brake pad(s) wearing thin (3.5.1g)
---------------	---



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2001-09-01
Last registration	2021-09-23
Complete history	See info



Registration #1	2001-09-01	11 mi
Registration #2	2006-05-18	26.107 mi
Registration #3	2007-04-17	29.566 mi
Registration #4	2008-04-23	43.906 mi
Registration #5	2009-04-22	51.388 mi
Registration #6	2010-06-15	67.032 mi
Registration #7	2011-06-21	77.640 mi
Registration #8	2012-07-13	83.239 mi
Registration #9	2013-10-02	87.626 mi
Registration #10	2014-05-20	91.377 mi
Registration #11	2015-05-20	95.377 mi
Registration #12	2016-05-20	99.377 mi
Registration #13	2017-05-20	103.377 mi
Registration #14	2018-05-20	107.377 mi
Registration #15	2019-05-20	111.377 mi
Registration #16	2020-05-20	115.377 mi
Registration #17	2021-05-20	119.377 mi
Registration #18	2022-05-20	123.377 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1940 mm
Height	1890 mm
Length	4890 mm
Wheel base	2850 mm
Kerb weight	2620 kg

Additional information

Fuel tank capacity	96 l
Fuel delivery	Direct Injection
Number of doors	5
Engine number	1HD0211093