




report date: 2024-03-28

General information

Make	KIA
Model	SORENTO CRDI KX-3 ISG
Colour	Black
Year of manufacture	2015
Top speed	124 mph
0 - 60 mph	9.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	197 BHP
Max. torque	441 Nm at 1.750 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	46.3 mpg
CO2 emission	161 g/km
CO2 label	G






Internet history

Entry 2


Date	2022-06-16
Pictures	11
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-07-25
Pictures	5
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-08-01
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	7
Total items failed	1

MOT #7	2023-07-21 09:10
MOT test number	314519827024
Result	✓ Passed
Next expiry date	2024-08-01
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #6	2022-08-02 11:12
MOT test number	681685571892
Result	✓ Passed

MOT #5	2021-06-14 08:23
MOT test number	859493941024
Result	✓ Passed
Advice	Rear Seat belt webbing slightly damaged or frayed both rear 3rd row seat belts have marks, damage but not significantly weakened. (7.1.2 (b) (ii))

MOT #4	2020-07-06 13:48
MOT test number	310324886319
Result	✓ Passed
Advice	Offside Rear Seat belt slightly damaged (7.1.2 (b) (i))



MOT #3 2020-07-06 09:54

MOT test number 665949341230

Result ✗ Failed

**Fail** Nearside Front Tyre has ply or cords damaged (5.2.3 (d) (ii))

**Advice** Offside Rear Seat belt slightly damaged (7.1.2 (b) (i))

MOT #2 2019-05-21 15:50

MOT test number 620063662869

Result ✓ Passed

**Advice** Rear unable to fully inspect 3rd row seats and belts due to luggage

MOT #1 2018-05-10 13:03

MOT test number 391596344561

Result ✓ Passed

**Advice** Offside Rear tyre worn on inner edge

**Advice** Nearside Rear tyre worn badly on edges



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
1 August 2024

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	279
<b>MOT expiry date</b>	1 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >





Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-05-25
Last registration	2023-07-21
Complete history	<a href="#">See info</a>



Registration #1	2015-05-25	27 mi
Registration #2	2018-05-10	24.564 mi
Registration #3	2019-05-21	32.995 mi
Registration #4	2020-07-06	39.976 mi
Registration #5	2020-07-06	39.979 mi
Registration #6	2020-07-06	39.979 mi
Registration #7	2020-07-06	39.979 mi
Registration #8	2020-07-06	39.979 mi
Registration #9	2020-07-06	39.979 mi
Registration #10	2020-07-06	39.979 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	83%
Pedestrian	67%
Safety systems	71%
Overall rating	80%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1890 mm
Height	1685 mm
Length	4780 mm
Wheel base	2780 mm
Kerb weight	1932 kg
Max. allowed weight	2590 kg

Additional information

Fuel tank capacity	71 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

<b>Number of axles</b>	2
<b>Engine number</b>	D4HBFH228189