



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	S-Class S320 CDI
Colour	Silver
Year of manufacture	-
Top speed	149 mph
0 - 60 mph	7.5 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	231 BHP
Max. torque	540 Nm at 1.600 rpm
Cylinders	6
Fuel type	Diesel
Consumption city	24.4 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.0 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-11
Pictures	18
Listing price	View report



01783 943990
07944 225693
Email: sales@handler.co.uk
www.handler.co.uk

£5,295

Mercedes-Benz S Class
3.5 S350 CDI 4MATIC
2007 (57 Reg)

This car has been thoroughly checked by our experienced technicians. It has a clean history, no accidents, and is in excellent condition. It is a rare find and a great investment. The car is in excellent condition and is a great investment. It is a rare find and a great investment. It is a rare find and a great investment.

HANDLER

DETAILS OF THIS CAR

Mileage	156,747 miles
Colour	Black
Transmission	Automatic
Fuel	Petrol
Power Tax (CO2 emissions)	230g
Year	2007
Local Service	2010 (57 Reg)
Service History	Full Service History
Warranty	6 months

TECHNICAL SPECIFICATIONS

Engine Size	3.5L
Number of Seats	4
Gearbox	Automatic
Colour	Black
Year	2007
Engine Power	230g



source: cargurus.co.uk

**MOT history**

MOT #17	2023-09-05 12:07
MOT test number	152977885839
Result	✓ Passed
Next expiry date	2024-09-04
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #16	2022-09-03 10:26
MOT test number	818667730271
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Wheel bearing has slight play offside and nearside front (5.1.3 (a) (i))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Front Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #15	2022-09-01 09:27
MOT test number	866205618705
Result	✗ Failed
Fail	Suspension arm pin or bush excessively worn offside and nearside front (5.3.4 (a) (i))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Fail	Offside Front Tyre(s) of different sizes are fitted on the same axle. incorrect size (5.2.3 (b))
Fail	Driver's seat fore and aft adjustment mechanism not functioning as intended. (6.2.5 (b) (i))
Advice	Front Service brake fluctuating, but not excessively (1.2.1 (e))
Fail	Fuel tank leaking (6.1.3 (b) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Wheel bearing has slight play offside and nearside front (5.1.3 (a) (i))
Fail	Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #14** 2021-07-26 08:47**MOT test number** 167117597905**Result** ✓ Passed**MOT #13** 2020-10-22 12:47**MOT test number** 475564107999**Result** ✓ Passed**MOT #12** 2019-10-18 10:29**MOT test number** 814001113496**Result** ✓ Passed

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #11 2018-10-17 15:02**MOT test number** 352245858934**Result** ✓ Passed**MOT #10** 2018-10-17 09:13**MOT test number** 825546583336**Result** ✗ Failed

- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #9** 2017-10-16 08:39**MOT test number** 203217534728**Result** ✓ Passed

- Advice** Front Tyre worn close to the legal limit both wearing on outer edge (4.1.E.1)
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Front Lower Suspension arm has slight play in a ball joint rearmost (2.4.G.2)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

MOT #8 2016-10-11 10:20**MOT test number** 326146915854**Result** ✓ Passed**MOT #7** 2016-10-11 10:20**MOT test number** 979221912200**Result** ✗ Failed

- Pass with rectification** Offside Front Headlamp aim too high and too far to the right. (1.8)
- Pass with rectification** Nearside Front Direction indicator not working (1.4.A.2c)

MOT #6 2015-10-08 09:32**MOT test number** 282346961746**Result** ✓ Passed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)

MOT #5 2014-10-16 13:00**MOT test number** 238029984256**Result** ✓ Passed



MOT #4	2013-10-23 15:23
MOT test number	295506493238
Result	✓ Passed
MOT #3	2012-03-08 16:38
MOT test number	406208062035
Result	✓ Passed
MOT #2	2011-03-08 10:16
MOT test number	145417561459
Result	✓ Passed
MOT #1	2011-03-08 09:13
MOT test number	637097761097
Result	✗ Failed
Fail	Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Fail	Nearside Front Front position lamp(s) not working (1.1.A.3b)



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	 XXXXX
Plate since	2024-03-29
Current registration	 XXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-12-21
Last registration	2023-09-05
Complete history	See info



Registration #1	2007-12-21	12 mi
Registration #2	2011-03-08	21.007 mi
Registration #3	2011-03-08	21.007 mi
Registration #4	2012-03-08	29.543 mi
Registration #5	2013-10-23	48.341 mi
Registration #6	2014-10-16	59.927 mi
Registration #7	2015-10-08	73.516 mi
Registration #8	2016-10-11	86.952 mi
Registration #9	2016-10-11	86.952 mi
Registration #10	2017-10-16	94.876 mi
Registration #11	2019-05-20	95.377 mi
Registration #12	2019-05-20	95.377 mi
Registration #13	2019-05-20	95.377 mi
Registration #14	2019-05-20	95.377 mi
Registration #15	2019-05-20	95.377 mi
Registration #16	2019-05-20	95.377 mi
Registration #17	2019-05-20	95.377 mi
Registration #18	2019-05-20	95.377 mi
Registration #19	2019-05-20	95.377 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1872 mm
Height	1473 mm
Length	5076 mm
Wheel base	3035 mm
Kerb weight	1965 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles

2

Engine number

64293040497268