



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	CELICA VVTi
Colour	Blue
Year of manufacture	-
Top speed	127 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	170 Nm at 4.200 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.7 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2021-06-25
Pictures	1
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-06-24
Pictures	1
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #17	2021-03-23 16:21
MOT test number	530657403621
Result	✓ Passed
Next expiry date	2022-03-22
Advice	Nearside Rear Coil spring corroded corroded (5.3.1 (b) (i))
Advice	Offside Rear Coil spring corroded corroded (5.3.1 (b) (i))
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #16	2020-10-21 16:43
MOT test number	261510040146
Result	✗ Failed
Advice	Nearside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive Sill area (5.3.6 (a) (i))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened Pitted (1.1.14 (a) (ii))
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Nearside Rear Service brake effort inadequate at a wheel (1.2.1 (a) (i))
Fail	Offside Rear Position lamp not working (4.2.1 (a) (ii))
Advice	Offside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive Sill area (5.3.6 (a) (i))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened Pitted (1.1.14 (a) (ii))
Fail	Offside Rear Service brake effort inadequate at a wheel (1.2.1 (a) (i))

MOT #15	2019-04-11 09:13
MOT test number	377890704698
Result	✓ Passed
MOT #14	2019-04-11 09:13
MOT test number	408372452342
Result	✗ Failed

Pass with rectification

Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #13** 2018-03-09 16:01**MOT test number** 660685966536**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #12** 2017-03-17 12:51**MOT test number** 242269492453**Result** ✓ Passed**Advice** Front number plate damaged**MOT #11** 2017-03-15 09:27**MOT test number** 384873491106**Result** ✗ Failed**Fail** Nearside Rear Mechanical brake component locking device missing bottom brake pad retraining pin missing (3.5.1I)**Advice** Front number plate damaged**Fail** Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #10** 2016-03-07 15:38**MOT test number** 443928838133**Result** ✓ Passed**MOT #9** 2016-03-03 12:56**MOT test number** 282012679726**Result** ✗ Failed**Fail** Brake pad(s) less than 1.5 mm thick rear pads low offside (3.5.1g)**Fail** Brake pad(s) less than 1.5 mm thick rear pads low nearside (3.5.1g)

**MOT #8** 2015-03-05 11:37**MOT test number** 675704565038**Result** ✓ Passed**MOT #7** 2014-03-08 12:23**MOT test number** 817277864064**Result** ✓ Passed**Advice** Front brake fluctuating, but not excessively (3.7.B.3)**Notice** Offside wiper blade performance**MOT #6** 2013-03-18 18:13**MOT test number** 909827173031**Result** ✓ Passed**MOT #5** 2013-03-18 16:52**MOT test number** 145567573430**Result** ✗ Failed**Notice** Wear offside rear tyre only just legal**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #4** 2012-02-27 12:12**MOT test number** 988538052033**Result** ✓ Passed**MOT #3** 2011-03-08 10:46**MOT test number** 868707761022**Result** ✓ Passed



MOT #2	2010-03-01 11:08
MOT test number	482470860010
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2009-03-02 15:25
MOT test number	332871169075
Result	✓ Passed



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	YD06YFG
Plate since	2024-03-28
Current registration	YD06YFG
Plate since	2024-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-03-24
Last registration	2021-03-23
Complete history	See info



Registration #1	2006-03-24	21 mi
Registration #2	2009-03-02	14.369 mi
Registration #3	2010-03-01	18.663 mi
Registration #4	2011-03-08	23.661 mi
Registration #5	2012-02-27	25.967 mi
Registration #6	2013-03-18	32.294 mi
Registration #7	2013-03-18	32.295 mi
Registration #8	2014-03-08	38.617 mi
Registration #9	2015-03-05	47.131 mi
Registration #10	2016-03-03	58.359 mi
Registration #11	2016-03-03	58.359 mi
Registration #12	2016-03-03	58.359 mi
Registration #13	2016-03-03	58.359 mi
Registration #14	2016-03-03	58.359 mi
Registration #15	2016-03-03	58.359 mi
Registration #16	2016-03-03	58.359 mi
Registration #17	2016-03-03	58.359 mi
Registration #18	2016-03-03	58.359 mi
Registration #19	2016-03-03	58.359 mi
Registration #20	2016-03-03	58.359 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1735 mm
Height	1315 mm
Length	4350 mm
Wheel base	2600 mm
Max. allowed weight	1565 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	1ZZ2365240