



report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D5 SE LUX
Colour	Red
Year of manufacture	2011
Top speed	140 mph
0 - 60 mph	7.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	212 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-06-26
Pictures	16
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-04
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	24
Total items failed	11

MOT #16	2023-06-29 10:31
MOT test number	434032525895
Result	✓ Passed
Next expiry date	2024-07-04
Advice	Nearside Rear Tyre distorted-225/50/17
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
Minor	Nearside Rear Tyre obviously under inflated (5.2.3 (l))
Advice	Rear Coil spring corroded Both (5.3.1 (b) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Coolant leak Radiator

MOT #15	2022-06-30 10:52
MOT test number	623810756949
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge Worn inner edge (5.2.3 (e))
Advice	Rear tyres distorted-225/50/17
Advice	Offside Front Tyre worn close to legal limit/worn on edge Worn inner edge (5.2.3 (e))

**MOT #14** 2022-06-30 08:37**MOT test number** 321461427770**Result** ✗ Failed**Fail** Electronic stability control warning lamp indicates a fault (7.12 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Worn inner edge (5.2.3 (e))**Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Advice** Offside Front Tyre worn close to legal limit/worn on edge Worn inner edge (5.2.3 (e))**Advice** Rear tyres distorted-225/50/17**MOT #13** 2021-07-05 12:07**MOT test number** 638222191712**Result** ✓ Passed**MOT #12** 2021-07-01 13:20**MOT test number** 894717955414**Result** ✗ Failed**Fail** Trailer electrical socket (13 pin) not operating the trailer lamps as intended (4.10 (c) (i))**MOT #11** 2020-11-07 11:43**MOT test number** 286420888932**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #10** 2019-11-11 09:52**MOT test number** 855121538268**Result** ✓ Passed

**MOT #9** 2018-11-21 11:18**MOT test number** 545210175323**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**MOT #8** 2017-11-29 11:29**MOT test number** 296771352314**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2017-11-27 14:19**MOT test number** 681077482197**Result** ✗ Failed**Fail** Nearside Rear Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Headlamp aim beam image obviously incorrect main beam (1.8.A.1b)**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Fail** Offside Rear Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2017-05-25 14:57**MOT test number** 884608845797**Result** ✓ Passed

**MOT #5** 2016-05-27 15:25**MOT test number** 997930136979**Result** ✓ Passed**MOT #4** 2016-05-25 16:10**MOT test number** 251483176951**Result** ✗ Failed**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**MOT #3** 2015-10-21 10:39**MOT test number** 934439866608**Result** ✓ Passed**Advice** Nearside Front tyre 3mm bald inner edge**Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Under trays fitted not allowing full inspection of some components**Advice** Rear Inner Brake pad(s) wearing thin advise remove wheels for further inspection (3.5.1g)**MOT #2** 2014-10-21 10:33**MOT test number** 307844194215**Result** ✓ Passed**MOT #1** 2014-10-21 10:33**MOT test number** 605934794236**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)**Pass with rectification** Offside Headlamp aim too low (1.8)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
4 July 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	4 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-10-30
Last registration	2023-06-29
Complete history	See info



Registration #1	2011-10-30	13 mi
Registration #2	2014-10-21	76.022 mi
Registration #3	2015-10-21	108.771 mi
Registration #4	2016-05-25	116.411 mi
Registration #5	2016-05-27	116.413 mi
Registration #6	2017-05-25	130.686 mi
Registration #7	2017-11-27	131.322 mi
Registration #8	2017-11-29	131.323 mi
Registration #9	2018-11-21	136.969 mi
Registration #10	2019-05-29	151.377 mi
Registration #11	2019-05-29	151.377 mi
Registration #12	2019-05-29	151.377 mi
Registration #13	2019-05-29	151.377 mi
Registration #14	2019-05-29	151.377 mi
Registration #15	2019-05-29	151.377 mi
Registration #16	2019-05-29	151.377 mi
Registration #17	2019-05-29	151.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1757 kg
Max. allowed weight	2300 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1058451