



report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D R-DESIGN SE
Colour	Silver
Year of manufacture	2010
Top speed	124 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	157 g/km
CO2 label	G







Internet history

Entry 1

Date	2021-08-27
Pictures	15
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-09
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	23
Total items failed	1

MOT #13	2023-07-10 12:43
MOT test number	596903062215
Result	✓ Passed
Next expiry date	2024-07-09
Advice	Light feathering to both rear tyres

MOT #12	2023-06-29 11:27
MOT test number	983382286089
Result	✗ Failed
Advice	Light feathering to both rear tyres
MAJOR	Nearside Rear Suspension arm pin or bush excessively worn trailing arm (5.3.4 (a) (i))
MAJOR	Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))
MAJOR	Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
DANGEROUS	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
MAJOR	Offside Rear Suspension arm pin or bush excessively worn trailing arm (5.3.4 (a) (i))
MAJOR	Offside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #11** 2022-06-20 14:55**MOT test number** 252456162962**Result** ✓ Passed**Advice** Tyre worn close to legal limit/worn on edge both front (5.2.3 (e))**MOT #10** 2021-03-15 09:18**MOT test number** 542303483581**Result** ✓ Passed**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #9** 2021-03-15 09:18**MOT test number** 956403343717**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #8** 2020-03-16 11:06**MOT test number** 437150681049**Result** ✓ Passed**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement front trailing arm bush (5.3.4 (a) (i))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement front trailing arm bush (5.3.4 (a) (i))**MOT #7** 2019-03-18 08:21**MOT test number** 526070988528**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt

**MOT #6** 2018-03-19 09:31**MOT test number** 756226031932**Result** ✓ Passed**Advice** Nearside Rear Trailing arm has slight play in a pin/bush front bush (2.4.G.2)**MOT #5** 2017-03-20 11:31**MOT test number** 483533054953**Result** ✓ Passed**Advice** Nearside Rear Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement front bush (2.4.G.2)**MOT #4** 2016-02-27 10:22**MOT test number** 832175524931**Result** ✓ Passed**Advice** Nearside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #3** 2015-03-07 11:21**MOT test number** 828056465060**Result** ✓ Passed**MOT #2** 2014-03-01 11:19**MOT test number** 818760864073**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)



MOT #1	2013-03-02 10:01
MOT test number	185561263487
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
9 July 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	9 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-03-23
Last registration	2023-07-10
Complete history	See info



Registration #1	2010-03-23	6 mi
Registration #2	2013-03-02	32.934 mi
Registration #3	2014-03-01	44.367 mi
Registration #4	2015-03-07	55.885 mi
Registration #5	2016-02-27	65.578 mi
Registration #6	2017-03-20	72.755 mi
Registration #7	2018-03-19	78.984 mi
Registration #8	2019-03-18	85.461 mi
Registration #9	2020-03-18	91.938 mi
Registration #10	2021-03-18	98.415 mi
Registration #11	2022-03-18	104.892 mi
Registration #12	2023-03-18	111.369 mi
Registration #13	2024-03-18	117.846 mi
Registration #14	2025-03-18	124.323 mi
Registration #15	2026-03-18	130.800 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1737 kg
Max. allowed weight	2270 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number

672615