



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN TDI SE
Colour	Blue
Year of manufacture	2007
Top speed	126 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.4 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.2 mpg
CO2 emission	174 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-08-06
Pictures	6
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-09
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	33
Total items failed	1

MOT #17	2023-08-10 14:31
MOT test number	737505936968
Result	✓ Passed
Next expiry date	2024-08-09
Advice	Nearside Front Tyre worn close to legal limit/worn on edge wearing on outer edge (5.2.3 (e))

MOT #16	2023-08-07 09:22
MOT test number	671378468361
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge wearing on outer edge (5.2.3 (e))
MAJOR	Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))
MAJOR	Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))
MAJOR	Offside Front Windscreen wiper missing (3.4 (a))

MOT #15	2022-03-09 07:51
MOT test number	532152565837
Result	✓ Passed

**MOT #14**

2021-03-06 10:02

MOT test number

769282642679

Result

✓ Passed

- Advice** MIL Inoperative or indicating a malfunction - diesel vehicle
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13

2020-02-14 10:29

MOT test number

578306096053

Result

✓ Passed

MOT #12

2019-02-28 14:13

MOT test number

355111186692

Result

✓ Passed

MOT #11

2019-02-23 13:31

MOT test number

988321343579

Result

✗ Failed

- MAJOR** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- DANGEROUS** Offside Front Inner Tyre has ply or cords exposed Cut in tread (5.2.3 (d) (ii))
- DANGEROUS** Nearside Rear Tyre has ply or cords exposed Cut in tread & damage to sidewall (5.2.3 (d) (ii))
- DANGEROUS** Nearside Front Inner Tyre has ply or cords exposed Cut in tread (5.2.3 (d) (ii))
- MAJOR** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- DANGEROUS** Offside Rear Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MOT #10** 2018-02-27 13:55**MOT test number** 442505428215**Result** ✓ Passed**MOT #9** 2017-02-18 12:35**MOT test number** 637285821150**Result** ✓ Passed**MOT #8** 2016-02-19 09:38**MOT test number** 969968737613**Result** ✓ Passed**MOT #7** 2015-02-05 09:58**MOT test number** 569086135029**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in nearside rear tyre**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2015-02-04 15:39**MOT test number** 985605535095**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Nail in nearside rear tyre**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2014-01-02 15:32**MOT test number** 426772404091**Result** ✓ Passed**MOT #4** 2013-02-28 14:00**MOT test number** 778159853016**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Notice** Engine cover loose**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Both rear tyre inner treads out of shape**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2012-02-14 09:29**MOT test number** 987555542024**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2011-02-16 12:15**MOT test number** 389837441007**Result** ✓ Passed**Notice** Both rear tyres perished on outer sidewalls**MOT #1** 2010-02-26 15:54**MOT test number** 362367850008**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
9 August 2024

Tax status	Valid until 1 January
Days left	247
MOT expiry date	9 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 GU07JYS
Plate since	2024-03-28
Current registration	 GU07JYS
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-03-01
Last registration	2023-08-10
Complete history	See info



Registration #1	2007-03-01	19 mi
Registration #2	2010-02-26	22.390 mi
Registration #3	2011-02-16	30.740 mi
Registration #4	2012-02-14	41.621 mi
Registration #5	2013-02-28	51.078 mi
Registration #6	2014-01-02	57.748 mi
Registration #7	2015-02-04	66.801 mi
Registration #8	2015-02-05	66.803 mi
Registration #9	2016-02-19	78.074 mi
Registration #10	2017-02-18	85.339 mi
Registration #11	2018-02-20	95.339 mi
Registration #12	2019-02-20	105.339 mi
Registration #13	2020-02-20	115.339 mi
Registration #14	2021-02-20	125.339 mi
Registration #15	2022-02-20	135.339 mi
Registration #16	2023-02-20	145.339 mi
Registration #17	2024-02-20	155.339 mi
Registration #18	2025-02-20	165.339 mi
Registration #19	2026-02-20	175.339 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1517 mm
Length	4774 mm
Wheel base	2709 mm
Kerb weight	1738 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	BKP 259788