





report date: 2024-03-29

General information

Make	ТОУОТА
Model	VERSO D-4D ICON
Colour	White
Year of manufacture	2015
Top speed	112 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/11




Internet history

Entry 1

Date 2021-02-05

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-05-17
MOT pass rate	100 %
MOT passed	6
Failed MOT tests	0
Total advice items	15
Total items failed	0

MOT #6		2023-05-15 12:02
MOT test	number	161748809130
Result		✓ Passed
Next expi	ry date	2024-05-17
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Front Tyre worn close to legal limit/worn on edge Both sides (5.2.3 (e))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) ((ii))
Advice	Front Oil leak, but not excessive Engine area (8.4.1 (a) (i))	

MOT #5		2022-04-30 10:28
MOT test i	number	519467071734
Result		✓ Passed
MOT #4		2021-05-18 11:58
MOT test	number	718235833903
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice (ii))	Front Brake disc worn, pitted or scored, but not seriously weakened	I and rear both side (1.1.14 (a)

CarCheck.co.uk page 3/11



NA15YPL

report date: 2024-03-29

MOT #3

MOT test number

707804074827

Result

Advice Under trays fitted obscuring underside components

2020-07-15 11:45

707804074827

MOT #2 2019-05-17 13:14 **MOT** test number 287854151751 Result ✓ Passed **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing tread cracking (5.2.3 (d) (ii)) **Advice** Offside Rear Tyre slightly damaged outer wall damaged. (5.2.3 (d) (ii)) **Advice** Offside Front Brake disc worn, but not excessively slight lip (1.1.14 (a) (i)) Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened corrosion. (1.1.14 (a) (ii)) Advice Nearside Front Tyre worn close to legal limit/worn on edge worn on edge. (5.2.3 (e)) Advice Offside Rear Tyre slightly damaged/cracking or perishing tread cracking (5.2.3 (d) (ii)) **Advice** Nearside Front Brake disc worn, but not excessively slight lip. (1.1.14 (a) (i)) Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened corrosion. (1.1.14 (a) (ii))

MOT #1	2018-05-11 15:03
MOT test number	807082550278
Result	✓ Passed

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 May
Days left	366
MOT expiry date	17 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



NA15YPL

report date: 2024-03-29

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

,		
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full respectively.)TA

	More info	>
Plate changes		
See in this check if this TOYOTA had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK W	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2015-05-22
Last registration	2023-05-15
Complete history	See info



Registration #1	2015-05-22	16 mi
Registration #2	2018-05-11	20.015 mi
Registration #3	2019-05-17	26.544 mi
Registration #4	2020-07-15	32.744 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	89%
Children	75%
Pedestrian	69%
Safety systems	86%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1790 mm
Height	1620 mm
Length	4460 mm
Wheel base	2780 mm
Kerb weight	1620 kg
Max. allowed weight	2260 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 11/11

Number of axles 2

Engine number N4776138840