



report date: 2024-03-29

General information

| | |
|---------------------|----------------|
| Make | VAUXHALL |
| Model | AGILA S AC |
| Colour | Blue |
| Year of manufacture | 2012 |
| Top speed | 109 mph |
| 0 - 60 mph | 12.0 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 92 BHP |
| Max. torque | 118 Nm at 4.800 rpm |
| Engine capacity | 1.242 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 46.3 mpg |
| Consumption extra urban | 62.8 mpg |
| Consumption combined | 55.4 mpg |
| CO2 emission | 118 g/km |
| CO2 label | C |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-09-24 |
| Pictures | 4 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-10-24 |
| MOT pass rate | 83 % |
| MOT passed | 10 |
| Failed MOT tests | 2 |
| Total advice items | 14 |
| Total items failed | 3 |

| | |
|------------------|------------------|
| MOT #12 | 2023-09-26 09:13 |
| MOT test number | 366278034050 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-24 |

| | |
|-----------------|------------------|
| MOT #11 | 2022-09-28 13:10 |
| MOT test number | 727034732300 |
| Result | ✓ Passed |

| | |
|-----------------|---|
| MOT #10 | 2022-09-28 10:29 |
| MOT test number | 529758603027 |
| Result | ✗ Failed |
| Fail | Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b)) |

| | |
|-----------------|------------------|
| MOT #9 | 2021-10-25 07:22 |
| MOT test number | 168197730404 |
| Result | ✓ Passed |

**MOT #8** 2021-08-25 11:55**MOT test number** 829033508521**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened discs corroded (1.1.14 (a) (ii))**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Nearside Rear Nail in tyre non repairable puncher**MOT #7** 2020-08-25 12:27**MOT test number** 967446708704**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #6** 2019-08-08 10:33**MOT test number** 687100972301**Result** ✓ Passed**Advice** Items removed from driver's view prior to test**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #5** 2018-08-09 10:51**MOT test number** 568404775756**Result** ✓ Passed**MOT #4** 2017-08-10 15:30**MOT test number** 598021501764**Result** ✓ Passed**Advice** Items removed from driver's view prior to test**Advice** Hand brake high travel

**MOT #3** 2017-08-10 15:30**MOT test number** 477829500336**Result** ✗ Failed**Advice** Hand brake high travel**Pass with rectification** Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Items removed from driver's view prior to test**Pass with rectification** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #2** 2016-08-22 10:03**MOT test number** 619146396829**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2015-09-02 11:17**MOT test number** 584113076191**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
24 October 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 October |
| Days left | 154 |
| MOT expiry date | 24 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 48 |
| Band | C |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | HV62FHY |
| Plate since | 2019-03-29 |
| Current registration | HV62FHY |
| Plate since | 2019-03-29 |

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 14 |
| First mileage registration | 2012-09-08 |
| Last registration | 2023-09-26 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2012-09-08 | 11 mi |
| Registration #2 | 2015-09-02 | 35.251 mi |
| Registration #3 | 2016-08-22 | 41.107 mi |
| Registration #4 | 2017-08-10 | 51.151 mi |
| Registration #5 | 2017-08-10 | 51.151 mi |
| Registration #6 | 2018-08-09 | 59.927 mi |
| Registration #7 | 2019-08-08 | 67.502 mi |
| Registration #8 | 2020-09-26 | 75,377 mi |
| Registration #9 | 2021-09-26 | 75,377 mi |
| Registration #10 | 2022-09-26 | 75,377 mi |
| Registration #11 | 2023-09-26 | 75,377 mi |
| Registration #12 | 2024-03-29 | 75,377 mi |
| Registration #13 | 2024-03-29 | 75,377 mi |
| Registration #14 | 2024-03-29 | 75,377 mi |

More info >



Safety ratings

| | |
|-------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1932 mm |
| Height | 1590 mm |
| Length | 3740 mm |
| Wheel base | 2360 mm |
| Kerb weight | 1000 kg |
| Max. allowed weight | 1485 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 45 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Engine number | 1494752 |