



EX07NWD

report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT 350 LWB EF HR DRW P/V 100
Colour	White
Year of manufacture	2007
Gearbox	5 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	285 Nm at 1.600 rpm
Engine capacity	2.402 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2021-08-03
MOT pass rate	55 %
MOT passed	11
Failed MOT tests	9
Total advice items	69
Total items failed	29

MOT #20	2020-08-04 06:50
MOT test number	352741496636
Result	✓ Passed
Next expiry date	2021-08-03

MOT #19	2020-08-03 10:52
MOT test number	977973157441
Result	✗ Failed
Fail	Offside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Nearside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt DUST BOOT SPLIT (5.3.4 (b) (ii))
Fail	Offside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))



MOT #18

2019-07-02 16:01

MOT test number

188697061859

Result

✓ Passed

- Advice

Items removed from driver's view prior to test
- Advice

Offside Rear offside rear undersill corroded
- Advice

Both rear inner wheel arch to floor joints corroded
- Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Underbody corrosion
- Advice

Both front lower inner bushes deteriorated
- Advice

Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice

Offside Rear tyre cracking

**MOT #17**

2019-07-01 09:14

MOT test number

113715506351

Result**✗ Failed****Advice** Offside Rear tyre cracking**Advice** Items removed from driver's view prior to test**Fail** Exhaust emissions exceed level of metered smoke for a turbo charged engine (8.2.2.2 (b))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear offside rear undersill corroded**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Both rear inner wheel arch to floor joints corroded**Advice** Underbody corrosion**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Both front lower inner bushes deteriorated**MOT #16**

2018-07-12 11:42

MOT test number

907478912562

Result**✓ Passed****Advice** Offside Front Tyre worn close to legal limit/worn on edge and sidewall damaged (5.2.3 (e))**Advice** Underbody corrosion**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive undersill (5.3.6 (a) (i))

**MOT #15**

2018-07-10 12:10

MOT test number

112127024404

Result

✗ Failed

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive undersill (5.3.6 (a) (i))

Advice Underbody corrosion

Fail Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength undersill (5.3.6 (a) (i))

Fail Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge and sidewall damaged (5.2.3 (e))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #14

2017-04-20 15:15

MOT test number

775811195118

Result

✓ Passed

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Rear Brake pipe slightly corroded axle (3.6.B.2c)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #13**

2017-04-19 15:04

MOT test number

790363005560

Result**✗ Failed**

- Advice** Nearside Rear Brake pipe slightly corroded axle (3.6.B.2c)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Central Stop lamp not working (1.2.1b)
- Fail** Offside Front Brake pipe excessively corroded (3.6.B.2c)
- Fail** Offside Rear Brake pipe excessively corroded axle (3.6.B.2c)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Nearside Front Brake pipe excessively corroded (3.6.B.2c)

MOT #12

2016-05-18 11:15

MOT test number

797768189264

Result**✓ Passed**

- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Wipers poor
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)

**MOT #11** 2016-04-25 11:34**MOT test number** 561830073324**Result** ✗ Failed**Advice** Brake disc worn, pitted or scored, but not seriously weakened all (3.5.1i)**Fail** Offside Front Brake pipe excessively corroded (3.6.B.2c)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Nearside Front Brake pipe excessively corroded (3.6.B.2c)**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Wipers deteriorating**MOT #10** 2015-01-15 15:04**MOT test number** 955715315070**Result** ✓ Passed**Notice** Play in steering rack inner joint(s)**MOT #9** 2015-01-15 10:45**MOT test number** 226075315056**Result** ✗ Failed**Notice** Play in steering rack inner joint(s)**Fail** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**MOT #8** 2014-01-22 10:24**MOT test number** 497412624065**Result** ✓ Passed**Notice** Clutch pedal rubber worn

**MOT #7**

2014-01-22 09:01

MOT test number

386122424091

Result

✗ Failed

Fail Offside Headlamp aim too low (1.8)**Notice** Clutch pedal rubber worn**Fail** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Offside Rear position lamp(s) obscured more than 50% (1.1.A.3c)**MOT #6**

2013-01-23 10:44

MOT test number

186503623491

Result

✓ Passed

MOT #5

2012-02-08 14:42

MOT test number

635029932018

Result

✓ Passed

Notice Clutch pedal rubber worn smooth**Notice** Engine oil leak**Notice** O/S head light cracked**Notice** Both rear hub seals leaking**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** N/S body damaged**Notice** Engine managment light on**Notice** Sub frame bushes cracking**Advice** Offside Track rod end ball joint has slight play (2.2.B.1f)

**MOT #4**

2012-02-08 11:56

MOT test number

677759532096

Result**✗ Failed**

- Notice** Clutch pedal rubber worn smooth
- Fail** Brake pedal anti-slip provision worn smooth (3.3.A.1b)
- Notice** Engine oil leak
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Notice** Both rear hub seals leaking
- Notice** O/S head light cracked
- Fail** Offside Seat belt damaged sufficient to significantly weakened the webbing (5.2.2a)
- Notice** N/S body damaged
- Fail** Rear Direction indicators incorrect colour (1.4.A.2f)
- Notice** Sub frame bushes cracking
- Advice** Offside Track rod end ball joint has slight play (2.2.B.1f)
- Notice** Engine managment light on

MOT #3

2011-02-23 12:59

MOT test number

635254151028

Result**✓ Passed**



MOT #2	2011-02-23 09:59
MOT test number	145504951073
Result	✗ Failed
Fail	Nearside Front Headlamp not working on dipped beam (1.7.5a)
Notice	Nail in offside rear tyre
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Offside Rear Registration plate lamp not working (1.1.C.1d)

MOT #1	2010-03-17 11:35
MOT test number	553136970083
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✕
Untaxed

Tax expired:
4 January 2021

✕
MOT

Expired:
3 August 2021

Tax status	Expired at 4 January 2021
Days left	1211 days too late
MOT expiry date	3 August 2021
Full MOT history	See MOT history



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	EX07NWD
Plate since	2019-09-29
Current registration	EX07NWD
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-03-22
Last registration	2020-08-04
Complete history	See info



Registration #1	2007-03-22	12 mi
Registration #2	2010-03-17	56.470 mi
Registration #3	2011-02-23	74.967 mi
Registration #4	2011-02-23	74.967 mi
Registration #5	2012-02-08	100.388 mi
Registration #6	2012-02-08	100.388 mi
Registration #7	2013-01-23	126.400 mi
Registration #8	2014-01-22	147.282 mi
Registration #9	2014-01-22	147.284 mi
Registration #10	2015-01-15	158.498 mi
Registration #11	2015-01-15	158.498 mi
Registration #12	2016-01-15	169.712 mi
Registration #13	2016-01-15	169.712 mi
Registration #14	2017-01-15	180.926 mi
Registration #15	2017-01-15	180.926 mi
Registration #16	2018-01-15	192.140 mi
Registration #17	2018-01-15	192.140 mi
Registration #18	2019-01-15	203.354 mi
Registration #19	2019-01-15	203.354 mi
Registration #20	2020-08-04	214.568 mi
Registration #21	2020-08-04	214.568 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2492 mm
Height	2025 mm
Length	6385 mm
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	7
Engine number	6A17202