





report date: 2024-03-28

General information

| Make | KIA |
|---------------------|-------------------|
| Model | SORENTO CRDI KX-2 |
| Colour | Silver |
| Year of manufacture | 2015 |
| Top speed | 118 mph |
| 0 - 60 mph | 9.5 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| Power | 194 BHP |
|-------------------------|---------------------|
| Max. torque | 422 Nm at 1.800 rpm |
| Engine capacity | 2.199 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 32.1 mpg |
| Consumption extra urban | 52.3 mpg |
| Consumption combined | 42.2 mpg |
| CO2 emission | 175 g/km |
| CO2 label | Н |



CarCheck.co.uk page 1/12



Internet history

Entry 2

Date 2022-04-02

Pictures 31

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

| Date | 2021-12-11 |
|----------|------------|
| Pictures | 3 |

Listing price <u>View report</u>







source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

| MOT expiry date | 2025-03-30 |
|--------------------|------------|
| MOT pass rate | 58 % |
| MOT passed | 7 |
| Failed MOT tests | 5 |
| Total advice items | 13 |
| Total items failed | 8 |

| MOT #12 | | 2024-03-19 16:42 |
|---|---|------------------|
| MOT test | number | 705665333543 |
| Result | | ✓ Passed |
| Next expi | ry date | 2025-03-30 |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | | |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #11 | 2024-03-19 10:23 |
|---|------------------|
| MOT test number | 670681843380 |
| Result | X Failed |
| Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i)) | |
| Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii)) | |
| Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #10 | 2023-03-31 12:27 |
|-----------------|------------------|
| MOT test number | 829389495106 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/12



× Failed

MOT #9 2023-03-31 07:43

MOT test number 353690902382

Result X Failed

Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #8 2022-03-29 19:53

MOT test number 241233608120

Result \square Passed

Advice Nearside Rear NSR Shock absorber misting oil slightly.

MOT #7 2022-03-17 13:52

MOT test number 160395234546

Result X Failed

Advice Nearside Rear NSR Shock absorber misting oil slightly.

Fail Driver's seat with a defective structure (6.2.5 (a) (i))

MOT #6 2022-02-17 19:04

MOT test number 330014931635

Result × Failed

Fail Offside Front Driver's seat insecure (6.2.5 (a) (ii))

Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #5 2021-10-26 12:56

MOT test number 813632562949

Result

Fail Driver's seat with a defective structure (6.2.5 (a) (i))

Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

CarCheck.co.uk page 4/12



 MOT #4
 2021-01-25 09:55

 MOT test number
 452026422793

 Result
 ✓ Passed

 Advice
 Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT test number

Result

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Advise 4 wheel alignment due to tyre wear

| MOT #2 | 2019-01-31 16:59 |
|-----------------|------------------|
| MOT test number | 900099957668 |
| Result | ✓ Passed |

| MOT #1 | 2018-03-19 10:21 |
|-----------------|------------------|
| MOT test number | 240273782333 |
| Result | ✓ Passed |

CarCheck.co.uk page 5/12



Tax & MOT check



| Tax status | Valid until 1 April |
|------------------|---------------------|
| Days left | 337 |
| MOT expiry date | 30 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | Н |
| Single payment (12 months) | £ 290,00,- |
| Single six month payment | £ 159,50,- |
| Total payable by 12 monthly instalments | £ 304,50,- |

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Туре | |



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

| , | | |
|---|--|---|
| For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report | | |
| | | |
| | | |
| | | |
| | | |
| ******* | | |
| | | |
| *************************************** | | |
| | More info | > |
| Plate changes | | |
| See in this check if this KIA had different number plates. | | |
| Number of plates | | |
| Current registration | NK NE | |
| Plate since | | |
| Current registration | OK ON THE STATE OF | |
| Plate since | | |
| | More info | > |

CarCheck.co.uk page 9/12



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 10/12



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 15 |
| First mileage registration | 2015-03-23 |
| Last registration | 2024-03-19 |
| Complete history | See info |



| Registration #1 | 2015-03-23 | 23 mi |
|------------------|------------|------------|
| Registration #2 | 2018-03-19 | 25.436 mi |
| Registration #3 | 2019-01-31 | 33.149 mi |
| Registration #4 | 2020-01-13 | 41.581 mi |
| Registration #5 | 2021-01-25 | 47.603 mi |
| Registration #6 | 2021-10-26 | 51.950 mi |
| Registration #7 | | 9.777 es |
| Registration #8 | 2022-02-17 | 51.957 mi |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 91.777 esi |
| Registration #12 | | 11.777 es |
| Registration #13 | | 91.777 esi |
| Registration #14 | | 11.777 es |
| Registration #15 | | 11.777 es |

More info >

CarCheck.co.uk page 11/12



Car features

| S0225 | Air conditioning |
|--------|------------------|
| S0295 | |
| S0482 | |
| \$0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 90% |
| Children | 83% |
| Pedestrian | 67% |
| Safety systems | 71% |
| Overall rating | 80% |
| Video | see crash video |



Dimensions & weight

| Width | 1885 mm |
|---------------------|---------|
| Height | 1735 mm |
| Length | 4685 mm |
| Wheel base | 2700 mm |
| Kerb weight | 1919 kg |
| Max. allowed weight | 2510 kg |

Additional information

| Fuel tank capacity | 64 I |
|-----------------------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 7 page 12/12 |

Number of axles 2

Engine number D4HBEH107714