





report date: 2024-03-28

General information

Make	LAND ROVER
Model	DEFENDER HARD-TOP TD5
Colour	Green
Year of manufacture	2004
Gearbox	5 speed Manual

Engine & fuel consumption

Power	127 BHP
Engine capacity	2.495 сс
Cylinders	5
Fuel type	Diesel



CarCheck.co.uk page 1/13



Internet history

Emter.	1
	ъ.

ciitiy 1	
Date	2021-07-11
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2023-01-11
MOT pass rate	89 %
MOT passed	16
Failed MOT tests	2
Total advice items	30
Total items failed	8

MOT #18		2022-01-12 10:59
MOT test	number	200937222258
Result		✓ Passed
Next expi	ry date	2023-01-11
Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))		
Advice Offside Rear Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))		
Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))		

MOT #17		2021-01-04 15:36
MOT test	number	790622437936
Result		✓ Passed
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1	.1.14 (a) (ii))
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))		
Minor Hazard warning switch faulty (4.4.2 (a) (i))		
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened ((1.1.14 (a) (ii))
Advice	Central Rear Brake pipe corroded, covered in grease or other material (1.1.11	. (c))

CarCheck.co.uk page 3/13



MOT #16 2020-12-29 10:52

MOT test number 190507509305

Result X Failed

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Fail Offside Front Drag link end ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

Fail Fuel system component leaking (6.1.3 (b) (i))

Fail Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Minor Hazard warning switch faulty (4.4.2 (a) (i))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Central Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #15 2019-06-20 15:17

MOT test number 449875349010

Result

Passed

Advice Rear Brake pipe corroded, covered in grease or other material across axle (1.1.11 (c))

Advice Power steering has small leak at drop arm seal

CarCheck.co.uk page 4/13



MOT #14 2019-06-20 15:17

MOT test number 575526844305

Result X Failed

Pass with rectification Offside Rear Stop lamp(s) not working 566 (4.3.1 (a) (ii))

Advice Power steering has small leak at drop arm seal

Pass with rectification Front Registration plate inscription illegible broken and stained (0.1 (b))

Advice Rear Brake pipe corroded, covered in grease or other material across axle (1.1.11 (c))

Pass with rectification Front Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen new jet fitted (3.5 (a))

MOT #13 2018-06-03 16:29

MOT test number 782792209699

Result ✓ Passed

Advice Front Power steering component has slight seepage from a component steering boxs (2.1.5 (a))

Advice Front Steering box has slight free play detected at steering wheel (2.3 (a) (i))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #12 2017-04-28 13:34

MOT test number 349978698348

Result

✓ Passed

MOT #11 2016-05-03 13:09

MOT test number 131872981778

Result ✓ Passed

CarCheck.co.uk page 5/13



MOT #10 2015-05-12 16:16

MOT test number 738372035114

Result
✓ Passed

Advice Nearside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

Advice Nearside Rear Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive

movement (2.4.G.2)

Advice Offside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

Advice Offside Rear Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive

movement (2.4.G.2)

MOT #9 2014-05-16 16:56

MOT test number 517026734193

Notice Oil leak

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #8 2013-12-19 09:08

MOT test number 125413453325

Result
✓ Passed

Advice Offside Front wheel bearing has slight play (2.5.A.3c)

Advice Nearside Front wheel bearing has slight play (2.5.A.3c)

MOT #7 2012-12-17 16:20

MOT test number 435872752447

MOT #6 2011-11-23 12:13

MOT test number 475597121340

Result

Passed

CarCheck.co.uk page 6/13



MOT #5	2010-11-22 08:34
MOT test number	121926520369
Result	✓ Passed
MOT #4	2009-12-22 14:33
MOT test number	690056959340
Result	✓ Passed
MOT #3	2009-02-03 16:34
MOT test number	380994539073
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #2	2008-02-15 16:42
MOT test number	351936348019
Result	✓ Passed
MOT #1	2007-01-26 16:45
MOT test number	751166227045
Result	✓ Passed

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category

Type

Damage 2

Date

Category

Type



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



O	history
IWADAL	
	IIISLUIV

For how long did the current and previous owner(s) have this LAND ROVER? How many of ROVER have? Check it in the premium report and see all owner registrations. Download to	
MARKET STATE OF THE STATE OF TH	

	More info >
Plate changes	
See in this check if this LAND ROVER had different number plates.	
Number of plates	
Current registration	NK SIK
Plate since	
Current registration	NK SIK
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2004-02-24
Last registration	2022-01-12
Complete history	See info



Registration #1	2004-02-24	8 mi
Registration #2	2007-01-26	58.631 mi
Registration #3	2008-02-15	80.506 mi
Registration #4	2009-02-03	104.469 mi
Registration #5	2009-12-22	125.244 mi
Registration #6	2010-11-22	148.571 mi
Registration #7	2011-11-23	170.523 mi
Registration #8	2012-12-17	184.919 mi
Registration #9	2013-12-19	195.248 mi
Registration #10	2014-05-16	198.449 mi
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		0.70 es
Registration #16		11.777 es
Registration #17		9.70 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		71.777 au

More info >

CarCheck.co.uk page 12/13



Additional information

Fuel delivery	Direct Injection
Number of seats	4
Number of axles	2
Engine number	15P85626A

CarCheck.co.uk page 13/13